



Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

Sautter Yard

on

6/1/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

Signature

Date

Table of Contents

● High ● Med ● Low Section

Man basket - *Sautter Yard*

Personnel Lifting Platform: *HMB9*

0

0




0

1.0




Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview




Breakdown by Form

Form Type	 High	 Med	 Low	# Forms
Man basket	0	0	0	1
Overall:	0	0	0	1

Breakdown by Location

Location	 High	 Med	 Low	# Forms
Sautter Yard	0	0	0	1
Overall:	0	0	0	1

Breakdown by Asset

Asset Type	 High	 Med	 Low	# Assets
Personnel Lifting Platform	0	0	0	1
Overall:	0	0	0	1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Man basket
Sautter Crane Rental
 2900 Black Lake Place
 Philadelphia, PA 19154

FolderID: 060126HMB9
 FormID: 29347405



Personnel Lifting Platform

Location: Sautter Yard
 2900 Black Lake Place
 Philadelphia, PA 19154

Identifier: HMB9

Description: Man Basket

Additional Notes: Ser No - J7160

Priorities Found: ● 19 - Good

This inspection was performed for	
● 1. Customer	Sautter
Manufacturer	
● 2. Manufacturer of device	Lakeshore Industries
Model	
● 3. Manufacturers Model number	M44
Capacity	
● 4. Maximum Rated Capacity of device	1,000 lbs
Tare Weight	
● 5. Weight of device	550 lbs
General	
● 6. Checked for structural deformation, cracks, or excessive wear of any part of the device.	(SAT) Satisfactory
Contact points	
● 7. Are all edges exposed to employee contact smooth enough to prevent injury?	(Y) Yes
Grab Rail	
● 8. Grab rail around entire inside perimeter with the exception of gate?	(SAT) Satisfactory
Gate/Door	
● 9. Does the gate swing inward and have a locking/latching device that can not be accidentally opened?	(SAT) Satisfactory
Markings	
● 11. Weight and rated capacity clearly and permanently posted on platform?	(Y) Yes P11
Rope Bridle	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 12. Each bridle leg is connected to a master link or shackle that ensures that the load is evenly divided among the individual legs? (Y) Yes

Rigging

● 13. The rigging used on the platform is only used for lifting the platform and is capable of supporting 5 times the maximum intended load (if rotation resistant-MUST be capable of supporting 10 times the intended load) (SAT) Satisfactory

Wire Rope Slings

● 14. Eyes in wire rope slings are fabricated with thimbles? (Y) Yes

Corrosion

● 15. The platform should show no signs of structural corrosion that may weaken the structural capacity or integrity. (SAT) Satisfactory

Connection Points

● 16. Rigging connection points on platform are not bent, worn, cracked or corroded. (SAT) Satisfactory

Proof Load Capability

● 17. Platform has safe means of proof test for pre personnel lifting. (SAT) Satisfactory P17

Inspector

● 18. Name Anthony Capozzi



Date Of Inspection

● 19. Inspection performed on 06/01/2026

Certification Issued

● 20. Was a certification issued? (Y) Yes

Deficiency Rectification Process

21. -IF THERE ARE NO DEFICIENCIES NOTHING NEEDS TO BE DONE -IF THERE ARE ANY (HIGH, RED) DEFICIENCIES PLEASE FOLLOW THE INSTRUCTIONS BELOW

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email this entire report to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certificate and label will be issued.

Customer Deficiency Sign Off

22. -ONLY complete this signature field after all deficiencies were corrected.

Please print, sign and date this section with all personnel that made corrections to the defective unit. Additionally, please have each respective person initial the individual deficiency/deficiencies.

PRINT: _____ SIGN: _____

DATE _____

Tandem Lift LLC

23. Disclaimer

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



P10.1



P11.2



P17.3