

## Prepared for:

# **Sautter Crane rental**

2900 Black Lake Place Philadelphia, PA 19154

Sautter Yard

on

10/11/2025

Please return the entire report.

#### **Customer Sign Off**

- -If there are no deficiencies nothing needs to be done
- -If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to <a href="mailto:tony.rossi@tandemlift.com">tony.rossi@tandemlift.com</a> or <a href="mailto:jon.santimaw@tandemlift.com">jon.santimaw@tandemlift.com</a>. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.			
Signature	Date		

## **Table of Contents**

Below the Hook Devices: SER NO -

High Med Low

0

Lifting Bar - Sautter Yard

SB03 - SB03

0

0

1.0

Section

# Overview

## **Breakdown by Form**

Form Type		High 🔵	Med 🧶	Low	# Forms
Lifting Bar		0	0	0	1
	Overall:	0	0	0	1
Breakdown by Location					
Location		High 🧶	Med 🧶	Low	# Forms
Sautter Yard		0	0	0	1
	Overall:	0	0	0	1
Breakdown by Asset					
Asset Type		High 🧶	Med 🧶	Low	# Assets
Below the Hook Devices		0	0	0	1
	Overall:	0	0	0	1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Lifting Bar Sautter Crane rental 2900 Black Lake Place Philadelphia, PA 19154

FolderID: 101125SB03 FormID: 26195784



Below the Hook Devices				
Location:	Sautter Yard 2900 Black Lake Place Philadelphia, PA 19154			
Identifier:	SER NO - SB03			
TagID:	SB03			

Type:	Spreader Beam
Capacity:	5 tons
Manufacturer:	Sautter
Model Number:	SCR.5T
Length/Lift:	8'2" to 13'3"

Priorities Found: 13 - Good

Gen	eral		
	Bar has no obvious bend, twist or deformation.	(SAT) Satisfactory	
Man	Manufacturer		
• :	2. Make	Sautter	
Man	ufacturer Model Number		
• :	3. Model	SCR.5T	
Сар	acity		
	4. Rated Capacity of device	5 Tons	
Tare	e Weight		
•	5. Weight of device	135 lbs	
Mar	kings		
	6. The weight and capacity of the device are clearly and permanently displayed.	(Y) Yes	
Pro	of Load Test		
•	7. Was a proof load test performed at time of inspection?	(Y) Yes	
	Proof tested at 12,500 lbs.		
Corrosion			
	3. No visible corrosion that may effect the structural integrity of the device.	(SAT) Satisfactory	
Rigg	ging Connection Points		
• !	<ol> <li>All possible points of connection do not have any visible cracks, deformation or excessive wear.</li> </ol>	(SAT) Satisfactory	
Adjı	ustability		
• 1	0. If the device is adjustable, Are all pins/fixtures secure and in proper working condition?	(Y) Yes	
Name Of Inspector			
• 1	1. Inspector	Anthony Capozzi	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Date Of Inspection	
12. Inspection performed on	10/11/2025
Certificate	
13. Was a certificate issued?	(Y) Yes

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.