Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

654 Berlin Crosskeys Rd

on

11/7/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

_____ _____

Signature Date

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Table of Contents

		High	Med	Low	Section
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400) - *654 Berlin Crosskeys Rd*	Telescoping Boom Crane*: 043 408 - S361*	0	1	0	**1.0**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview

Breakdown by Form

Form Type	High	Med	Low	# Forms
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)	0	1	0	1
Overall:	**0**	**1**	**0**	**1**

Breakdown by Location

Location	High	Med	Low	# Forms
654 Berlin Crosskeys Rd	0	1	0	1
Overall:	**0**	**1**	**0**	**1**

Breakdown by Asset

Asset Type	High	Med	Low	# Assets
Telescoping Boom Crane	0	1	0	1
Overall:	**0**	**1**	**0**	**1**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)

FolderID: 110726S361
FormID: 31579289

Sautter Crane Rental
2900 Black Lake Place
Philadelphia, PA 19154



Telescoping Boom Crane

Location:	654 Berlin Crosskeys Rd
Serial Number:	043 408
Unit Number:	S361
Status:	In Service

Additional Notes: 197 ft boom
3 parts of line

Manufacturer:	Liebherr
Model:	LTM 1110-5.1
Capacity:	125 Ton
Length/Lift:	197'
Type of Crane:	All Terrain Crane
Number of Hoists:	Main and Auxiliary (Not in Use)
Boom Configuration:	Main Boom with Stowed Jib
Load Test:	No

Priorities Found: **1 - Medium** **110 - Good**

General

●	1.	Location of Equipment	**654 Berlin Crosskeys Rd**
	2.	Customer Sign Off	

Please return the entire report.
Customer Sign Off
-If there are no deficiencies nothing needs to be done
-If there are any (HIGH, RED) deficiencies please follow the instructions below
The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.
-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

_____ _____
Signature

●	3.	Hours & Mileage		
		Hours	Mileage	
		2,341	**23,519**	

Inspection Information

●	4.	Inspection Number	**110726S361**
●	5.	Inspection Date	**11/07/2026**
●	6.	Inspection Type	**(Ann) Annual**

Information & Records

●	7.	Documentation of Annual/Comprehensive Inspection	**(SAT) Satisfactory**
●	8.	Daily/Monthly Inspection Records	**(SAT) Satisfactory**
●	9.	Maintenance Records	**(SAT) Satisfactory**
●	10.	Hand Signal Chart	**(SAT) Satisfactory**
●	11.	Safety and Warning Decals	**(SAT) Satisfactory**
●	12.	Operators Manual	**(SAT) Satisfactory**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Safety Devices & Operational Aids		
●	13. Backup Alarm	**(SAT) Satisfactory**
●	14. Audible Warning Device	**(SAT) Satisfactory**
●	15. Boom Angle Indicator	**(SAT) Satisfactory**
●	16. Boom Length Indicator	**(SAT) Satisfactory**
●	17. Drum Rotation Indicator(s)	**(SAT) Satisfactory**
●	18. Anti Two-Block Device/System	**(SAT) Satisfactory**
●	19. Load Moment Indicator (LMI)	**(SAT) Satisfactory**
●	20. Load Weight Indicator	**(SAT) Satisfactory**
●	21. Radius Indicator	**(SAT) Satisfactory**
●	22. Level Indicator(s)	**(SAT) Satisfactory**
●	23. Fire Extinguisher	**(SAT) Satisfactory**
Load Chart		
●	24. Visible/Accessible	**(SAT) Satisfactory**
●	25. Per Configuration	**(SAT) Satisfactory**
●	26. Durable/Legible/Secured	**(SAT) Satisfactory**
Carrier		
●	27. Steering	**(SAT) Satisfactory**
●	28. Parking Brake	**(SAT) Satisfactory**
●	29. Exterior Lights (Headlights, Turn Signals, Brake Lights, Reverse Lights)	**(SAT) Satisfactory**
●	30. Windshield & Wipers	**(SAT) Satisfactory**
●	31. Windows & Mirrors	**(SAT) Satisfactory**
●	32. Wheels & Tires	**(SAT) Satisfactory**
●	33. Engine	**(SAT) Satisfactory**
●	34. Exhaust System	**(SAT) Satisfactory**
●	35. Axle Lockout	**(SAT) Satisfactory**
●	36. Drive Line	**(SAT) Satisfactory**
●	37. Main Frame Members	**(SAT) Satisfactory**
●	38. Hoses/Fittings//Valves	**(SAT) Satisfactory**
●	39. Hydraulic Tank & Fluid Level	**(SAT) Satisfactory**
●	40. Slip Resistant Walking Surfaces	**(SAT) Satisfactory**
●	41. Steps/Ladders/Handrails	**(SAT) Satisfactory**
Outriggers/Stabilizers		
●	42. Structure & Mounting	**(SAT) Satisfactory**
●	43. Boxes & Beams	**(SAT) Satisfactory**
●	44. Cylinders	**(SAT) Satisfactory**
●	45. Pads/Floats	**(SAT) Satisfactory**
●	46. Hoses/Fittings/Valves	**(SAT) Satisfactory**
Operators Station		
●	47. Windows & Wipers	**(SAT) Satisfactory**
●	48. Cab Door Restraint	**(SAT) Satisfactory**
●	49. Cab Access	**(SAT) Satisfactory**
●	50. Steps/Ladders/Handrails	**(SAT) Satisfactory**
●	51. Anti-Skid Stepping Surfaces	**(SAT) Satisfactory**
●	52. Fire Extinguisher	**(SAT) Satisfactory**
●	53. Operator Horn	**(REC) Recommendation**
	Operators horn not hooked up. Needs to be hooked up before using crane.	
●	54. Controls Identified	**(SAT) Satisfactory**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

55.	Control Functions	**(SAT) Satisfactory**
56.	Power Plant Controls	**(SAT) Satisfactory**
57.	Operator Cutoff Switch (Deadman)	**(SAT) Satisfactory**
58.	Brake & Clutch	**(NA) Not Applicable**
59.	Travel Controls	**(NA) Not Applicable**
60.	Accelerator/Throttle Control	**(SAT) Satisfactory**
61.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
62.	Housekeeping	**(SAT) Satisfactory**
Rotating Upper Structure		
63.	Structure	**(SAT) Satisfactory**
64.	Engine	**(NA) Not Applicable**
65.	Exhaust System/Guards/Insulators	**(NA) Not Applicable**
66.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
67.	Hydraulic & Pneumatic Pumps	**(SAT) Satisfactory**
68.	Hydraulic Pressure	**(SAT) Satisfactory**
69.	Electrical Wiring	**(SAT) Satisfactory**
70.	Ring & Pinion Gear	**(SAT) Satisfactory**
71.	Swing System/Assembly	**(SAT) Satisfactory**
72.	Counterweight Frame	**(SAT) Satisfactory**
73.	Counterweight Mounting	**(SAT) Satisfactory**
Hoist System		
74.	Brakes & Clutch System	**(SAT) Satisfactory**
75.	Wire Rope Reeving	**(SAT) Satisfactory**
	3 parts of line	
76.	2 Rope Wrap Minimum	**(SAT) Satisfactory**
77.	Hoist Motor	**(SAT) Satisfactory**
78.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
79.	Drums/Lagging/Flanges	**(SAT) Satisfactory**
80.	Anchor System	**(SAT) Satisfactory**
81.	Hoist Spooling	**(SAT) Satisfactory**
Main Boom		
82.	Lift Cylinder(s)	**(SAT) Satisfactory**
83.	Telescoping Boom Cylinder(s)	**(SAT) Satisfactory**
84.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
85.	Holding Device	**(SAT) Satisfactory**
86.	Boom Sections Alignment	**(SAT) Satisfactory**
87.	Wear Pads	**(SAT) Satisfactory**
88.	Sheaves	**(SAT) Satisfactory**
89.	Wire Rope Retainers	**(SAT) Satisfactory**
90.	Boom Hinge Pin	**(SAT) Satisfactory**
91.	Boom Head Section	**(SAT) Satisfactory**
92.	Auxiliary Boom Head	**(SAT) Satisfactory**
93.	Structure	**(SAT) Satisfactory**
Jib/Fly Extension		
94.	Structure	**(SAT) Satisfactory**
95.	Locking Devices	**(SAT) Satisfactory**
96.	Sheaves	**(SAT) Satisfactory**
97.	Wire Rope Retainers	**(SAT) Satisfactory**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

98.	Alignment	**(SAT) Satisfactory**
99.	End Connectors & Pins	**(SAT) Satisfactory**

Main Drum Wire Rope

100. Wire Rope Information

Diameter	Construction/Type	Number of Parts
19.61mm	**Non Rot RLL**	**3**

101.	Rope Damage	**(SAT) Satisfactory**
102.	Lubrication	**(SAT) Satisfactory**
103.	End Connectors	**(SAT) Satisfactory**

Main Hoist Load Block/Headache Ball/Hook

104. Capacity and Weight

Capacity	Weight
32 tonnes	**450 kg**

105.	Capacity Marking	**(SAT) Satisfactory**
106.	Weight Marking	**(SAT) Satisfactory**
107.	Sheave(s)	**(SAT) Satisfactory**
108.	Safety Latch(es)	**(SAT) Satisfactory**
109.	0° Hook Bend/Twist	**(SAT) Satisfactory**
110.	5% Hook Opening or 1/4" Max	**(SAT) Satisfactory**
111.	10% Hook Wear Max	**(SAT) Satisfactory**
112.	Bearing	**(SAT) Satisfactory**
113.	Wedge Socket/End Fitting	**(SAT) Satisfactory**
114.	Reeving	**(SAT) Satisfactory**

3 parts of line

Auxiliary Drum Wire Rope

115. Wire Rope Information

Diameter	Constrcution/Type	Number of Parts
19.87 mm	**Non Rot RLL**	**N/A**

Verification and Completion

116. Inspector Name & Signature **Anthony Capozzi**



117. Additional Inspection Notes

118. Sticker Given **(Y) Yes, Given on Site**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.