



Prepared for:

## **Sautter Crane rental**

2900 Black Lake Place Philadelphia, PA 19154

Sautter Yard

on

10/14/2023

Please return the entire report.

**Customer Sign Off**

**-If there are no deficiencies nothing needs to be done**

**-If there are any (HIGH, RED) deficiencies please follow the instructions below**

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to [tony.rossi@tandemlift.com](mailto:tony.rossi@tandemlift.com) or [jon.santimaw@tandemlift.com](mailto:jon.santimaw@tandemlift.com). After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

\_\_\_\_\_  
Signature

\_\_\_\_\_  
Date

# Table of Contents

 High  Med  Low Section

---


Inspection - <i>Sautter Yard</i>	Boom Truck Crane: 301395 - S283	0	1	1	<b>1.0</b>
----------------------------------	---------------------------------	---	---	---	------------

---

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

# Overview




## Breakdown by Form

Form Type	 High	 Med	 Low	# Forms
Inspection	0	1	1	1
<b>Overall:</b>	<b>0</b>	<b>1</b>	<b>1</b>	<b>1</b>

## Breakdown by Location

Location	 High	 Med	 Low	# Forms
Sautter Yard	0	1	1	1
<b>Overall:</b>	<b>0</b>	<b>1</b>	<b>1</b>	<b>1</b>

## Breakdown by Asset

Asset Type	 High	 Med	 Low	# Assets
Boom Truck Crane	0	1	1	1
<b>Overall:</b>	<b>0</b>	<b>1</b>	<b>1</b>	<b>1</b>

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Tandem Lift LLC  
 321 Enlow Place  
 Pennsville, NJ 08070  
 833-TANDEM1

## Inspection

**Sautter Crane rental**  
 2900 Black Lake Place  
 Philadelphia, PA 19154

FolderID: 101423S283  
 FormID: 18154766



### Boom Truck Crane

**Location:** Sautter Yard  
 2900 Black Lake Place  
 Philadelphia, PA 19154

**Serial #:** 301395

**TagID:** S283

*Additional Notes: 100 ft boom  
 2 parts of line*

**Manufacturer:** National

**Model Number:** 800D

**Capacity:** 23 Tons

**Hook Type :** Load Block & Hook

**Length/Lift:** 100 ft.

Priorities Found: ● 1 - Medium ● 1 - Low ● 100 - Good

### Miles and Hours

1. Miles	121,509 Miles
2. Hours	1,368 Hours

### General

● 3. Guards / Covers	(SAT) Satisfactory
● 4. External Lights	(SAT) Satisfactory
● 5. Warning Decals	(SAT) Satisfactory
● 6. Housekeeping	(SAT) Satisfactory
● 7. Hand Signal Chart	(SAT) Satisfactory

### Driver's Cab

● 12. Glass	(SAT) Satisfactory
● 13. Windshield Wipers	(SAT) Satisfactory
● 14. Mirrors	(SAT) Satisfactory
● 15. Fire Extinguishers	(SAT) Satisfactory
● 16. Seat	(SAT) Satisfactory
● 17. Seat Belt	(SAT) Satisfactory
● 18. Power Take-Off	(SAT) Satisfactory
● 19. Parking Brake	(SAT) Satisfactory
● 20. Air Pressure	(SAT) Satisfactory
● 21. Instruments / Gauges	(SAT) Satisfactory
● 22. Switches / Functions	(SAT) Satisfactory
● 23. Horn	(SAT) Satisfactory
● 24. Steering	(SAT) Satisfactory
● 25. Engine Clutch	(SAT) Satisfactory
● 26. Accelerator	(SAT) Satisfactory
● 27. Brake	(SAT) Satisfactory


Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 28. Defroster	(SAT) Satisfactory
● 29. Operator's Manual	(SAT) Satisfactory
<b>Truck Power Plant</b>	
● 30. Performance	(SAT) Satisfactory
● 31. Exhaust System Guards & Insulators	(SAT) Satisfactory
● 32. Belts / Hoses	(SAT) Satisfactory
● 33. Moving Parts Guards & Covers	(SAT) Satisfactory
<b>Chassis</b>	
● 34. Transmission	(SAT) Satisfactory
● 35. Driveline	(SAT) Satisfactory
● 36. Tires / Wheels	(SAT) Satisfactory
● 37. Tire Air Pressure	(SAT) Satisfactory
● 38. Chassis Frame Members	(SAT) Satisfactory
● 39. Hydraulic Hoses / Tubing / Fittings	(SAT) Satisfactory
● 40. Hydraulic Fluid Level	(REC) Recommendation
■ <i>Low on hydraulic oil</i>	
● 41. Anti Skid Surface	(SAT) Satisfactory
● 42. Guards / Covers	(SAT) Satisfactory
● 43. Backup Alarm	(SAT) Satisfactory
<b>Outriggers / Stabilizers</b>	
● 44. Boxes	(SAT) Satisfactory
● 45. Beams	(SAT) Satisfactory
● 46. Cylinders	(SAT) Satisfactory
● 47. Floats / Pads	(SAT) Satisfactory
● 48. Hydraulic Hoses / Tubes / Fittings	(SAT) Satisfactory
● 49. Holding Valves	(SAT) Satisfactory
● 50. Caution / Warning Signs	(SAT) Satisfactory
<b>Operators Station</b>	
● 51. Grab Rails / Steps / Platforms	(SAT) Satisfactory
● 52. Door Restraint	(NA) Not Applicable
● 53. Windows	(NA) Not Applicable
● 54. Anti Skid Surface	(SAT) Satisfactory
● 55. Fire Extinguisher	(NA) Not Applicable
● 56. Electrocutation Warning Sign	(SAT) Satisfactory
● 57. Controls Identified	(SAT) Satisfactory
● 58. Accelerator / Throttle Control	(SAT) Satisfactory
● 59. Horn	(SAT) Satisfactory
● 60. Seat	(NA) Not Applicable
<b>Load Chart</b>	
● 61. Per Configuration	(SAT) Satisfactory
● 62. Durable	(SAT) Satisfactory
● 63. Legible	(SAT) Satisfactory
● 64. Secured	(SAT) Satisfactory
● 65. Visible From Operators Station	(SAT) Satisfactory
<b>Safety Devices / Operational Aids</b>	
● 66. Boom Angle Indicator	(SAT) Satisfactory
● 67. Boom Length Indicator	(SAT) Satisfactory

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 68. Drum Rotation Indicator	(NA) Not Applicable
● 69. Overload Protection	(SAT) Satisfactory
● 70. Crane Level Indicator	(SAT) Satisfactory
● 71. Anti Two-Block Device	(SAT) Satisfactory
● 72. Outrigger / Stabilizer Position Sensor	(SAT) Satisfactory
<b>Upper Structure</b>	
● 73. Turntable	(SAT) Satisfactory
● 74. Mounting	(SAT) Satisfactory
● 75. Turret	(SAT) Satisfactory
● 76. Hydraulic Pump(s)	(SAT) Satisfactory
● 77. Hydraulic Hoses / Tubes / Fittings	(SAT) Satisfactory
● 78. Hydraulic Pressure	(SAT) Satisfactory
● 79. Electrical Wiring	(SAT) Satisfactory
● 80. Hoist Brake	(SAT) Satisfactory
● 81. Hoist - Motor / Valves / Lines	(SAT) Satisfactory
● 82. Hoist Spooling	(SAT) Satisfactory
● 83. Hoist - Minimum 2 Rope Wraps	(SAT) Satisfactory
● 84. Swing Gear Box	(SAT) Satisfactory
● 85. Electrocutation Warning Sign	(SAT) Satisfactory
<b>Main Boom</b>	
● 86. Lift Cylinder(s)	(SAT) Satisfactory
● 87. Telescoping Cylinder(s)	(SAT) Satisfactory
● 88. Hydraulic Hoses / Tubes / Fittings	(SAT) Satisfactory
● 89. Holding Device	(SAT) Satisfactory
● 90. Boom Sections Alignment	(SAT) Satisfactory
● 91. Wear Pads	(SAT) Satisfactory
● 92. Sheave(s)	(SAT) Satisfactory
● 93. Hoist Line Dead End	(SAT) Satisfactory
● 94. Wire Rope Retainer	(SAT) Satisfactory
● 95. Boom Hinge Pin	(SAT) Satisfactory
● 96. Boom Head Section	(SAT) Satisfactory
● 97. Structure	(SAT) Satisfactory
<b>Load Block &amp; Hook</b>	
● 103. Capacity Marking	(SAT) Satisfactory
● 104. Weight Marking	(SAT) Satisfactory
● 105. Sheave(s)	(SAT) Satisfactory
● 106. Safety Latch(s)	(SAT) Satisfactory
● 107. 0° Hook Bend or Twist	(SAT) Satisfactory
● 108. 5% Hook Opening or 1/4" Max	(SAT) Satisfactory
● 109. 10% Hook Wear Max	(SAT) Satisfactory
● 110. Bearing	(SAT) Satisfactory
● 111. Wedge Socket / End Fitting	(SAT) Satisfactory
● 112. Reeving	(SAT) Satisfactory
■ 2 parts of line	
<b>Wire Rope</b>	
● 121. Rope Damage	(MON) Monitor
■ Slight deformations at various spots in the cable	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 122. Measured Wear	(SAT) Satisfactory
■ 9/16 inch actual- 579 inch	
● 123. Broken Wires	(SAT) Satisfactory
● 124. Lubrication	(SAT) Satisfactory
● 125. End Connectors	(SAT) Satisfactory
<b>Verification and Completion</b>	
126. Inspector Name and Signature	Anthony Capozzi
	
127. Date of Inspection	10/14/2023
128. Customer Name and Signature	
● 129. Certificate Issued	(Y) Yes

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.