



Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

Sautter Yard

on

8/15/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

Signature

Date

Table of Contents

 High  Med  Low Section

Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400) - <i>Sautter Yard</i>	Telescoping Boom Crane: 056 838 - S360	0	0	0	1.0
---	---	---	---	---	------------

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview

Breakdown by Form

Form Type	 High	 Med	 Low	# Forms
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)	0	0	0	1
Overall:	0	0	0	1

Breakdown by Location

Location	 High	 Med	 Low	# Forms
Sautter Yard	0	0	0	1
Overall:	0	0	0	1

Breakdown by Asset

Asset Type	 High	 Med	 Low	# Assets
Telescoping Boom Crane	0	0	0	1
Overall:	0	0	0	1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)

Sautter Crane Rental
2900 Black Lake Place
Philadelphia, PA 19154

FolderID: 081526S360
FormID: 30383635



Telescoping Boom Crane

Location: Sautter Yard
2900 Black Lake Place
Philadelphia, PA 19154

Serial Number: 056 838

Unit Number: S360

Manufacturer: Liebherr

Model: LTC 1050-3.1

Capacity: 50 Tons

Length/Lift: 118'

Type of Crane: All Terrain Crane

Number of Hoists: Main and Auxiliary (Not in Use)

Boom Configuration: Main Boom with Stowed Jib

Load Test: No

Priorities Found: ● 105 - Good

General

- | | |
|--------------------------|---------------------------|
| 1. Location of Equipment | Sautter Crane Rental Yard |
| 2. Hours & Mileage | |
| Hours | Mileage |
| 2495 | 27,402 |

Inspection Information

- | | |
|----------------------|--------------|
| 3. Inspection Number | 081526S360 |
| 4. Inspection Date | 08/15/2026 |
| 5. Inspection Type | (Ann) Annual |

Information & Records

- | | | |
|---|--------------------|-----|
| 6. Documentation of Annual/Comprehensive Inspection | (SAT) Satisfactory | |
| 7. Daily/Monthly Inspection Records | (SAT) Satisfactory | |
| 8. Maintenance Records | (SAT) Satisfactory | |
| 9. Hand Signal Chart | (SAT) Satisfactory | P9 |
| 10. Safety and Warning Decals | (SAT) Satisfactory | P10 |
| 11. Operators Manual | (SAT) Satisfactory | |

Safety Devices & Operational Aids

- | | |
|----------------------------------|--------------------|
| 12. Backup Alarm | (SAT) Satisfactory |
| 13. Audible Warning Device | (SAT) Satisfactory |
| 14. Boom Angle Indicator | (SAT) Satisfactory |
| 15. Boom Length Indicator | (SAT) Satisfactory |
| 16. Drum Rotation Indicator(s) | (SAT) Satisfactory |
| 17. Anti Two-Block Device/System | (SAT) Satisfactory |
| 18. Load Moment Indicator (LMI) | (SAT) Satisfactory |
| 19. Load Weight Indicator | (SAT) Satisfactory |


Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 20. Radius Indicator	(SAT) Satisfactory	
● 21. Level Indicator(s)	(SAT) Satisfactory	
● 22. Fire Extinguisher	(SAT) Satisfactory	
Load Chart		
● 23. Visible/Accessible	(SAT) Satisfactory	
● 24. Per Configuration	(SAT) Satisfactory	
● 25. Durable/Legible/Secured	(SAT) Satisfactory	
Carrier		
● 26. Steering	(SAT) Satisfactory	
● 27. Parking Brake	(SAT) Satisfactory	
● 28. Exterior Lights (Headlights, Turn Signals, Brake Lights, Reverse Lights)	(SAT) Satisfactory	
● 29. Windshield & Wipers	(SAT) Satisfactory	
● 30. Windows & Mirrors	(SAT) Satisfactory	
● 31. Wheels & Tires	(SAT) Satisfactory	
● 32. Engine	(SAT) Satisfactory	
● 33. Exhaust System	(SAT) Satisfactory	
● 34. Axle Lockout	(SAT) Satisfactory	
● 35. Drive Line	(SAT) Satisfactory	
● 36. Main Frame Members	(SAT) Satisfactory	
● 37. Hoses/Fittings/Valves	(SAT) Satisfactory	
● 38. Hydraulic Tank & Fluid Level	(SAT) Satisfactory	
● 39. Slip Resistant Walking Surfaces	(SAT) Satisfactory	
● 40. Steps/Ladders/Handrails	(SAT) Satisfactory	P40
Outriggers/Stabilizers		
● 41. Structure & Mounting	(SAT) Satisfactory	
● 42. Boxes & Beams	(SAT) Satisfactory	
● 43. Cylinders	(SAT) Satisfactory	
● 44. Pads/Floats	(SAT) Satisfactory	P44
● 45. Hoses/Fittings/Valves	(SAT) Satisfactory	
Operators Station		
● 46. Windows & Wipers	(SAT) Satisfactory	
● 47. Cab Door Restraint	(SAT) Satisfactory	
● 48. Cab Access	(SAT) Satisfactory	P48
● 49. Steps/Ladders/Handrails	(SAT) Satisfactory	P49
● 50. Anti-Skid Stepping Surfaces	(SAT) Satisfactory	
● 51. Fire Extinguisher	(SAT) Satisfactory	
● 52. Operator Horn	(SAT) Satisfactory	
● 53. Controls Identified	(SAT) Satisfactory	
● 54. Control Functions	(SAT) Satisfactory	
● 55. Power Plant Controls	(SAT) Satisfactory	
● 56. Operator Cutoff Switch (Deadman)	(SAT) Satisfactory	
● 57. Brake & Clutch	(SAT) Satisfactory	
● 58. Travel Controls	(SAT) Satisfactory	
● 59. Accelerator/Throttle Control	(SAT) Satisfactory	
● 60. Hoses/Fittings/Valves	(SAT) Satisfactory	
● 61. Housekeeping	(SAT) Satisfactory	
Rotating Upper Structure		
● 62. Structure	(SAT) Satisfactory	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.


63.	Hoses/Fittings/Valves	(SAT) Satisfactory	
64.	Hydraulic & Pneumatic Pumps	(SAT) Satisfactory	
65.	Hydraulic Pressure	(SAT) Satisfactory	
66.	Electrical Wiring	(SAT) Satisfactory	
67.	Ring & Pinion Gear	(SAT) Satisfactory	P67
68.	Swing System/Assembly	(SAT) Satisfactory	
69.	Counterweight Mounting	(SAT) Satisfactory	
Hoist System			
70.	Brakes & Clutch System	(SAT) Satisfactory	
71.	Wire Rope Reeving	(SAT) Satisfactory	
72.	2 Rope Wrap Minimum	(SAT) Satisfactory	
73.	Hoist Motor	(SAT) Satisfactory	
74.	Hoses/Fittings/Valves	(SAT) Satisfactory	
75.	Drums/Lagging/Flanges	(SAT) Satisfactory	P75
76.	Anchor System	(SAT) Satisfactory	
77.	Hoist Spooling	(SAT) Satisfactory	
Main Boom			
78.	Lift Cylinder(s)	(SAT) Satisfactory	P78
79.	Telescoping Boom Cylinder(s)	(SAT) Satisfactory	
80.	Hoses/Fittings/Valves	(SAT) Satisfactory	
81.	Holding Device	(SAT) Satisfactory	
82.	Boom Sections Alignment	(SAT) Satisfactory	
83.	Wear Pads	(SAT) Satisfactory	
84.	Sheaves	(SAT) Satisfactory	P84
85.	Wire Rope Retainers	(SAT) Satisfactory	
86.	Boom Hinge Pin	(SAT) Satisfactory	
87.	Boom Head Section	(SAT) Satisfactory	
88.	Auxiliary Boom Head	(SAT) Satisfactory	
89.	Structure	(SAT) Satisfactory	
Jib/Fly Extension			
90.	Structure	(SAT) Satisfactory	
91.	Locking Devices	(SAT) Satisfactory	
92.	Sheaves	(SAT) Satisfactory	P92
93.	Wire Rope Retainers	(SAT) Satisfactory	
94.	Alignment	(SAT) Satisfactory	
95.	End Connectors & Pins	(SAT) Satisfactory	P95
Main Drum Wire Rope			
96.	Wire Rope Information		
	Diameter	Construction/Type	Number of Parts
	15mm	non rotational	2 parts
	 15.54mm		
97.	Rope Damage	(SAT) Satisfactory	
98.	Lubrication	(SAT) Satisfactory	
99.	End Connectors	(SAT) Satisfactory	
Main Hoist Load Block/Headache Ball/Hook			
100.	Capacity and Weight		
	Capacity	Weight	
	16 tons	95kg	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

101. Capacity Marking	(SAT) Satisfactory	P101
16 tons		
102. Weight Marking	(SAT) Satisfactory	P102
95kg		
103. Sheave(s)	(SAT) Satisfactory	
1 sheave		
104. Safety Latch(es)	(SAT) Satisfactory	
105. 0° Hook Bend/Twist	(SAT) Satisfactory	
106. 5% Hook Opening or 1/4" Max	(SAT) Satisfactory	
107. 10% Hook Wear Max	(SAT) Satisfactory	
108. Bearing	(SAT) Satisfactory	
109. Wedge Socket/End Fitting	(SAT) Satisfactory	P109
110. Reeving	(SAT) Satisfactory	
Auxiliary Drum Wire Rope		
111. Wire Rope Information		
Diameter	Constrcution/Type	Number of Parts
15mm	non rotational	stowed
Not in use		
Verification and Completion		
112. Inspector Name & Signature	James Doan	
		
113. Additional Inspection Notes	P113	
114. Sticker Given	(Y) Yes, Given on Site	



P9.1



P10.2



P10.3



P10.4



P10.5



P40.6



P44.7



P44.8



P44.9



P44.10



P48.11



P49.12




P67.13



P67.14



P75.15



P75.16




P78.17



P84.18



P92.19




P92.20


Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



P95.21



P100.22



P101.23



P102.24



P109.25



P113.26