



Below the Hook Lifting Devices
Sautter Crane Rental

FolderID: 12121
FormID: 16729914



Below the Hook Devices

Completed by: Dylan VanHorn on 05/06/2023

Location: Black Lake Place, Phila., PA

Serial Number: J7942

Unit #: HMB12

Type: Manbasket (1926.1431)

Manufacturer: Lakeshore Industrial

Model Number: M44

Capacity: 900 lbs

Net Weight: 550 lbs

Rigging Attached : Yes

Work Performed: Inspection

Priorities Found: ● 17 - Good

Location of Equipment

1. Location of Equipment **Philadelphia, PA**

Customer Sign Off

2. Customer Sign Off

IF THERE ARE NO DEFICIENCIES NOTHING NEEDS TO BE DONE.

IF THERE ARE ANY HIGH, RED, DEFICIENCIES PLEASE FOLLOW THE BELOW INSTRUCTIONS

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS PAGE ONLY to either jaim@atlanticcrane.com or gina@atlanticcrane.com or fax THIS PAGE ONLY to our office at 215-639-2316 and a certification and sticker will be issued. The above deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However, those items should be corrected to improve equipment reliability and safety.

The undersigned verifies the listed deficiencies denoted with an (DEF, HIGH, RED) have been corrected.

Signature

Date

Inspection Information

3. Inspection Number **23050601DV**

4. Inspection Date **05/06/2023**

● 5. Inspection Type **(Ann) Annual**

Manbasket

6. Max Persons **3**

● 7. Rating Plate **(SAT) Satisfactory**

● 8. Grab Rail **(SAT) Satisfactory**

● 9. Access Gate **(SAT) Satisfactory**


● 10. Access Gate Lock **(SAT) Satisfactory**

● 11. Headroom **(SAT) Satisfactory**

● 12. Edge & Surfaces **(SAT) Satisfactory**

● 13. Welds **(SAT) Satisfactory**

Atlantic Crane Inspection Services disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Atlantic Crane Inspection Services. Atlantic Crane Inspection Services shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 14. Lifting Eyes			(SAT) Satisfactory
● 15. Lanyard Attachment Points			(SAT) Satisfactory
● 16. Toe Board & Mid Rail			(SAT) Satisfactory
● 17. Mesh Walling			(SAT) Satisfactory
● 18. Hand Signal Chart			(SAT) Satisfactory
19. Test Weight			
Weight	Tested	How Long Tested	
1125 lbs	No	N/A	
Rigging			
20. Wire Rope Information			
Size	Overall Capacity	Number of Legs	
1/2"	8.8 tons	4 legs	
☐ <i>5/8" / 6' / 8.8tons / 1 Leg</i>			
● 21. Wire Rope Condition			(SAT) Satisfactory
22. Shackle Information			
Size	Capacity	Number of Shackles	
5/8"	3 1/4 tons	4 shackles	
☐ <i>3/4" / 4 3/4 tons / 1 shackle</i>			
● 23. Shackle Condition			(SAT) Satisfactory
24. Ring Link Information			
Size	Capacity		
1 1/4"			
● 25. Ring Link Condition			(SAT) Satisfactory
Verification and Completion			
26. Inspector Name & Signature			Dylan VanHorn
			
27. Additional Inspection Notes			
<i>No visible deficiencies found at time of inspection</i>			
● 28. Sticker Given			(N) No, Will be Mailed

Atlantic Crane Inspection Services disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Atlantic Crane Inspection Services. Atlantic Crane Inspection Services shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.