



Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

3400 Spruce Street Phila

on

8/29/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

Signature

Date

Table of Contents

 High  Med  Low Section

Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400) - 3400 Spruce Street Phila	Telescoping Boom Crane: 046 840 - S344	0	0	0	1.0
--	---	---	---	---	------------

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview

Breakdown by Form

Form Type	 High	 Med	 Low	# Forms
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)	0	0	0	1
Overall:	0	0	0	1

Breakdown by Location

Location	 High	 Med	 Low	# Forms
3400 Spruce Street Phila	0	0	0	1
Overall:	0	0	0	1

Breakdown by Asset

Asset Type	 High	 Med	 Low	# Assets
Telescoping Boom Crane	0	0	0	1
Overall:	0	0	0	1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)

Sautter Crane Rental
2900 Black Lake Place
Philadelphia, PA 19154

FolderID: 082926S344
FormID: 30581172



Telescoping Boom Crane

Location: 3400 Spruce Street Phila

Serial Number: 046 840

Unit Number: S344

Status: In Service

Additional Notes: 207 ft Luffing Jib with 40 ft extension and Y Guy
341,000 lbs counterweight
1 part of line

Manufacturer: Liebherr

Model: LTM 1650-8.1

Capacity: 770 Tons

Length/Lift: 263'

Type of Crane: All Terrain Crane

Number of Hoists: Main and Auxiliary

Boom Configuration: Main Boom & Luffing Jib Assembled

Load Test: No

Priorities Found: ● 121 - Good

General

1. Location of Equipment **3400 Spruce Street**

2. Customer Sign Off

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

Signature

3. Hours & Mileage

Hours

Mileage

3,709

14,958

Inspection Information

4. Inspection Number **082926S344**

5. Inspection Date **08/29/2026**

6. Inspection Type **(Ann) Annual**

Information & Records

7. Documentation of Annual/Comprehensive Inspection **(SAT) Satisfactory**

8. Daily/Monthly Inspection Records **(SAT) Satisfactory**

9. Maintenance Records **(SAT) Satisfactory**

10. Hand Signal Chart **(SAT) Satisfactory**

11. Safety and Warning Decals **(SAT) Satisfactory**

12. Operators Manual **(SAT) Satisfactory**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Safety Devices & Operational Aids		
● 13.	Backup Alarm	(SAT) Satisfactory
● 14.	Audible Warning Device	(SAT) Satisfactory
● 15.	Boom Angle Indicator	(SAT) Satisfactory
● 16.	Boom Length Indicator	(SAT) Satisfactory
● 17.	Drum Rotation Indicator(s)	(SAT) Satisfactory
● 18.	Anti Two-Block Device/System	(SAT) Satisfactory
● 19.	Load Moment Indicator (LMI)	(SAT) Satisfactory
● 20.	Load Weight Indicator	(SAT) Satisfactory
● 21.	Radius Indicator	(SAT) Satisfactory
● 22.	Level Indicator(s)	(SAT) Satisfactory
● 23.	Fire Extinguisher	(SAT) Satisfactory
Load Chart		
● 24.	Visible/Accessible	(SAT) Satisfactory
● 25.	Per Configuration	(SAT) Satisfactory
● 26.	Durable/Legible/Secured	(SAT) Satisfactory
Carrier		
● 27.	Steering	(SAT) Satisfactory
● 28.	Parking Brake	(SAT) Satisfactory
● 29.	Exterior Lights (Headlights, Turn Signals, Brake Lights, Reverse Lights)	(SAT) Satisfactory
● 30.	Windshield & Wipers	(SAT) Satisfactory
● 31.	Windows & Mirrors	(SAT) Satisfactory
● 32.	Wheels & Tires	(SAT) Satisfactory
● 33.	Engine	(SAT) Satisfactory
● 34.	Exhaust System	(SAT) Satisfactory
● 35.	Axle Lockout	(SAT) Satisfactory
● 36.	Drive Line	(SAT) Satisfactory
● 37.	Main Frame Members	(SAT) Satisfactory
● 38.	Hoses/Fittings/Valves	(SAT) Satisfactory
● 39.	Hydraulic Tank & Fluid Level	(SAT) Satisfactory
● 40.	Slip Resistant Walking Surfaces	(SAT) Satisfactory
● 41.	Steps/Ladders/Handrails	(SAT) Satisfactory
Outriggers/Stabilizers		
● 42.	Structure & Mounting	(SAT) Satisfactory
● 43.	Boxes & Beams	(SAT) Satisfactory
● 44.	Cylinders	(SAT) Satisfactory
● 45.	Pads/Floats	(SAT) Satisfactory
● 46.	Hoses/Fittings/Valves	(SAT) Satisfactory
Operators Station		
● 47.	Windows & Wipers	(SAT) Satisfactory
● 48.	Cab Door Restraint	(SAT) Satisfactory
● 49.	Cab Access	(SAT) Satisfactory
● 50.	Steps/Ladders/Handrails	(SAT) Satisfactory
● 51.	Anti-Skid Stepping Surfaces	(SAT) Satisfactory
● 52.	Fire Extinguisher	(SAT) Satisfactory
● 53.	Operator Horn	(SAT) Satisfactory
● 54.	Controls Identified	(SAT) Satisfactory
● 55.	Control Functions	(SAT) Satisfactory

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 56.	Power Plant Controls	(SAT) Satisfactory
● 57.	Operator Cutoff Switch (Deadman)	(SAT) Satisfactory
● 58.	Brake & Clutch	(NA) Not Applicable
● 59.	Travel Controls	(NA) Not Applicable
● 60.	Accelerator/Throttle Control	(SAT) Satisfactory
● 61.	Hoses/Fittings/Valves	(SAT) Satisfactory
● 62.	Housekeeping	(SAT) Satisfactory
Rotating Upper Structure		
● 63.	Structure	(SAT) Satisfactory
● 64.	Engine	(NA) Not Applicable
● 65.	Exhaust System/Guards/Insulators	(NA) Not Applicable
● 66.	Hoses/Fittings/Valves	(SAT) Satisfactory
● 67.	Hydraulic & Pneumatic Pumps	(SAT) Satisfactory
● 68.	Hydraulic Pressure	(SAT) Satisfactory
● 69.	Electrical Wiring	(SAT) Satisfactory
● 70.	Ring & Pinion Gear	(SAT) Satisfactory
● 71.	Swing System/Assembly	(SAT) Satisfactory
● 72.	Counterweight Frame	(SAT) Satisfactory
● 73.	Counterweight Mounting	(SAT) Satisfactory
Hoist System		
● 74.	Brakes & Clutch System	(SAT) Satisfactory
● 75.	Wire Rope Reeving	(SAT) Satisfactory
●	1 part of line	
● 76.	2 Rope Wrap Minimum	(SAT) Satisfactory
● 77.	Hoist Motor	(SAT) Satisfactory
● 78.	Hoses/Fittings/Valves	(SAT) Satisfactory
● 79.	Drums/Lagging/Flanges	(SAT) Satisfactory
● 80.	Anchor System	(SAT) Satisfactory
● 81.	Hoist Spooling	(SAT) Satisfactory
Main Boom		
● 82.	Lift Cylinder(s)	(SAT) Satisfactory
● 83.	Telescoping Boom Cylinder(s)	(SAT) Satisfactory
● 84.	Hoses/Fittings/Valves	(SAT) Satisfactory
● 85.	Holding Device	(SAT) Satisfactory
● 86.	Boom Sections Alignment	(SAT) Satisfactory
● 87.	Wear Pads	(SAT) Satisfactory
● 88.	Sheaves	(SAT) Satisfactory
● 89.	Wire Rope Retainers	(SAT) Satisfactory
● 90.	Boom Hinge Pin	(SAT) Satisfactory
● 91.	Boom Head Section	(SAT) Satisfactory
● 92.	Auxiliary Boom Head	(NA) Not Applicable
● 93.	Structure	(SAT) Satisfactory
Luffing Boom Attachment		
● 94.	Luffing Jib Section Identification	(SAT) Satisfactory
● 95.	Luffing Jib Section Sequence	(SAT) Satisfactory
● 96.	Luffing Jib Tip Section	(SAT) Satisfactory
● 97.	Luffing Jib Point Sheaves	(SAT) Satisfactory
● 98.	Luffing Hoist Line Dead End	(SAT) Satisfactory

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 99.	Luffing Jib Warning Decals	(SAT) Satisfactory
● 100.	Luffing Jib Foot Keepers & Pins	(SAT) Satisfactory
● 101.	Lattice Members	(SAT) Satisfactory
● 102.	Cord Members	(SAT) Satisfactory
● 103.	End Connections & Pins	(SAT) Satisfactory
● 104.	Luffing Jib Angle Indicator	(SAT) Satisfactory
● 105.	Luffing Jib Stops	(SAT) Satisfactory
● 106.	Luffing Jib Hoist Reeving	(SAT) Satisfactory
● 107.	Guard Rails & Walking Surfaces	(SAT) Satisfactory
Main Drum Wire Rope		
● 108.	Wire Rope Information	
	Diameter	Construction/Type
	25.66 mm	Non Rot RLL
		Number of Parts
		1
● 109.	Rope Damage	(SAT) Satisfactory
● 110.	Lubrication	(SAT) Satisfactory
● 111.	End Connectors	(SAT) Satisfactory
Main Hoist Load Block/Headache Ball/Hook		
● 112.	Capacity and Weight	
	Capacity	Weight
	16 tonnes	700 kg
● 113.	Capacity Marking	(SAT) Satisfactory
● 114.	Weight Marking	(SAT) Satisfactory
● 115.	Sheave(s)	(NA) Not Applicable
● 116.	Safety Latch(es)	(SAT) Satisfactory
● 117.	0° Hook Bend/Twist	(SAT) Satisfactory
● 118.	5% Hook Opening or 1/4" Max	(SAT) Satisfactory
● 119.	10% Hook Wear Max	(SAT) Satisfactory
● 120.	Bearing	(SAT) Satisfactory
● 121.	Wedge Socket/End Fitting	(SAT) Satisfactory
● 122.	Reeving	(SAT) Satisfactory
●	1 part of line	
Auxiliary Drum Wire Rope		
● 123.	Wire Rope Information	
	Diameter	Constrcution/Type
	25.88 mm	RRL
		Number of Parts
		Luffing Jib
● 124.	Rope Damage	(SAT) Satisfactory
● 125.	Lubrication	(SAT) Satisfactory
● 126.	End Connectors	(SAT) Satisfactory
Verification and Completion		
● 127.	Inspector Name & Signature	Anthony Capozzi
		
	128. Additional Inspection Notes	
● 129.	Sticker Given	(Y) Yes, Given on Site

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.