


| <b>Certificate of Unit Test/Examination of Lifting Device</b> |  |
|---|--|
| <b>Certificate Number:</b>                                    | 102619- SB03   |
| <b>Unit Number:</b>   | SB03   |
| <b>Company Name:</b>  | Sautter Crane  |
| <b>Address:</b>   | 2900 Black Lake Pl., Phila., PA  |
| <b>Manufacturer:</b>  | n/a  |
| <b>Serial Number:</b>   | n/a  |
| <b>Model:</b>   | n/a  |
| <b>Type Of Lifting Device:</b>                                | Lifting Beam   |
| <b>Maximum Rated Capacity:</b>                                | 25,000 lbs   |
| <b>Length:</b>  | 6-10 ft.   |
| <b>Weight:</b>  | 100 lbs  |
| <b>Test Loads Applied</b>                                     |  |
| <b>Rated Load:</b>  | n/a  |
| <b>Proof Load:</b>  | n/a  |
| <b>Description of Proof Load:</b>                             | n/a  |
| <b>Basis for Assigned Load Ratings:</b>                       | n/a  |
| <b>Remarks and/or Limitations Assigned:</b>                   | Rigging designated with lifting beam was inspected as part of this annual inspection. This includes shackles and wire chokers identified with zip tie #'s 673, 682, 655, and 604.                                      |
|   | I certify that the above device was tested and/or examined by the undersigned and authorized representative who, in their opinion, said the unit met the requirements of OSHA 1926.1431 subpart CC and/or ASME B30.20. |
| <b>Qualified Inspector:</b>                                   |    |
| <b>Date:</b>  | 10/26/2019   |
| <b>Email</b>  |  |

The message has been sent from 198.185.128.1 (United States) at 2019-10-28 06:32:51 on Chrome 78.0.3904.70  
Entry ID: 60