



Below the Hook Lifting Devices
Sautter Crane Rental

FolderID: 11974
FormID: 16400314



Below the Hook Devices

Completed by: Matt Hottenstein on 04/03/2023

Location: USA

Serial Number: J6894

Unit #: MB-2

Type: Manbasket (1926.1431)

Manufacturer: Lakeshore

Model Number: M44

Capacity: 1000 lbs

Net Weight: 550 lbs

Rigging Attached : Yes

Work Performed: Inspection

Priorities Found: ● **16 - Good**

Location of Equipment

1. Location of Equipment **Philadelphia PA Yard**

Customer Sign Off

2. Customer Sign Off

IF THERE ARE NO DEFICIENCIES NOTHING NEEDS TO BE DONE.

IF THERE ARE ANY HIGH, RED, DEFICIENCIES PLEASE FOLLOW THE BELOW INSTRUCTIONS

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS PAGE ONLY to either jaime@atlanticcrane.com or gina@atlanticcrane.com or fax THIS PAGE ONLY to our office at 215-639-2316 and a certification and sticker will be issued. The above deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However, those items should be corrected to improve equipment reliability and safety.

The undersigned verifies the listed deficiencies denoted with an (DEF, HIGH, RED) have been corrected.

Signature

Date

Inspection Information

3. Inspection Number **23040301MH**

4. Inspection Date **04/03/2023**

● 5. Inspection Type **(Ann) Annual**

Manbasket

6. Max Persons **3**

● 7. Rating Plate **(SAT) Satisfactory**

● 8. Grab Rail **(SAT) Satisfactory**

● 9. Access Gate **(SAT) Satisfactory**

● 10. Access Gate Lock **(SAT) Satisfactory**

● 11. Headroom **(SAT) Satisfactory**

● 12. Edge & Surfaces **(SAT) Satisfactory**

● 13. Welds **(SAT) Satisfactory**

● 14. Lifting Eyes **(SAT) Satisfactory**

● 15. Lanyard Attachment Points **(SAT) Satisfactory**

Atlantic Crane Inspection Services disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Atlantic Crane Inspection Services. Atlantic Crane Inspection Services shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

- 16. Toe Board & Mid Rail **(SAT) Satisfactory**
- 17. Mesh Walling **(SAT) Satisfactory**
- 18. Hand Signal Chart **(SAT) Satisfactory**

Rigging



19. Wire Rope Information P21

Size	Overall Capacity	Number of Legs
1/2"	8.8 ton	5

● 20. Wire Rope Condition **(SAT) Satisfactory**

21. Shackle Information

Size	Capacity	Number of Shackles
5/8"	3.25 ton	5

● 22. Shackle Condition **(SAT) Satisfactory**

23. Ring Link Information

Size	Capacity


● 24. Ring Link Condition **(SAT) Satisfactory**

Verification and Completion

25. Inspector Name & Signature

26. Additional Inspection Notes

No visible deficiencies found at time of inspection



P21.1