



Below the Hook Lifting Devices
 Sautter Crane Rental

FolderID: 12158
 FormID: 16786314



Below the Hook Devices
Completed by: Dylan VanHorn on 05/13/2023
 Location: Newark, DE
 Serial Number: J5372
 Unit #: 4

Type: Manbasket (1926.1431)
 Manufacturer: Lakeshore Industrial
 Model Number: M44
 Capacity: 1000 lbs
 Net Weight: 540
 Rigging Attached : Yes
 Work Performed: Inspection

Priorities Found: ● 1 - Medium ● 17 - Good

Location of Equipment

1. Location of Equipment Newark, DE

Customer Sign Off

2. Customer Sign Off

IF THERE ARE NO DEFICIENCIES NOTHING NEEDS TO BE DONE.

IF THERE ARE ANY HIGH, RED, DEFICIENCIES PLEASE FOLLOW THE BELOW INSTRUCTIONS

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS PAGE ONLY to either jaime@atlanticcrane.com or gina@atlanticcrane.com or fax THIS PAGE ONLY to our office at 215-639-2316 and a certification and sticker will be issued. The above deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However, those items should be corrected to improve equipment reliability and safety.

The undersigned verifies the listed deficiencies denoted with an (DEF, HIGH, RED) have been corrected.

 Signature

 Date


Inspection Information

3. Inspection Number 23051301DV
 4. Inspection Date 05/13/2023
 ● 5. Inspection Type (Ann) Annual

Manbasket

6. Max Persons 4
 ● 7. Rating Plate (SAT) Satisfactory
 ● 8. Grab Rail (SAT) Satisfactory
 ● 9. Access Gate (SAT) Satisfactory
 ● 10. Access Gate Lock (SAT) Satisfactory
 ● 11. Headroom (SAT) Satisfactory
 ● 12. Edge & Surfaces (SAT) Satisfactory
 ● 13. Welds (SAT) Satisfactory

Atlantic Crane Inspection Services disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Atlantic Crane Inspection Services. Atlantic Crane Inspection Services shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

●	14. Lifting Eyes			(SAT) Satisfactory
●	15. Lanyard Attachment Points			(SAT) Satisfactory
●	16. Toe Board & Mid Rail			(SAT) Satisfactory
●	17. Overhead Protection			(SAT) Satisfactory
●	18. Mesh Walling			(SAT) Satisfactory
●	19. Hand Signal Chart			(SAT) Satisfactory
Rigging				
	20. Wire Rope Information			
	Size	Overall Capacity	Number of Legs	
	5/8"	14 tons	5 Legs	
●	21. Wire Rope Condition			(REC) Recommendation
	☞ <i>Lubricate wire rope.</i>			
	22. Shackle Information			
	Size	Capacity	Number of Shackles	
	3/4"	4 3/4 tons	4	
	☞ <i>7/8" / 6 1/2 tons / 1 shackle</i>			
●	23. Shackle Condition			(SAT) Satisfactory
	24. Ring Link Information			
	Size	Capacity		
	1 1/2"			
●	25. Ring Link Condition			(SAT) Satisfactory
Verification and Completion				
	26. Inspector Name & Signature			Dylan VanHorn
				
	27. Additional Inspection Notes			
	<i>No visible deficiencies found at time of inspection</i>			
●	28. Sticker Given			(N) No, Will be Mailed