



Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

Sautter Yard

on

7/21/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

Signature

Date

Table of Contents

 High  Med  Low Section

Lifting Bar - <i>Sautter Yard</i>	Below the Hook Devices: 6-196930-5 - SB-12	0	0	0	1.0
-----------------------------------	---	---	---	---	------------

Overview

Breakdown by Form

Form Type	 High	 Med	 Low	# Forms
Lifting Bar	0	0	0	1
Overall:	0	0	0	1

Breakdown by Location

Location	 High	 Med	 Low	# Forms
Sautter Yard	0	0	0	1
Overall:	0	0	0	1

Breakdown by Asset

Asset Type	 High	 Med	 Low	# Assets
Below the Hook Devices	0	0	0	1
Overall:	0	0	0	1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Lifting Bar
Sautter Crane Rental
2900 Black Lake Place
Philadelphia, PA 19154

FolderID: 072126SB-12
FormID: 30050379



Below the Hook Devices

Location: Sautter Yard
2900 Black Lake Place
Philadelphia, PA 19154

Identifier: 6-196930-5

TagID: SB-12

Status: In Service

Type: Spreader Bar

Capacity: 10 tons

Manufacturer: Caldwell

Model Number: 32-10-8/14

Length/Lift: 8'-14'

Priorities Found: ● 6 - Good

General

● 1. Bar has no obvious bend, twist or deformation. (SAT) Satisfactory

Manufacturer

2. Make Caldwell

Manufacturer Model Number

3. Model 32-10-8/14

Capacity

4. Rated Capacity of device 10 tons

Tare Weight

5. Weight of device 460lbs

Markings

● 6. The weight and capacity of the device are clearly and permanently displayed. (Y) Yes P6

Corrosion

● 8. No visible corrosion that may effect the structural integrity of the device. (SAT) Satisfactory

Rigging Connection Points

● 9. All possible points of connection do not have any visible cracks, deformation or excessive wear. (SAT) Satisfactory P9

Adjustability

● 10. If the device is adjustable, Are all pins/fixtures secure and in proper working condition? (Y) Yes P10

Name Of Inspector

11. Inspector James Doan

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Date Of Inspection

12. Inspection performed on

07/21/2026


Certificate

13. Was a certificate issued?

(Y) Yes



P6.1



P9.2:



P9.3



P9.4



P9.5



P9.6



P9.7



P10.8

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.