Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

1020 Riverside Drive Pottstown PA.

on

11/5/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

_____ _____

Signature Date

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Table of Contents

		High	Med	Low	Section
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400) - *1020 Riverside Drive Pottstown PA.*	Telescoping Boom Crane*: 047 597 - S326*	0	0	0	**1.0**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview

Breakdown by Form

Form Type	High	Med	Low	# Forms
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Breakdown by Location

Location	High	Med	Low	# Forms
1020 Riverside Drive Pottstown PA.	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Breakdown by Asset

Asset Type	High	Med	Low	# Assets
Telescoping Boom Crane	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)

FolderID: 110526S326
FormID: 31549808

Sautter Crane Rental
2900 Black Lake Place
Philadelphia, PA 19154



Telescoping Boom Crane

Completed by: Steve Edling on 11/05/2026

Location:	1020 Riverside Drive Pottstown PA.
Serial Number:	047 597
Unit Number:	S326
Status:	In Service

Manufacturer:	Liebherr
Model:	LTR 1220
Capacity:	250 tons
Length/Lift:	86 Ft.
Type of Crane:	Load Block & Hook
Number of Hoists:	Main Only
Boom Configuration:	Main Boom w/o Attached Jib
Load Test:	No

Priorities Found: **94 - Good**

General				
	1.	Location of Equipment	**1020 Riverside Drive Pottstown PA.**	
	2.	Customer Sign Off		
	3.	Hours & Mileage		
		Hours: **1395.0** / Mileage: **0**		
Inspection Information				
	4.	Inspection Number	**110526S326**	
	5.	Inspection Date	**11/05/2026**	
●	6.	Inspection Type	**(Ann) Annual**	
Information & Records				
●	7.	Documentation of Annual/Comprehensive Inspection	**(SAT) Satisfactory**	
●	8.	Daily/Monthly Inspection Records	**(SAT) Satisfactory**	
●	9.	Maintenance Records	**(SAT) Satisfactory**	
●	10.	Hand Signal Chart	**(SAT) Satisfactory**	P10
●	11.	Safety and Warning Decals	**(SAT) Satisfactory**	P11
●	12.	Operators Manual	**(SAT) Satisfactory**	
●	13.	Equipment Modification(s) or Additions	**(SAT) Satisfactory**	
Safety Devices & Operational Aids				
●	14.	Backup Alarm	**(SAT) Satisfactory**	
●	15.	Audible Warning Device	**(SAT) Satisfactory**	
●	16.	Boom Angle Indicator	**(SAT) Satisfactory**	P16
●	17.	Boom Length Indicator	**(SAT) Satisfactory**	
●	18.	Drum Rotation Indicator(s)	**(SAT) Satisfactory**	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

19.	Anti Two-Block Device/System	**(SAT) Satisfactory**	
20.	Load Moment Indicator (LMI)	**(SAT) Satisfactory**	
21.	Load Weight Indicator	**(SAT) Satisfactory**	
22.	Radius Indicator	**(SAT) Satisfactory**	
23.	Level Indicator(s)	**(SAT) Satisfactory**	
24.	Fire Extinguisher	**(SAT) Satisfactory**	
Load Chart			
25.	Visible/Accessible	**(SAT) Satisfactory**	
26.	Per Configuration	**(SAT) Satisfactory**	
27.	Durable/Legible/Secured	**(SAT) Satisfactory**	
Crawler Assembly			
28.	Car Body & Side Frames	**(SAT) Satisfactory**	
29.	Chain & Idler Sprockets	**(SAT) Satisfactory**	P29
30.	Crawler Tracks/Pads/Pins	**(SAT) Satisfactory**	P30
31.	Travel Steering/Brakes/Locking Devices	**(NA) Not Applicable**	
32.	Steering Clutches	**(NA) Not Applicable**	
Operators Station			
71.	Windows & Wipers	**(SAT) Satisfactory**	
72.	Cab Door Restraint	**(SAT) Satisfactory**	
73.	Cab Access	**(SAT) Satisfactory**	
74.	Steps/Ladders/Handrails	**(SAT) Satisfactory**	
75.	Anti-Skid Stepping Surfaces	**(SAT) Satisfactory**	
76.	Fire Extinguisher	**(SAT) Satisfactory**	
77.	Operator Horn	**(SAT) Satisfactory**	
78.	Controls Identified	**(SAT) Satisfactory**	P78
79.	Control Functions	**(SAT) Satisfactory**	
80.	Power Plant Controls	**(SAT) Satisfactory**	
81.	Operator Cutoff Switch (Deadman)	**(SAT) Satisfactory**	
82.	Brake & Clutch	**(NA) Not Applicable**	
83.	Travel Controls	**(SAT) Satisfactory**	
84.	Accelerator/Throttle Control	**(SAT) Satisfactory**	
85.	Hoses/Fittings/Valves	**(SAT) Satisfactory**	
86.	Housekeeping	**(SAT) Satisfactory**	
Upper Structure			
87.	Turntable	**(SAT) Satisfactory**	P87
88.	Mounting	**(SAT) Satisfactory**	
89.	Turret	**(SAT) Satisfactory**	
90.	Hydraulic Pump(s)	**(SAT) Satisfactory**	
91.	Hoses/Fittings/Valves	**(SAT) Satisfactory**	
92.	Electrical Wiring	**(SAT) Satisfactory**	
93.	Hoist Brake	**(SAT) Satisfactory**	
94.	Hoist Motor	**(SAT) Satisfactory**	
95.	Hoist Spooling	**(SAT) Satisfactory**	P95
96.	Hoist-Minimum 2 Rope Wraps	**(SAT) Satisfactory**	P96
97.	Swing Gearbox	**(SAT) Satisfactory**	
Rotating Upper Structure			
98.	Structure	**(SAT) Satisfactory**	
99.	Engine	**(SAT) Satisfactory**	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

100. Exhaust System/Guards/Insulators		**(SAT) Satisfactory**	
101. Hoses/Fittings/Valves		**(SAT) Satisfactory**	
102. Hydraulic & Pneumatic Pumps		**(SAT) Satisfactory**	
103. Hydraulic Pressure		**(SAT) Satisfactory**	
104. Electrical Wiring		**(SAT) Satisfactory**	
105. Ring & Pinion Gear		**(SAT) Satisfactory**	P105
106. Swing System/Assembly		**(SAT) Satisfactory**	
107. Counterweight Frame		**(SAT) Satisfactory**	P107
108. Counterweight Mounting		**(SAT) Satisfactory**	P108
Hoist System			
109. Brakes & Clutch System		**(NA) Not Applicable**	
110. Wire Rope Reeving		**(SAT) Satisfactory**	
111. 2 Rope Wrap Minimum		**(SAT) Satisfactory**	P111
112. Hoist Motor		**(SAT) Satisfactory**	
113. Hoses/Fittings/Valves		**(SAT) Satisfactory**	
114. Drums/Lagging/Flanges		**(SAT) Satisfactory**	
115. Anchor System		**(SAT) Satisfactory**	
116. Hoist Spooling		**(SAT) Satisfactory**	
Main Boom			
117. Lift Cylinder(s)		**(SAT) Satisfactory**	
118. Telescoping Boom Cylinder(s)		**(SAT) Satisfactory**	
119. Hoses/Fittings/Valves		**(SAT) Satisfactory**	
120. Holding Device		**(SAT) Satisfactory**	
121. Boom Sections Alignment		**(SAT) Satisfactory**	P121
122. Wear Pads		**(SAT) Satisfactory**	
123. Sheaves		**(SAT) Satisfactory**	
124. Wire Rope Retainers		**(SAT) Satisfactory**	
125. Boom Hinge Pin		**(SAT) Satisfactory**	
126. Boom Head Section		**(SAT) Satisfactory**	
127. Auxiliary Boom Head		**(NA) Not Applicable**	
128. Structure		**(SAT) Satisfactory**	
Main Drum Wire Rope			
129. Wire Rope Information			
Diameter	Construction/Type	Number of Parts	
23 mm	**non rotation**	**6**	
130. Rope Damage		**(SAT) Satisfactory**	
131. Lubrication		**(SAT) Satisfactory**	
132. End Connectors		**(SAT) Satisfactory**	
Main Hoist Load Block/Headache Ball/Hook			
133. Capacity and Weight			
Capacity	Weight		
125 tons	**1250 kg**		
134. Capacity Marking		**(SAT) Satisfactory**	P134
135. Weight Marking		**(SAT) Satisfactory**	
136. Sheave(s)		**(SAT) Satisfactory**	P136
137. Safety Latch(es)		**(SAT) Satisfactory**	
138. 0° Hook Bend/Twist		**(SAT) Satisfactory**	
139. 5% Hook Opening or 1/4" Max		**(SAT) Satisfactory**	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

140.	10% Hook Wear Max	**(SAT) Satisfactory**
141.	Bearing	**(SAT) Satisfactory**
142.	Wedge Socket/End Fitting	**(SAT) Satisfactory**
143.	Reeving	**(SAT) Satisfactory**

Verification and Completion

144. Inspector Name & Signature **Steven Edling**



145. Additional Inspection Notes

146. Sticker Given **(Y) Yes, Given on Site** P146



P10.1



P11.2



P16.3



P29.4



P30.5



P78.6



P87.7



P95.8



P96.9



P105.10



P107.11



P108.12

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



P111.13



P121.14



P134.15



P136.16



P146.17

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.