

Below the Hook Lifting Devices Sautter Crane Rental

FolderID: 12158 FormID: 16786318



Below the Hook Devices Completed by: Dylan VanHorn on 05/13/2023 Location: Newark, DE 521712 Serial Number: Unit #: 18

Type:	Lifting Beam (B30.20)
Manufacturer:	ASC
Model Number:	Z2010081
Capacity:	10 tons
Net Weight:	320 lbs
Rigging Attached :	Yes
Work Performed:	Inspection

Priorities Found: 11 - Good

Location of Equipment

1. Location of Equipment Newark, NJ

Customer Sign Off

2. Customer Sign Off

IF THERE ARE NO DEFICIENCIES NOTHING NEEDS TO BE DONE.

IF THERE ARE ANY HIGH, RED, DEFICIENCIES PLEASE FOLLOW THE BELOW INSTRUCTIONS

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS PAGE ONLY to either jaime@atlanticcrane.com or gina@atlanticcrane.com or fax THIS PAGE ONLY to our office at215-639-2316 and a certification and sticker will be issued. The above deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However, those items should be corrected to improve equipment reliability and safety.

The undersigned verifies the listed deficient	ncies denoted with an (DEF, HIGH, RE	ED) have been corrected.
Signature	Date	

		Signature	Date			
In	Inspection Information					
	3.	Inspection Number		23051305DV		
	4.	Inspection Date		05/13/2023		
	5.	Inspection Type		(Ann) Annual		
Li	Lifting Equipment					
	6.	Lifting Equipment Description		Spreader Bar		
	7.	Lifting Equipment Dimensions		8' - 14'		
	8.	Identification Marking		(SAT) Satisfactory		
	9.	Weight & Capacity marking		(SAT) Satisfactory		
	10.	Manufacturer Plate		(SAT) Satisfactory		
	11.	Structure		(SAT) Satisfactory		
	12.	Welds		(SAT) Satisfactory		
	13.	Lifting Eyes		(SAT) Satisfactory		
	14.	Locking Pins/Keeper Pins		(SAT) Satisfactory		
Ri	Rigging					

Atlantic Crane Inspection Services disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis

disclosed to the Customer by Atlantic Crane Inspection Services. Atlantic Crane Inspection Services shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

15.	Wire Rope Information				
	Size	Overall Capacity	Number of Legs		
	7/8"	7.6 tons	2 legs		
16.	Wire Rope Condition		(SAT) Satisfactory		
17.	Shackle Information				
	Size	Capacity	Number of Shackles		
	1 3/8"	13.5 tons	2 shackles		
18.	Shackle Condition		(SAT) Satisfactory		
Verification and Completion					
19. Inspector Name & Signature Dylan VanHorn					
20.	Additional Inspection Notes				
No visible deficiencies found at time of inspection					
	16. 17. 18. erific 19.	7/8" 16. Wire Rope Condition 17. Shackle Information Size 1 3/8" 18. Shackle Condition erification and Completion 19. Inspector Name & Signature 20. Additional Inspection Notes	Size Overall Capacity 7/8" 7.6 tons 16. Wire Rope Condition 17. Shackle Information Size Capacity 1 3/8" 13.5 tons 18. Shackle Condition erification and Completion 19. Inspector Name & Signature 20. Additional Inspection Notes		