



Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

Sautter Yard

on

11/16/2025

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

Signature

Date

Table of Contents



 High  Med  Low Section

Inspection - <i>Sautter Yard</i>	Boom Truck Crane: 303495 - S445	0	0	0	1.0
----------------------------------	---------------------------------	---	---	---	------------




Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview




Breakdown by Form

Form Type	 High	 Med	 Low	# Forms
Inspection	0	0	0	1
Overall:	0	0	0	1

Breakdown by Location

Location	 High	 Med	 Low	# Forms
Sautter Yard	0	0	0	1
Overall:	0	0	0	1

Breakdown by Asset

Asset Type	 High	 Med	 Low	# Assets
Boom Truck Crane	0	0	0	1
Overall:	0	0	0	1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Inspection

Sautter Crane Rental
2900 Black Lake Place
Philadelphia, PA 19154

FolderID: 111525S445
FormID: 26635353



Boom Truck Crane

Location: Sautter Yard
2900 Black Lake Place
Philadelphia, PA 19154

Serial #: 303495

TagID: S445

Manufacturer: National

Model Number: NTC45-2

Capacity: 45 Tons

Hook Type : Overhaul Ball & Hook

Length/Lift: 125'

Description: Swing Cab Boom Truck

*Additional Notes: 125 ft boom
1 part of line
Can't inspect extend and retract cables without
disassembling boom*

Priorities Found: ● 114 - Good

Miles and Hours

- | | |
|------------|-------------|
| ● 1. Miles | 1,934 Miles |
| ● 2. Hours | 28 Hours |

General

- | | |
|------------------------|--------------------|
| ● 3. Guards / Covers | (SAT) Satisfactory |
| ● 4. External Lights | (SAT) Satisfactory |
| ● 5. Warning Decals | (SAT) Satisfactory |
| ● 6. Housekeeping | (SAT) Satisfactory |
| ● 7. Hand Signal Chart | (SAT) Satisfactory |

Historical Data

- | | |
|---------------------------------|---------------------|
| ● 8. Monthly Inspection Records | (NA) Not Applicable |
| ● 9. Maintenance Records | (SAT) Satisfactory |

Driver's Cab

- | | |
|----------------------------|--------------------|
| ● 10. Glass | (SAT) Satisfactory |
| ● 11. Windshield Wipers | (SAT) Satisfactory |
| ● 12. Mirrors | (SAT) Satisfactory |
| ● 13. Fire Extinguishers | (SAT) Satisfactory |
| ● 14. Seat | (SAT) Satisfactory |
| ● 15. Seat Belt | (SAT) Satisfactory |
| ● 16. Power Take-Off | (SAT) Satisfactory |
| ● 17. Parking Brake | (SAT) Satisfactory |
| ● 18. Air Pressure | (SAT) Satisfactory |
| ● 19. Instruments / Gauges | (SAT) Satisfactory |
| ● 20. Switches / Functions | (SAT) Satisfactory |


Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 21. Horn	(SAT) Satisfactory
● 22. Steering	(SAT) Satisfactory
● 23. Engine Clutch	(NA) Not Applicable
● 24. Accelerator	(SAT) Satisfactory
● 25. Brake	(SAT) Satisfactory
● 26. Defroster	(SAT) Satisfactory
● 27. Operator's Manual	(SAT) Satisfactory
Truck Power Plant	
● 28. Performance	(SAT) Satisfactory
● 29. Exhaust System Guards & Insulators	(SAT) Satisfactory
● 30. Belts / Hoses	(SAT) Satisfactory
● 31. Moving Parts Guards & Covers	(SAT) Satisfactory
Chassis	
● 32. Transmission	(SAT) Satisfactory
● 33. Driveline	(SAT) Satisfactory
● 34. Tires / Wheels	(SAT) Satisfactory
● 35. Tire Air Pressure	(SAT) Satisfactory
● 36. Chassis Frame Members	(SAT) Satisfactory
● 37. Hydraulic Hoses / Tubing / Fittings	(SAT) Satisfactory
● 38. Hydraulic Fluid Level	(SAT) Satisfactory
● 39. Anti Skid Surface	(SAT) Satisfactory
● 40. Guards / Covers	(SAT) Satisfactory
● 41. Backup Alarm	(SAT) Satisfactory
Outriggers / Stabilizers	
● 42. Boxes	(SAT) Satisfactory
● 43. Beams	(SAT) Satisfactory
● 44. Cylinders	(SAT) Satisfactory
● 45. Floats / Pads	(SAT) Satisfactory
● 46. Hydraulic Hoses / Tubes / Fittings	(SAT) Satisfactory
● 47. Holding Valves	(SAT) Satisfactory
● 48. Caution / Warning Signs	(SAT) Satisfactory
Operators Station	
● 49. Grab Rails / Steps / Platforms	(SAT) Satisfactory
● 50. Door Restraint	(SAT) Satisfactory
● 51. Windows	(SAT) Satisfactory
● 52. Anti Skid Surface	(SAT) Satisfactory
● 53. Fire Extinguisher	(SAT) Satisfactory
● 54. Electrocution Warning Sign	(SAT) Satisfactory
● 55. Controls Identified	(SAT) Satisfactory
● 56. Accelerator / Throttle Control	(SAT) Satisfactory
● 57. Horn	(SAT) Satisfactory
● 58. Seat	(SAT) Satisfactory
Load Chart	
● 59. Per Configuration	(SAT) Satisfactory
● 60. Durable	(SAT) Satisfactory
● 61. Legible	(SAT) Satisfactory
● 62. Secured	(SAT) Satisfactory
● 63. Visible From Operators Station	(SAT) Satisfactory

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Safety Devices / Operational Aids		
● 64.	Boom Angle Indicator	(SAT) Satisfactory
● 65.	Boom Length Indicator	(SAT) Satisfactory
● 66.	Drum Rotation Indicator	(SAT) Satisfactory
● 67.	Overload Protection	(SAT) Satisfactory
● 68.	Crane Level Indicator	(SAT) Satisfactory
● 69.	Anti Two-Block Device	(SAT) Satisfactory
● 70.	Outrigger / Stabilizer Position Sensor	(SAT) Satisfactory
Upper Structure		
● 71.	Turntable	(SAT) Satisfactory
● 72.	Mounting	(SAT) Satisfactory
● 73.	Turret	(SAT) Satisfactory
● 74.	Hydraulic Pump(s)	(SAT) Satisfactory
● 75.	Hydraulic Hoses / Tubes / Fittings	(SAT) Satisfactory
● 76.	Hydraulic Pressure	(SAT) Satisfactory
● 77.	Electrical Wiring	(SAT) Satisfactory
● 78.	Hoist Brake	(SAT) Satisfactory
● 79.	Hoist - Motor / Valves / Lines	(SAT) Satisfactory
● 80.	Hoist Spooling	(SAT) Satisfactory
■	1 part of line	
● 81.	Hoist - Minimum 2 Rope Wraps	(SAT) Satisfactory
● 82.	Swing Gear Box	(SAT) Satisfactory
● 83.	Electrocution Warning Sign	(SAT) Satisfactory
Main Boom		
● 84.	Lift Cylinder(s)	(SAT) Satisfactory
● 85.	Telescoping Cylinder(s)	(SAT) Satisfactory
● 86.	Hydraulic Hoses / Tubes / Fittings	(SAT) Satisfactory
● 87.	Holding Device	(SAT) Satisfactory
● 88.	Boom Sections Alignment	(SAT) Satisfactory
● 89.	Wear Pads	(SAT) Satisfactory
● 90.	Sheave(s)	(SAT) Satisfactory
● 91.	Hoist Line Dead End	(SAT) Satisfactory
● 92.	Wire Rope Retainer	(SAT) Satisfactory
● 93.	Boom Hinge Pin	(SAT) Satisfactory
● 94.	Boom Head Section	(SAT) Satisfactory
● 95.	Structure	(SAT) Satisfactory
Jib / Extension		
● 96.	Positive Stops	(SAT) Satisfactory
● 97.	Sheave(s)	(SAT) Satisfactory
● 98.	Wire Rope Retainer(s)	(SAT) Satisfactory
● 99.	Structure	(SAT) Satisfactory
● 100.	Pins / Locking Devices	(SAT) Satisfactory
Overhaul Ball & Hook		
● 101.	Capacity Marking	(SAT) Satisfactory
● 102.	Weight Marking	(SAT) Satisfactory
● 103.	Safety Latches	(SAT) Satisfactory
● 104.	0° Hook Bend or Twist	(SAT) Satisfactory
● 105.	5% Hook Opening or 1/4" Max	(SAT) Satisfactory

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 106. 10% Hook Wear Max	(SAT) Satisfactory
● 107. Swivel / Bearing	(SAT) Satisfactory
● 108. Wedge Socket / End Fitting	(SAT) Satisfactory
Wire Rope	
● 109. Rope Damage	(SAT) Satisfactory
● 110. Measured Wear 🗨 5/8 inch Actual - .649 inch	(SAT) Satisfactory
● 111. Broken Wires	(SAT) Satisfactory
● 112. Lubrication	(SAT) Satisfactory
● 113. End Connectors	(SAT) Satisfactory
Verification and Completion	
● 114. Inspector Name and Signature 	Anthony Capozzi
● 115. Date of Inspection	11/15/2025
● 116. Customer Name and Signature	
● 117. Certificate Issued	(Y) Yes

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.