



Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

3400 Spruce Street Phila

on

7/18/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

Signature

Date

Table of Contents

 High  Med  Low Section

Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400) - 3400 Spruce Street Phila	Telescoping Boom Crane: 072 270 - S217	0	0	0	1.0
--	---	---	---	---	------------

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview

Breakdown by Form

Form Type	 High	 Med	 Low	# Forms
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)	0	0	0	1
Overall:	0	0	0	1

Breakdown by Location

Location	 High	 Med	 Low	# Forms
3400 Spruce Street Phila	0	0	0	1
Overall:	0	0	0	1

Breakdown by Asset

Asset Type	 High	 Med	 Low	# Assets
Telescoping Boom Crane	0	0	0	1
Overall:	0	0	0	1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)

Sautter Crane Rental
2900 Black Lake Place
Philadelphia, PA 19154

FolderID: 071826S217
FormID: 30009903



Telescoping Boom Crane

Location: 3400 Spruce Street Phila

Serial Number: 072 270

Unit Number: S217

Status: In Service

Additional Notes: 153 ft main boom with Y Guy
207 ft luffing jib
1 part of line
220,000 lbs counterweight

Manufacturer: Liebherr

Model: LTM1400-7.1

Capacity: 500 Tons

Length/Lift: 152' Main With 207' Luffing Jib

Type of Crane: All Terrain Crane

Number of Hoists: Main Only

Boom Configuration: Main Boom & Luffing Jib Assembled

Load Test: No

Priorities Found: ● 119 - Good

General

1. Location of Equipment **3400 Spruce Street**

2. Customer Sign Off

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

Signature

3. Hours & Mileage

Hours

Mileage

7,596

55,916 km

Inspection Information

4. Inspection Number **071826S217**

5. Inspection Date **07/18/2026**

6. Inspection Type **(Ann) Annual**

Information & Records

7. Documentation of Annual/Comprehensive Inspection **(SAT) Satisfactory**

8. Daily/Monthly Inspection Records **(SAT) Satisfactory**

9. Maintenance Records **(SAT) Satisfactory**

10. Hand Signal Chart **(SAT) Satisfactory**

11. Safety and Warning Decals **(SAT) Satisfactory**

12. Operators Manual **(SAT) Satisfactory**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Safety Devices & Operational Aids		
● 13.	Backup Alarm	(SAT) Satisfactory
● 14.	Audible Warning Device	(SAT) Satisfactory
● 15.	Boom Angle Indicator	(SAT) Satisfactory
● 16.	Boom Length Indicator	(SAT) Satisfactory
● 17.	Drum Rotation Indicator(s)	(SAT) Satisfactory
● 18.	Anti Two-Block Device/System	(SAT) Satisfactory
● 19.	Load Moment Indicator (LMI)	(SAT) Satisfactory
● 20.	Load Weight Indicator	(SAT) Satisfactory
● 21.	Radius Indicator	(SAT) Satisfactory
● 22.	Level Indicator(s)	(SAT) Satisfactory
● 23.	Fire Extinguisher	(SAT) Satisfactory
Load Chart		
● 24.	Visible/Accessible	(SAT) Satisfactory
● 25.	Per Configuration	(SAT) Satisfactory
● 26.	Durable/Legible/Secured	(SAT) Satisfactory
Carrier		
● 27.	Steering	(SAT) Satisfactory
● 28.	Parking Brake	(SAT) Satisfactory
● 29.	Exterior Lights (Headlights, Turn Signals, Brake Lights, Reverse Lights)	(SAT) Satisfactory
● 30.	Windshield & Wipers	(SAT) Satisfactory
● 31.	Windows & Mirrors	(SAT) Satisfactory
● 32.	Wheels & Tires	(SAT) Satisfactory
● 33.	Engine	(SAT) Satisfactory
● 34.	Exhaust System	(SAT) Satisfactory
● 35.	Axle Lockout	(SAT) Satisfactory
● 36.	Drive Line	(SAT) Satisfactory
● 37.	Main Frame Members	(SAT) Satisfactory
● 38.	Hoses/Fittings/Valves	(SAT) Satisfactory
● 39.	Hydraulic Tank & Fluid Level	(SAT) Satisfactory
● 40.	Slip Resistant Walking Surfaces	(SAT) Satisfactory
● 41.	Steps/Ladders/Handrails	(SAT) Satisfactory
Outriggers/Stabilizers		
● 42.	Structure & Mounting	(SAT) Satisfactory
● 43.	Boxes & Beams	(SAT) Satisfactory
● 44.	Cylinders	(SAT) Satisfactory
● 45.	Pads/Floats	(SAT) Satisfactory
● 46.	Hoses/Fittings/Valves	(SAT) Satisfactory
Operators Station		
● 47.	Windows & Wipers	(SAT) Satisfactory
● 48.	Cab Door Restraint	(SAT) Satisfactory
● 49.	Cab Access	(SAT) Satisfactory
● 50.	Steps/Ladders/Handrails	(SAT) Satisfactory
● 51.	Anti-Skid Stepping Surfaces	(SAT) Satisfactory
● 52.	Fire Extinguisher	(SAT) Satisfactory
● 53.	Operator Horn	(SAT) Satisfactory
● 54.	Controls Identified	(SAT) Satisfactory
● 55.	Control Functions	(SAT) Satisfactory

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

●	56. Power Plant Controls	(SAT) Satisfactory
●	57. Operator Cutoff Switch (Deadman)	(SAT) Satisfactory
●	58. Brake & Clutch	(NA) Not Applicable
●	59. Travel Controls	(NA) Not Applicable
●	60. Accelerator/Throttle Control	(SAT) Satisfactory
●	61. Hoses/Fittings/Valves	(SAT) Satisfactory
●	62. Housekeeping	(SAT) Satisfactory
Rotating Upper Structure		
●	63. Structure	(SAT) Satisfactory
●	64. Engine	(SAT) Satisfactory
●	65. Exhaust System/Guards/Insulators	(SAT) Satisfactory
●	66. Hoses/Fittings/Valves	(SAT) Satisfactory
●	67. Hydraulic & Pneumatic Pumps	(SAT) Satisfactory
●	68. Hydraulic Pressure	(SAT) Satisfactory
●	69. Electrical Wiring	(SAT) Satisfactory
●	70. Ring & Pinion Gear	(SAT) Satisfactory
●	71. Swing System/Assembly	(SAT) Satisfactory
●	72. Counterweight Frame	(SAT) Satisfactory
●	73. Counterweight Mounting	(SAT) Satisfactory
Hoist System		
●	74. Brakes & Clutch System	(SAT) Satisfactory
●	75. Wire Rope Reeving	(SAT) Satisfactory
●	1 part of line	
●	76. 2 Rope Wrap Minimum	(SAT) Satisfactory
●	77. Hoist Motor	(SAT) Satisfactory
●	78. Hoses/Fittings/Valves	(SAT) Satisfactory
●	79. Drums/Lagging/Flanges	(SAT) Satisfactory
●	80. Anchor System	(SAT) Satisfactory
●	81. Hoist Spooling	(SAT) Satisfactory
Main Boom		
●	82. Lift Cylinder(s)	(SAT) Satisfactory
●	83. Telescoping Boom Cylinder(s)	(SAT) Satisfactory
●	84. Hoses/Fittings/Valves	(SAT) Satisfactory
●	85. Holding Device	(SAT) Satisfactory
●	86. Boom Sections Alignment	(SAT) Satisfactory
●	87. Wear Pads	(SAT) Satisfactory
●	88. Sheaves	(SAT) Satisfactory
●	89. Wire Rope Retainers	(SAT) Satisfactory
●	90. Boom Hinge Pin	(SAT) Satisfactory
●	91. Boom Head Section	(SAT) Satisfactory
●	92. Auxiliary Boom Head	(NA) Not Applicable
●	93. Structure	(SAT) Satisfactory
Luffing Boom Attachment		
●	94. Luffing Jib Section Identification	(SAT) Satisfactory
●	95. Luffing Jib Section Sequence	(SAT) Satisfactory
●	96. Luffing Jib Tip Section	(SAT) Satisfactory
●	97. Luffing Jib Point Sheaves	(SAT) Satisfactory
●	98. Luffing Hoist Line Dead End	(SAT) Satisfactory

P94

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 99.	Luffing Jib Warning Decals	(SAT) Satisfactory
● 100.	Luffing Jib Foot Keepers & Pins	(SAT) Satisfactory
● 101.	Lattice Members	(SAT) Satisfactory
● 102.	Cord Members	(SAT) Satisfactory
● 103.	End Connections & Pins	(SAT) Satisfactory
● 104.	Luffing Jib Angle Indicator	(SAT) Satisfactory
● 105.	Luffing Jib Stops	(SAT) Satisfactory
● 106.	Luffing Jib Hoist Reeving	(SAT) Satisfactory
● 107.	Guard Rails & Walking Surfaces	(SAT) Satisfactory
Main Drum Wire Rope		
● 108.	Wire Rope Information	
	Diameter	Construction/Type
	25.58 mm	Non Rot RLL
		Number of Parts
		1
● 109.	Rope Damage	(SAT) Satisfactory
● 110.	Lubrication	(SAT) Satisfactory
● 111.	End Connectors	(SAT) Satisfactory
Main Hoist Load Block/Headache Ball/Hook		
● 112.	Capacity and Weight	
	Capacity	Weight
	12.5 tonnes	133 kg
● 113.	Capacity Marking	(SAT) Satisfactory
● 114.	Weight Marking	(SAT) Satisfactory
● 115.	Sheave(s)	(NA) Not Applicable
● 116.	Safety Latch(es)	(SAT) Satisfactory
● 117.	0° Hook Bend/Twist	(SAT) Satisfactory
● 118.	5% Hook Opening or 1/4" Max	(SAT) Satisfactory
● 119.	10% Hook Wear Max	(SAT) Satisfactory
● 120.	Bearing	(SAT) Satisfactory
● 121.	Wedge Socket/End Fitting	(SAT) Satisfactory
● 122.	Reeving	(SAT) Satisfactory
	1 part of line	
Verification and Completion		
● 123.	Inspector Name & Signature	Anthony Capozzi
		
	124. Additional Inspection Notes	
● 125.	Sticker Given	(Y) Yes, Given on Site

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



P94.1



P94.2



P94.3