Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

Our Lady Of Lourdes Hospital Camden, Nj

on

10/17/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

_____ _____

Signature Date

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Table of Contents

		High	Med	Low	Section
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400) - *Our Lady Of Lourdes Hospital Camden, Nj*	Telescoping Boom Crane*: 093 192 - S428*	0	0	0	**1.0**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview

Breakdown by Form

Form Type		High	Med	Low	# Forms
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)		0	0	0	1
	Overall:	**0**	**0**	**0**	**1**

Breakdown by Location

Location		High	Med	Low	# Forms
Our Lady Of Lourdes Hospital Camden, Nj		0	0	0	1
	Overall:	**0**	**0**	**0**	**1**

Breakdown by Asset

Asset Type		High	Med	Low	# Assets
Telescoping Boom Crane		0	0	0	1
	Overall:	**0**	**0**	**0**	**1**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)

FolderID: 101726S428
FormID: 31277347

Sautter Crane Rental
2900 Black Lake Place
Philadelphia, PA 19154



Telescoping Boom Crane

Completed by: Steve Edling on 10/17/2026

Location:	Our Lady Of Lourdes Hospital Camden, Nj
Serial Number:	093 192
Unit Number:	S428

Manufacturer:	Liebherr
Model:	LTM 1300-6.2
Capacity:	360 Tons
Length/Lift:	256'
Type of Crane:	All Terrain Crane
Number of Hoists:	Main Only
Boom Configuration:	Main Boom with Erected jib
Load Test:	No

Priorities Found: **104 - Good**

General

1.	Location of Equipment	**our lad of lourdes hospital**	
2.	Customer Sign Off		
3.	Hours & Mileage		
	Hours	Mileage	
	14,720.5	**9529.0**	

Inspection Information

4.	Inspection Number	**101726S428**	
5.	Inspection Date	**10/17/2026**	
6.	Inspection Type	**(Ann) Annual**	

Information & Records

7.	Documentation of Annual/Comprehensive Inspection	**(SAT) Satisfactory**	
8.	Daily/Monthly Inspection Records	**(SAT) Satisfactory**	
9.	Maintenance Records	**(SAT) Satisfactory**	
10.	Hand Signal Chart	**(SAT) Satisfactory**	
11.	Safety and Warning Decals	**(SAT) Satisfactory**	P11
12.	Operators Manual	**(SAT) Satisfactory**	
13.	Equipment Modification(s) or Additions	**(SAT) Satisfactory**	

Safety Devices & Operational Aids

14.	Backup Alarm	**(SAT) Satisfactory**	
15.	Audible Warning Device	**(SAT) Satisfactory**	
16.	Boom Angle Indicator	**(SAT) Satisfactory**	P16
17.	Boom Length Indicator	**(SAT) Satisfactory**	
18.	Drum Rotation Indicator(s)	**(SAT) Satisfactory**	
19.	Anti Two-Block Device/System	**(SAT) Satisfactory**	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

20.	Load Moment Indicator (LMI)	**(SAT) Satisfactory**	
21.	Load Weight Indicator	**(SAT) Satisfactory**	
22.	Radius Indicator	**(SAT) Satisfactory**	
23.	Level Indicator(s)	**(SAT) Satisfactory**	
24.	Fire Extinguisher	**(SAT) Satisfactory**	
Load Chart			
25.	Visible/Accessible	**(SAT) Satisfactory**	
26.	Per Configuration	**(SAT) Satisfactory**	
27.	Durable/Legible/Secured	**(SAT) Satisfactory**	
Carrier			
28.	Steering	**(SAT) Satisfactory**	
29.	Parking Brake	**(SAT) Satisfactory**	
30.	Exterior Lights (Headlights, Turn Signals, Brake Lights, Reverse Lights)	**(SAT) Satisfactory**	
31.	Windshield & Wipers	**(SAT) Satisfactory**	
32.	Windows & Mirrors	**(SAT) Satisfactory**	
33.	Wheels & Tires	**(SAT) Satisfactory**	
34.	Engine	**(SAT) Satisfactory**	
35.	Exhaust System	**(SAT) Satisfactory**	
36.	Axle Lockout	**(SAT) Satisfactory**	
37.	Drive Line	**(SAT) Satisfactory**	
38.	Main Frame Members	**(SAT) Satisfactory**	
39.	Hoses/Fittings//Valves	**(SAT) Satisfactory**	
40.	Hydraulic Tank & Fluid Level	**(SAT) Satisfactory**	
41.	Slip Resistant Walking Surfaces	**(SAT) Satisfactory**	
42.	Steps/Ladders/Handrails	**(SAT) Satisfactory**	P42
Outriggers/Stabilizers			
43.	Structure & Mounting	**(SAT) Satisfactory**	
44.	Boxes & Beams	**(SAT) Satisfactory**	P44
45.	Cylinders	**(SAT) Satisfactory**	
46.	Pads/Floats	**(SAT) Satisfactory**	
47.	Hoses/Fittings/Valves	**(SAT) Satisfactory**	
Operators Station			
48.	Windows & Wipers	**(SAT) Satisfactory**	
49.	Cab Door Restraint	**(SAT) Satisfactory**	
50.	Cab Access	**(SAT) Satisfactory**	
51.	Steps/Ladders/Handrails	**(SAT) Satisfactory**	
52.	Anti-Skid Stepping Surfaces	**(SAT) Satisfactory**	
53.	Fire Extinguisher	**(SAT) Satisfactory**	
54.	Operator Horn	**(SAT) Satisfactory**	
55.	Controls Identified	**(SAT) Satisfactory**	
56.	Control Functions	**(SAT) Satisfactory**	
57.	Power Plant Controls	**(SAT) Satisfactory**	
58.	Operator Cutoff Switch (Deadman)	**(SAT) Satisfactory**	
59.	Brake & Clutch	**(NA) Not Applicable**	
60.	Travel Controls	**(NA) Not Applicable**	
61.	Accelerator/Throttle Control	**(SAT) Satisfactory**	
62.	Hoses/Fittings/Valves	**(SAT) Satisfactory**	
63.	Housekeeping	**(SAT) Satisfactory**	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Rotating Upper Structure			
64. Structure			**(SAT) Satisfactory**
65. Engine			**(SAT) Satisfactory**
66. Exhaust System/Guards/Insulators			**(SAT) Satisfactory**
67. Hoses/Fittings/Valves			**(SAT) Satisfactory**
68. Hydraulic & Pneumatic Pumps			**(SAT) Satisfactory**
69. Hydraulic Pressure			**(SAT) Satisfactory**
70. Electrical Wiring			**(SAT) Satisfactory**
71. Ring & Pinion Gear			**(SAT) Satisfactory** P71
72. Swing System/Assembly			**(SAT) Satisfactory**
73. Counterweight Frame			**(SAT) Satisfactory** P73
74. Counterweight Mounting			**(SAT) Satisfactory**
Hoist System			
75. Brakes & Clutch System			**(NA) Not Applicable**
76. Wire Rope Reeving			**(SAT) Satisfactory**
77. 2 Rope Wrap Minimum			**(SAT) Satisfactory**
78. Hoist Motor			**(SAT) Satisfactory**
79. Hoses/Fittings/Valves			**(SAT) Satisfactory**
80. Drums/Lagging/Flanges			**(SAT) Satisfactory**
81. Anchor System			**(SAT) Satisfactory**
82. Hoist Spooling			**(SAT) Satisfactory** P82
Main Boom			
83. Lift Cylinder(s)			**(SAT) Satisfactory**
84. Telescoping Boom Cylinder(s)			**(SAT) Satisfactory**
85. Hoses/Fittings/Valves			**(SAT) Satisfactory**
86. Holding Device			**(SAT) Satisfactory**
87. Boom Sections Alignment			**(SAT) Satisfactory** P87
88. Wear Pads			**(SAT) Satisfactory**
89. Sheaves			**(SAT) Satisfactory**
90. Wire Rope Retainers			**(SAT) Satisfactory**
91. Boom Hinge Pin			**(SAT) Satisfactory** P91
92. Boom Head Section			**(SAT) Satisfactory**
93. Auxiliary Boom Head			**(NA) Not Applicable**
94. Structure			**(SAT) Satisfactory**
Jib/Fly Extension			
95. Structure			**(SAT) Satisfactory**
96. Locking Devices			**(SAT) Satisfactory**
97. Sheaves			**(SAT) Satisfactory** P97
98. Wire Rope Retainers			**(SAT) Satisfactory**
99. Alignment			**(SAT) Satisfactory**
100. End Connectors & Pins			**(SAT) Satisfactory**
Main Drum Wire Rope			
101. Wire Rope Information			
Diameter	Construction/Type	Number of Parts	
23 mm	**non rotation**	**1**	
102. Rope Damage			**(SAT) Satisfactory**
103. Lubrication			**(SAT) Satisfactory**
104. End Connectors			**(SAT) Satisfactory**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Main Hoist Load Block/Headache Ball/Hook

105. Capacity and Weight

Capacity	Weight
12.5 tons	**500 kg**

106.	Capacity Marking	**(SAT) Satisfactory**	P106
107.	Weight Marking	**(SAT) Satisfactory**	
108.	Sheave(s)	**(NA) Not Applicable**	
109.	Safety Latch(es)	**(SAT) Satisfactory**	P109
110.	0° Hook Bend/Twist	**(SAT) Satisfactory**	
111.	5% Hook Opening or 1/4" Max	**(SAT) Satisfactory**	
112.	10% Hook Wear Max	**(SAT) Satisfactory**	
113.	Bearing	**(SAT) Satisfactory**	
114.	Wedge Socket/End Fitting	**(SAT) Satisfactory**	
115.	Reeving	**(SAT) Satisfactory**	

Verification and Completion

116. Inspector Name & Signature — **Steven Edling**



117. Additional Inspection Notes

118.	Sticker Given	**(Y) Yes, Given on Site**	P118



P11.1



P16.2



P42.3



P44.4



P71.5



P73.6



P82.7



P87.8

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



P91.9




P97.10



P106.11



P109.12



P118.13

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.