



Prepared for:

Sautter Crane rental

2900 Black Lake Place Philadelphia, PA 19154

Sautter Yard

on

11/8/2025

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

William Sautter

Signature

11/10/25

Date

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Table of Contents

 High  Med  Low Section

Inspection - Sautter Yard

Boom Truck Crane:
1T9I4792LDW140746 - S187

2 3 0 **1.0**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview

Breakdown by Form

| Form Type | High | Med | Low | # Forms |
|------------|------|-----|-----|---------|
| Inspection | 2 | 3 | 0 | 1 |
| Overall: | 2 | 3 | 0 | 1 |

Breakdown by Location

| Location | High | Med | Low | # Forms |
|--------------|------|-----|-----|---------|
| Sautter Yard | 2 | 3 | 0 | 1 |
| Overall: | 2 | 3 | 0 | 1 |

Breakdown by Asset

| Asset Type | High | Med | Low | # Assets |
|------------------|------|-----|-----|----------|
| Boom Truck Crane | 2 | 3 | 0 | 1 |
| Overall: | 2 | 3 | 0 | 1 |

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Inspection

Sautter Crane rental
2900 Black Lake Place
Philadelphia, PA 19154

FolderID: 110825S187
FormID: 26538487



Boom Truck Crane

Location: Sautter Yard
2900 Black Lake Place
Philadelphia, PA 19154
Serial #: 1T9I4792LDW140746
TagID: S187
Status: In Service

Manufacturer: Terex
Model Number: BT4792
Capacity: 23 1/2 Ton
Hook Type : Load Block & Hook
Length/Lift: 92'

*Additional Notes: 92 ft boom
2 parts of line
Can't inspect extend and retract cables without
disassembling boom*

Priorities Found: ● 2 - High ● 3 - Medium ● 104 - Good

Miles and Hours

| | |
|---|----------------------|
| ● 1. Miles | 113,625 Miles |
| ● 2. Hours | 7620 Hours |

General

| | |
|---|---------------------------|
| ● 3. Guards / Covers | (SAT) Satisfactory |
| ● 4. External Lights | (SAT) Satisfactory |
| ● 5. Warning Decals | (SAT) Satisfactory |
| ● 6. Housekeeping | (SAT) Satisfactory |
| ● 7. Hand Signal Chart | (SAT) Satisfactory |

Historical Data

| | |
|--|---------------------------|
| ● 8. Monthly Inspection Records | (SAT) Satisfactory |
| ● 9. Maintenance Records | (SAT) Satisfactory |

Driver's Cab

| | |
|---|---------------------------|
| ● 10. Glass | (SAT) Satisfactory |
| ● 11. Windshield Wipers | (SAT) Satisfactory |
| ● 12. Mirrors | (SAT) Satisfactory |
| ● 13. Fire Extinguishers | (SAT) Satisfactory |
| ● 14. Seat | (SAT) Satisfactory |
| ● 15. Seat Belt | (SAT) Satisfactory |
| ● 16. Power Take-Off | (SAT) Satisfactory |
| ● 17. Parking Brake | (SAT) Satisfactory |
| ● 18. Air Pressure | (SAT) Satisfactory |
| ● 19. Instruments / Gauges | (SAT) Satisfactory |
| ● 20. Switches / Functions | (SAT) Satisfactory |

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

| | |
|---|--------------------------|
| ● 21. Horn | (SAT) Satisfactory |
| ● 22. Steering | (SAT) Satisfactory |
| ● 23. Engine Clutch | (NA) Not Applicable |
| ● 24. Accelerator | (SAT) Satisfactory |
| ● 25. Brake | (SAT) Satisfactory |
| ● 26. Defroster | (SAT) Satisfactory |
| ● 27. Operator's Manual | (SAT) Satisfactory |
| Truck Power Plant | |
| ● 28. Performance | (REC) Recommendation P28 |
| <i>Check engine light on</i> | |
| ● 29. Exhaust System Guards & Insulators | (SAT) Satisfactory |
| ● 30. Belts / Hoses | (SAT) Satisfactory |
| ● 31. Moving Parts Guards & Covers | (SAT) Satisfactory |
| Chassis | |
| ● 32. Transmission | (SAT) Satisfactory |
| ● 33. Driveline | (SAT) Satisfactory |
| ● 34. Tires / Wheels | (SAT) Satisfactory |
| ● 35. Tire Air Pressure | (SAT) Satisfactory |
| ● 36. Chassis Frame Members | (SAT) Satisfactory |
| ● 37. Hydraulic Hoses / Tubing / Fittings | (SAT) Satisfactory |
| ● 38. Hydraulic Fluid Level | (SAT) Satisfactory |
| ● 39. Anti Skid Surface | (SAT) Satisfactory |
| ● 40. Guards / Covers | (SAT) Satisfactory |
| ● 41. Backup Alarm | (SAT) Satisfactory |
| Outriggers / Stabilizers | |
| ● 42. Boxes | (SAT) Satisfactory |
| ● 43. Beams | (REC) Recommendation P43 |
| <i>Rear outrigger locking pins rusted</i> | |
| ● 44. Cylinders | (SAT) Satisfactory |
| ● 45. Floats / Pads | (SAT) Satisfactory |
| ● 46. Hydraulic Hoses / Tubes / Fittings | (SAT) Satisfactory |
| ● 47. Holding Valves | (REC) Recommendation P47 |
| <i>Oil seeping from left rear holding valve</i> | |
| ● 48. Caution / Warning Signs | (SAT) Satisfactory |
| Operators Station | |
| ● 49. Grab Rails / Steps / Platforms | (SAT) Satisfactory |
| ● 50. Door Restraint | (NA) Not Applicable |
| ● 51. Windows | (NA) Not Applicable |
| ● 52. Anti Skid Surface | (SAT) Satisfactory |
| ● 53. Fire Extinguisher | (SAT) Satisfactory |
| ● 54. Electrocution Warning Sign | (SAT) Satisfactory |
| ● 55. Controls Identified | (SAT) Satisfactory |
| ● 56. Accelerator / Throttle Control | (SAT) Satisfactory |
| ● 57. Horn | (DEF) Deficiency |
| <i>Horn at operators station not working</i> | |
| ● 58. Seat | (NA) Not Applicable |
| Load Chart | |
| ● 59. Per Configuration | (SAT) Satisfactory |

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.


| | |
|--|--------------------|
| 60. Durable | (SAT) Satisfactory |
| 61. Legible | (SAT) Satisfactory |
| 62. Secured | (SAT) Satisfactory |
| 63. Visible From Operators Station | (SAT) Satisfactory |
| Safety Devices / Operational Aids | |
| 64. Boom Angle Indicator | (SAT) Satisfactory |
| 65. Boom Length Indicator | (SAT) Satisfactory |
| 66. Drum Rotation Indicator | (SAT) Satisfactory |
| 67. Overload Protection | (SAT) Satisfactory |
| 68. Crane Level Indicator | (SAT) Satisfactory |
| 69. Anti Two-Block Device | (SAT) Satisfactory |
| 70. Outrigger / Stabilizer Position Sensor | (SAT) Satisfactory |
| Upper Structure | |
| 71. Turntable | (SAT) Satisfactory |
| 72. Mounting | (SAT) Satisfactory |
| 73. Turret | (SAT) Satisfactory |
| 74. Hydraulic Pump(s) | (SAT) Satisfactory |
| 75. Hydraulic Hoses / Tubes / Fittings | (SAT) Satisfactory |
| 76. Hydraulic Pressure | (SAT) Satisfactory |
| 77. Electrical Wiring | (SAT) Satisfactory |
| 78. Hoist Brake | (SAT) Satisfactory |
| 79. Hoist - Motor / Valves / Lines | (SAT) Satisfactory |
| 80. Hoist Spooling | (SAT) Satisfactory |
| 81. Hoist - Minimum 2 Rope Wraps | (SAT) Satisfactory |
| 82. Swing Gear Box | (SAT) Satisfactory |
| 83. Electrocution Warning Sign | (SAT) Satisfactory |
| Main Boom | |
| 84. Lift Cylinder(s) | (SAT) Satisfactory |
| 85. Telescoping Cylinder(s) | (SAT) Satisfactory |
| 86. Hydraulic Hoses / Tubes / Fittings | (SAT) Satisfactory |
| 87. Holding Device | (SAT) Satisfactory |
| 88. Boom Sections Alignment | (SAT) Satisfactory |
| 89. Wear Pads | (SAT) Satisfactory |
| 90. Sheave(s) | (SAT) Satisfactory |
| 91. Hoist Line Dead End | (SAT) Satisfactory |
| 92. Wire Rope Retainer | (SAT) Satisfactory |
| 93. Boom Hinge Pin | (SAT) Satisfactory |
| 94. Boom Head Section | (SAT) Satisfactory |
| 95. Structure | (SAT) Satisfactory |
| Load Block & Hook | |
| 96. Capacity Marking | (SAT) Satisfactory |
| 97. Weight Marking | (SAT) Satisfactory |
| 98. Sheave(s) | (SAT) Satisfactory |
| 99. Safety Latche(s) | (SAT) Satisfactory |
| 100. 0° Hook Bend or Twist | (SAT) Satisfactory |
| 101. 5% Hook Opening or 1/4" Max | (SAT) Satisfactory |
| 102. 10% Hook Wear Max | (SAT) Satisfactory |
| 103. Bearing | (SAT) Satisfactory |

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

| | |
|---|--------------------|
| ● 104. Wedge Socket / End Fitting | (SAT) Satisfactory |
| ● 105. Reeving | (SAT) Satisfactory |
| <i>2 parts of line</i> | |
| Wire Rope | |
| ● 106. Rope Damage | (SAT) Satisfactory |
| ● 107. Measured Wear | (SAT) Satisfactory |
| <i>9/16 inch Actual - .587 inch</i> | |
| ● 108. Broken Wires | (SAT) Satisfactory |
| ● 109. Lubrication | (SAT) Satisfactory |
| ● 110. End Connectors | (SAT) Satisfactory |
| Verification and Completion | |
| ● 111. Inspector Name and Signature | Anthony Capozzi |
|  | |
| ● 112. Date of Inspection | 11/08/2025 |
| 113. Customer Name and Signature | |
| ● 114. Certificate Issued | (N) No |



P28.1



P43.2



P47.3

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.