



Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

Sautter Yard

on

6/1/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

Signature

Date

Table of Contents

● High ● Med ● Low Section

Lifting Bar - Sautter Yard

Below the Hook Devices: SER NO -
16-41175-3 - SB15




0 0 0

1.0




Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview




Breakdown by Form

| Form Type |  High |  Med |  Low | # Forms |
|-----------------|--|---|---|----------|
| Lifting Bar | 0 | 0 | 0 | 1 |
| Overall: | 0 | 0 | 0 | 1 |

Breakdown by Location

| Location |  High |  Med |  Low | # Forms |
|-----------------|--|---|---|----------|
| Sautter Yard | 0 | 0 | 0 | 1 |
| Overall: | 0 | 0 | 0 | 1 |

Breakdown by Asset

| Asset Type |  High |  Med |  Low | # Assets |
|------------------------|--|---|---|----------|
| Below the Hook Devices | 0 | 0 | 0 | 1 |
| Overall: | 0 | 0 | 0 | 1 |

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Lifting Bar
Sautter Crane Rental
 2900 Black Lake Place
 Philadelphia, PA 19154

FolderID: 060126SB15
 FormID: 29347396



Below the Hook Devices

Location: Sautter Yard
 2900 Black Lake Place
 Philadelphia, PA 19154

Identifier: SER NO - 16-41175-3

TagID: SB15

Description: Spreader Beam

Type: Spreader Beam

Capacity: 30 tons

Manufacturer: Caldwell

Model Number: 32-30-9/15

Length/Lift: 9' to 15'

Priorities Found: ● 12 - Good

| General | |
|---|--------------------|
| ● 1. Bar has no obvious bend, twist or deformation. | (SAT) Satisfactory |
| Manufacturer | |
| ● 2. Make | Caldwell |
| Manufacturer Model Number | |
| ● 3. Model | 32-30-9/15 |
| Capacity | |
| ● 4. Rated Capacity of device | 30 Tons |
| Tare Weight | |
| ● 5. Weight of device | 750 lbs |
| Markings | |
| ● 6. The weight and capacity of the device are clearly and permanently displayed. | (Y) Yes |
| Corrosion | |
| ● 7. No visible corrosion that may effect the structural integrity of the device. | (SAT) Satisfactory |
| Rigging Connection Points | |
| ● 8. All possible points of connection do not have any visible cracks, deformation or excessive wear. | (SAT) Satisfactory |
| Adjustability | |
| ● 9. If the device is adjustable, Are all pins/fixtures secure and in proper working condition? | (Y) Yes |
| Name Of Inspector | |
| ● 10. Inspector | Anthony Capozzi |

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Date Of Inspection

● 11. Inspection performed on **06/01/2026**

Certificate

● 12. Was a certificate issued? **(Y) Yes**