



Below the Hook Lifting Devices
 Sautter Crane Rental

FolderID: 12121
 FormID: 16729916



Below the Hook Devices

Completed by: Dylan VanHorn on 05/06/2023

Location: 1 Industrial Hwy Eddystone Pa
 19022

Serial Number: J6800

Unit #: HMB08

Type: Manbasket (1926.1431)

Manufacturer: Lakeshore Industrial

Model Number: M44

Capacity: 1000 lbs

Net Weight: 550 lbs

Rigging Attached : No

Work Performed: Inspection

Priorities Found: ● 1 - Medium ● 13 - Good

Location of Equipment

1. Location of Equipment **Philadelphia, PA**

Customer Sign Off

2. Customer Sign Off

IF THERE ARE NO DEFICIENCIES NOTHING NEEDS TO BE DONE.

IF THERE ARE ANY HIGH, RED, DEFICIENCIES PLEASE FOLLOW THE BELOW INSTRUCTIONS

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS PAGE ONLY to either jaime@atlanticcrane.com or gina@atlanticcrane.com or fax THIS PAGE ONLY to our office at 215-639-2316 and a certification and sticker will be issued. The above deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However, those items should be corrected to improve equipment reliability and safety.

The undersigned verifies the listed deficiencies denoted with an (DEF, HIGH, RED) have been corrected.

 Signature

 Date

Inspection Information

3. Inspection Number **23050602DV**

4. Inspection Date **05/06/2023**

● 5. Inspection Type **(Ann) Annual**

Manbasket

6. Max Persons **3**

● 7. Rating Plate **(SAT) Satisfactory**

● 8. Grab Rail **(SAT) Satisfactory**

● 9. Access Gate **(SAT) Satisfactory**

● 10. Access Gate Lock **(SAT) Satisfactory**

● 11. Headroom **(SAT) Satisfactory**


● 12. Edge & Surfaces **(SAT) Satisfactory**

● 13. Welds **(SAT) Satisfactory**

● 14. Lifting Eyes **(SAT) Satisfactory**

● 15. Lanyard Attachment Points **(SAT) Satisfactory**

Atlantic Crane Inspection Services disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Atlantic Crane Inspection Services. Atlantic Crane Inspection Services shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

●	16. Toe Board & Mid Rail		(SAT) Satisfactory
●	17. Mesh Walling		(SAT) Satisfactory
●	18. Hand Signal Chart		(REC) Recommendation
	☞ <i>Hand signal chart peeling. Recommend replacing.</i>		
	19. Test Weight		
	Weight	Tested	How Long Tested
	1250 lbs	No	N/A
Verification and Completion			
	20. Inspector Name & Signature		Dylan VanHorn
			
	21. Additional Inspection Notes		
	<i>No visible deficiencies found at time of inspection</i>		
●	22. Sticker Given		(N) No, Will be Mailed