



Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

Our Lady Of Lourdes Hospital Camden, Nj

on

8/15/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

Signature

Date

Table of Contents

High

Med

Low

Section

Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400) - <i>Our Lady Of Lourdes</i> <i>Hospital Camden, Nj</i>	Telescoping Boom Crane: 043 562 - S371	0	0	0	1.0
--	---	---	---	---	------------

Overview

Breakdown by Form

Form Type	 High	 Med	 Low	# Forms
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)	0	0	0	1
Overall:	0	0	0	1

Breakdown by Location

Location	 High	 Med	 Low	# Forms
Our Lady Of Lourdes Hospital Camden, Nj	0	0	0	1
Overall:	0	0	0	1

Breakdown by Asset

Asset Type	 High	 Med	 Low	# Assets
Telescoping Boom Crane	0	0	0	1
Overall:	0	0	0	1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)

Sautter Crane Rental
2900 Black Lake Place
Philadelphia, PA 19154

FolderID: 081526S371
FormID: 30382821



Telescoping Boom Crane

Location: Our Lady Of Lourdes Hospital
Camden, Nj
Serial Number: 043 562
Unit Number: S371

Manufacturer: Liebherr
Model: LTM1110-5.2
Capacity: 125 Tons
Length/Lift: 197'
Type of Crane: All Terrain Crane
Number of Hoists: Main and Auxiliary (Not in Use)
Boom Configuration: Main Boom with Stowed Jib
Load Test: No

Priorities Found: ● **104 - Good**

General

1. Location of Equipment	Our Lady Of Lourdes Hospital Camden Nj
2. Hours & Mileage	
Hours	Mileage
1782	18,301

Inspection Information

3. Inspection Number	081526S371
4. Inspection Date	08/15/2026
5. Inspection Type	(Ann) Annual

Information & Records

6. Documentation of Annual/Comprehensive Inspection	(SAT) Satisfactory	
7. Daily/Monthly Inspection Records	(SAT) Satisfactory	
8. Maintenance Records	(SAT) Satisfactory	
9. Hand Signal Chart	(SAT) Satisfactory	P9
10. Safety and Warning Decals	(SAT) Satisfactory	P10
11. Operators Manual	(SAT) Satisfactory	

Safety Devices & Operational Aids

12. Backup Alarm	(SAT) Satisfactory
13. Audible Warning Device	(SAT) Satisfactory
14. Boom Angle Indicator	(SAT) Satisfactory
15. Boom Length Indicator	(SAT) Satisfactory
16. Drum Rotation Indicator(s)	(SAT) Satisfactory
17. Anti Two-Block Device/System	(SAT) Satisfactory
18. Load Moment Indicator (LMI)	(SAT) Satisfactory


Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 19.	Load Weight Indicator	(SAT) Satisfactory	
● 20.	Radius Indicator	(SAT) Satisfactory	
● 21.	Level Indicator(s)	(SAT) Satisfactory	
● 22.	Fire Extinguisher	(SAT) Satisfactory	P22
Load Chart			
● 23.	Visible/Accessible	(SAT) Satisfactory	
● 24.	Per Configuration	(SAT) Satisfactory	
● 25.	Durable/Legible/Secured	(SAT) Satisfactory	
Carrier			
● 26.	Steering	(SAT) Satisfactory	
● 27.	Parking Brake	(SAT) Satisfactory	
● 28.	Exterior Lights (Headlights, Turn Signals, Brake Lights, Reverse Lights)	(SAT) Satisfactory	
● 29.	Windshield & Wipers	(SAT) Satisfactory	P29
● 30.	Windows & Mirrors	(SAT) Satisfactory	P30
● 31.	Wheels & Tires	(SAT) Satisfactory	
● 32.	Engine	(SAT) Satisfactory	
● 33.	Exhaust System	(SAT) Satisfactory	
● 34.	Axle Lockout	(SAT) Satisfactory	
● 35.	Drive Line	(SAT) Satisfactory	
● 36.	Main Frame Members	(SAT) Satisfactory	
● 37.	Hoses/Fittings/Valves	(SAT) Satisfactory	
● 38.	Hydraulic Tank & Fluid Level	(SAT) Satisfactory	
● 39.	Slip Resistant Walking Surfaces	(SAT) Satisfactory	
● 40.	Steps/Ladders/Handrails	(SAT) Satisfactory	P40
Outriggers/Stabilizers			
● 41.	Structure & Mounting	(SAT) Satisfactory	
● 42.	Boxes & Beams	(SAT) Satisfactory	
● 43.	Cylinders	(SAT) Satisfactory	
● 44.	Pads/Floats	(SAT) Satisfactory	
● 45.	Hoses/Fittings/Valves	(SAT) Satisfactory	
Operators Station			
● 46.	Windows & Wipers	(SAT) Satisfactory	
● 47.	Cab Door Restraint	(SAT) Satisfactory	
● 48.	Cab Access	(SAT) Satisfactory	
● 49.	Steps/Ladders/Handrails	(SAT) Satisfactory	P49
● 50.	Anti-Skid Stepping Surfaces	(SAT) Satisfactory	
● 51.	Fire Extinguisher	(SAT) Satisfactory	
● 52.	Operator Horn	(SAT) Satisfactory	
● 53.	Controls Identified	(SAT) Satisfactory	
● 54.	Control Functions	(SAT) Satisfactory	
● 55.	Power Plant Controls	(SAT) Satisfactory	
● 56.	Operator Cutoff Switch (Deadman)	(SAT) Satisfactory	
● 57.	Accelerator/Throttle Control	(SAT) Satisfactory	
● 58.	Hoses/Fittings/Valves	(SAT) Satisfactory	
● 59.	Housekeeping	(SAT) Satisfactory	
Rotating Upper Structure			
● 60.	Structure	(SAT) Satisfactory	
● 61.	Hoses/Fittings/Valves	(SAT) Satisfactory	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 62.	Hydraulic & Pneumatic Pumps	(SAT) Satisfactory	
● 63.	Hydraulic Pressure	(SAT) Satisfactory	
● 64.	Electrical Wiring	(SAT) Satisfactory	
● 65.	Ring & Pinion Gear	(SAT) Satisfactory	P65
● 66.	Swing System/Assembly	(SAT) Satisfactory	
● 67.	Counterweight Frame	(SAT) Satisfactory	
● 68.	Counterweight Mounting	(SAT) Satisfactory	
Hoist System			
● 69.	Brakes & Clutch System	(SAT) Satisfactory	
● 70.	Wire Rope Reeving	(SAT) Satisfactory	
● 71.	2 Rope Wrap Minimum	(SAT) Satisfactory	
● 72.	Hoist Motor	(SAT) Satisfactory	
● 73.	Hoses/Fittings/Valves	(SAT) Satisfactory	
● 74.	Drums/Lagging/Flanges	(SAT) Satisfactory	
● 75.	Anchor System	(SAT) Satisfactory	
● 76.	Hoist Spooling	(SAT) Satisfactory	
Main Boom			
● 77.	Lift Cylinder(s)	(SAT) Satisfactory	
● 78.	Telescoping Boom Cylinder(s)	(SAT) Satisfactory	
● 79.	Hoses/Fittings/Valves	(SAT) Satisfactory	
● 80.	Holding Device	(SAT) Satisfactory	
● 81.	Boom Sections Alignment	(SAT) Satisfactory	P81
● 82.	Wear Pads	(SAT) Satisfactory	
● 83.	Sheaves	(SAT) Satisfactory	P83
● 84.	Wire Rope Retainers	(SAT) Satisfactory	
● 85.	Boom Hinge Pin	(SAT) Satisfactory	
● 86.	Boom Head Section	(SAT) Satisfactory	
● 87.	Auxiliary Boom Head	(SAT) Satisfactory	P87
● 88.	Structure	(SAT) Satisfactory	
Jib/Fly Extension			
● 89.	Structure	(SAT) Satisfactory	
● 90.	Locking Devices	(SAT) Satisfactory	
● 91.	Sheaves	(SAT) Satisfactory	P91
● 92.	Wire Rope Retainers	(SAT) Satisfactory	
● 93.	Alignment	(SAT) Satisfactory	
● 94.	End Connectors & Pins	(SAT) Satisfactory	P94
Main Drum Wire Rope			
95.	Wire Rope Information		
	Diameter	Construction/Type	Number of Parts
	19mm	non rotational	1 part
■	19.62mm		
● 96.	Rope Damage	(SAT) Satisfactory	
● 97.	Lubrication	(SAT) Satisfactory	
● 98.	End Connectors	(SAT) Satisfactory	
Main Hoist Load Block/Headache Ball/Hook			
99.	Capacity and Weight		
	Capacity	Weight	
	10 tons	250kg	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

100. Capacity Marking	(SAT) Satisfactory	P100
10 tons		
101. Weight Marking	(SAT) Satisfactory	P101
250lg		
102. Sheave(s)	(SAT) Satisfactory	P102
1 sheave block not in use on job		
103. Safety Latch(es)	(SAT) Satisfactory	P103
104. 0° Hook Bend/Twist	(SAT) Satisfactory	
105. 5% Hook Opening or 1/4" Max	(SAT) Satisfactory	
106. 10% Hook Wear Max	(SAT) Satisfactory	
107. Bearing	(SAT) Satisfactory	
108. Wedge Socket/End Fitting	(SAT) Satisfactory	P108
109. Reeving	(SAT) Satisfactory	
Auxiliary Drum Wire Rope		
110. Wire Rope Information		
Diameter	Constrcution/Type	Number of Parts
19mm	non rotational	stowed
19.83mm		
Verification and Completion		
111. Inspector Name & Signature	James Doan	
		
112. Additional Inspection Notes		
113. Sticker Given	(Y) Yes, Given on Site	



P9.1



P10.2



P10.3



P10.4




P22.5



P29.6




P30.7




P30.8



P40.9



P40.10



P49.11



P65.12




P65.13




P81.14



P83.15



P83.16



P87.17



P91.18



P94.19




P99.20

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



P100.21



P101.22



P102.23



P103.24



P103.25



P108.26