

Below the Hook Lifting Devices Sautter Crane Rental

FolderID: 12222 FormID: 16959697



Below the Hook Devices Completed by: Dylan VanHorn on 06/03/2023 Location: Black Lake Place, Phila., PA Serial Number: SB09 Unit #: SB09

Type:	Lifting Beam (B30.20)
Manufacturer:	Progressive
Model Number:	N/A
Capacity:	10,000 lbs
Net Weight:	130 lbs
Rigging Attached :	Yes
Work Performed:	Inspection

Priorities Found: • 11 - Good

Location of Equipment

1. Location of Equipment Philadelphia, PA

Customer Sign Off

2. Customer Sign Off

IF THERE ARE NO DEFICIENCIES NOTHING NEEDS TO BE DONE.

IF THERE ARE ANY HIGH, RED, DEFICIENCIES PLEASE FOLLOW THE BELOW INSTRUCTIONS

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS PAGE ONLY to either jaime@atlanticcrane.com or gina@atlanticcrane.com or fax THIS PAGE ONLY to our office at215-639-2316 and a certification and sticker will be issued. The above deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However, those items should be corrected to improve equipment reliability and safety.

The undersigned verifies the listed deficience	cies denoted with an (DEF, HIGH, RED) have been corrected.
Signature	

		Signature	Date				
In	Inspection Information						
	3.	Inspection Number		23060302DV			
	4.	Inspection Date		06/03/2023			
	5.	Inspection Type		(Ann) Annual			
Li	Lifting Equipment						
	6.	Lifting Equipment Description		Spreader Bar			
	7.	Lifting Equipment Dimensions		8' - 14'			
	8.	Identification Marking		(SAT) Satisfactory			
	9.	Weight & Capacity marking		(SAT) Satisfactory			
	10.	Manufacturer Plate		(SAT) Satisfactory			
	11.	Structure		(SAT) Satisfactory			
	12.	Welds		(SAT) Satisfactory			
	13.	Lifting Eyes		(SAT) Satisfactory			
	14.	Locking Pins/Keeper Pins		(SAT) Satisfactory			
D	Pigging						

Rigging

Atlantic Crane Inspection Services disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Atlantic Crane Inspection Services. Atlantic Crane Inspection Services shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

15	5. Wire Rope Information				
	Size	Overall Capacity	Number of Legs		
	3/4"	5.6 tons	2 legs		
• 16	6. Wire Rope Condition		(SAT) Satisfactory		
17	7. Shackle Information				
	Size	Capacity	Number of Shackles		
	3/4"	4 3/4 tons	2 shackles		
• 18	8. Shackle Condition		(SAT) Satisfactory		
Verification and Completion					
19	9. Inspector Name & Signature		Dylan VanHorn		
1). Vale				
20	0. Additional Inspection Notes				
	No visible deficiencies found at time o	finspection			
21	1. Sticker Given		(N) No, Will be Mailed		