Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

4101 Market Street

on

10/11/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

_____ _____

Signature Date

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Table of Contents

		High	Med	Low	Section
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400) - *4101 Market Street*	Telescoping Boom Crane*: 072 405 - S307*	0	0	0	**1.0**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview

Breakdown by Form

Form Type	High	Med	Low	# Forms
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Breakdown by Location

Location	High	Med	Low	# Forms
4101 Market Street	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Breakdown by Asset

Asset Type	High	Med	Low	# Assets
Telescoping Boom Crane	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)

FolderID: 101026S307
FormID: 31185258

Sautter Crane Rental
2900 Black Lake Place
Philadelphia, PA 19154



Telescoping Boom Crane

Location:	4101 Market Street 4101 Market Street Philadelphia, PA 19104
Serial Number:	072 405
Unit Number:	S307
Status:	In Service

Additional Notes: 152' main boom with Y--Guy
253' luffing jib
1 part of line
264,000 lbs counterweight

Manufacturer:	Liebherr
Model:	LTM 1400-7.1
Capacity:	500 Tons
Length/Lift:	Main Boom 152' Luffing Jib 253'
Type of Crane:	All Terrain Crane
Number of Hoists:	Main and Auxiliary
Boom Configuration:	Main Boom & Luffing Jib Assembled
Load Test:	No

Priorities Found: ● **121 - Good**

General

● 1.	Location of Equipment	**4101 Market Street**
2.	Customer Sign Off	

Please return the entire report.
Customer Sign Off
-If there are no deficiencies nothing needs to be done
-If there are any (HIGH, RED) deficiencies please follow the instructions below
The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.
-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

_____ _____
Signature

● 3. Hours & Mileage

Hours	Mileage
4,410	**26,976**

Inspection Information

● 4.	Inspection Number	**101026S307**
● 5.	Inspection Date	**10/10/2026**
● 6.	Inspection Type	**(Ann) Annual**

Information & Records

● 7.	Documentation of Annual/Comprehensive Inspection	**(SAT) Satisfactory**
● 8.	Daily/Monthly Inspection Records	**(SAT) Satisfactory**
● 9.	Safety and Warning Decals	**(SAT) Satisfactory**
● 10.	Operators Manual	**(SAT) Satisfactory**

Safety Devices & Operational Aids

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

11.	Backup Alarm	**(SAT) Satisfactory**
12.	Audible Warning Device	**(SAT) Satisfactory**
13.	Boom Angle Indicator	**(SAT) Satisfactory**
14.	Boom Length Indicator	**(SAT) Satisfactory**
15.	Drum Rotation Indicator(s)	**(SAT) Satisfactory**
16.	Anti Two-Block Device/System	**(SAT) Satisfactory**
17.	Load Moment Indicator (LMI)	**(SAT) Satisfactory**
18.	Load Weight Indicator	**(SAT) Satisfactory**
19.	Radius Indicator	**(SAT) Satisfactory**
20.	Level Indicator(s)	**(SAT) Satisfactory**
21.	Fire Extinguisher	**(SAT) Satisfactory**
Load Chart		
22.	Visible/Accessible	**(SAT) Satisfactory**
23.	Per Configuration	**(SAT) Satisfactory**
24.	Durable/Legible/Secured	**(SAT) Satisfactory**
Carrier		
25.	Steering	**(SAT) Satisfactory**
26.	Parking Brake	**(SAT) Satisfactory**
27.	Exterior Lights (Headlights, Turn Signals, Brake Lights, Reverse Lights)	**(SAT) Satisfactory**
28.	Windshield & Wipers	**(SAT) Satisfactory**
29.	Windows & Mirrors	**(SAT) Satisfactory**
30.	Wheels & Tires	**(SAT) Satisfactory**
31.	Engine	**(SAT) Satisfactory**
32.	Exhaust System	**(SAT) Satisfactory**
33.	Axle Lockout	**(SAT) Satisfactory**
34.	Drive Line	**(SAT) Satisfactory**
35.	Main Frame Members	**(SAT) Satisfactory**
36.	Hoses/Fittings//Valves	**(SAT) Satisfactory**
37.	Hydraulic Tank & Fluid Level	**(SAT) Satisfactory**
38.	Slip Resistant Walking Surfaces	**(SAT) Satisfactory**
39.	Steps/Ladders/Handrails	**(SAT) Satisfactory**
Outriggers/Stabilizers		
40.	Structure & Mounting	**(SAT) Satisfactory**
41.	Boxes & Beams	**(SAT) Satisfactory**
42.	Cylinders	**(SAT) Satisfactory**
43.	Pads/Floats	**(SAT) Satisfactory**
44.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
Operators Station		
45.	Windows & Wipers	**(SAT) Satisfactory**
46.	Cab Door Restraint	**(SAT) Satisfactory**
47.	Cab Access	**(SAT) Satisfactory**
48.	Steps/Ladders/Handrails	**(SAT) Satisfactory**
49.	Anti-Skid Stepping Surfaces	**(SAT) Satisfactory**
50.	Fire Extinguisher	**(SAT) Satisfactory**
51.	Operator Horn	**(SAT) Satisfactory**
52.	Controls Identified	**(SAT) Satisfactory**
53.	Control Functions	**(SAT) Satisfactory**
54.	Power Plant Controls	**(SAT) Satisfactory**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

55.	Operator Cutoff Switch (Deadman)	**(SAT) Satisfactory**
56.	Brake & Clutch	**(NA) Not Applicable**
57.	Travel Controls	**(NA) Not Applicable**
58.	Accelerator/Throttle Control	**(SAT) Satisfactory**
59.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
60.	Housekeeping	**(SAT) Satisfactory**
Rotating Upper Structure		
61.	Structure	**(SAT) Satisfactory**
62.	Engine	**(SAT) Satisfactory**
63.	Exhaust System/Guards/Insulators	**(SAT) Satisfactory**
64.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
65.	Hydraulic & Pneumatic Pumps	**(SAT) Satisfactory**
66.	Hydraulic Pressure	**(SAT) Satisfactory**
67.	Electrical Wiring	**(SAT) Satisfactory**
68.	Ring & Pinion Gear	**(SAT) Satisfactory**
69.	Swing System/Assembly	**(SAT) Satisfactory**
70.	Counterweight Frame	**(SAT) Satisfactory**
71.	Counterweight Mounting	**(SAT) Satisfactory**
Hoist System		
72.	Brakes & Clutch System	**(SAT) Satisfactory**
73.	Wire Rope Reeving	**(SAT) Satisfactory**
	1 part of line	
74.	2 Rope Wrap Minimum	**(SAT) Satisfactory**
75.	Hoist Motor	**(SAT) Satisfactory**
76.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
77.	Drums/Lagging/Flanges	**(SAT) Satisfactory**
78.	Anchor System	**(SAT) Satisfactory**
79.	Hoist Spooling	**(SAT) Satisfactory**
Main Boom		
80.	Lift Cylinder(s)	**(SAT) Satisfactory**
81.	Telescoping Boom Cylinder(s)	**(SAT) Satisfactory**
82.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
83.	Holding Device	**(SAT) Satisfactory**
84.	Boom Sections Alignment	**(SAT) Satisfactory**
85.	Wear Pads	**(SAT) Satisfactory**
86.	Sheaves	**(SAT) Satisfactory**
87.	Wire Rope Retainers	**(SAT) Satisfactory**
88.	Boom Hinge Pin	**(SAT) Satisfactory**
89.	Boom Head Section	**(SAT) Satisfactory**
90.	Auxiliary Boom Head	**(NA) Not Applicable**
91.	Structure	**(SAT) Satisfactory**
Luffing Boom Attachment		
92.	Luffing Jib Section Identification	**(SAT) Satisfactory**
93.	Luffing Jib Section Sequence	**(SAT) Satisfactory**
94.	Luffing Jib Tip Section	**(SAT) Satisfactory**
95.	Luffing Jib Point Sheaves	**(SAT) Satisfactory**
96.	Luffing Hoist Line Dead End	**(SAT) Satisfactory**
97.	Luffing Jib Warning Decals	**(SAT) Satisfactory**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

98.	Luffing Jib Foot Keepers & Pins	**(SAT) Satisfactory**
99.	Lattice Members	**(SAT) Satisfactory**
100.	Cord Members	**(SAT) Satisfactory**
101.	End Connections & Pins	**(SAT) Satisfactory**
102.	Luffing Jib Angle Indicator	**(SAT) Satisfactory**
103.	Luffing Jib Stops	**(SAT) Satisfactory**
104.	Luffing Jib Hoist Reeving	**(SAT) Satisfactory**
105.	Guard Rails & Walking Surfaces	**(SAT) Satisfactory**

Main Drum Wire Rope

106. Wire Rope Information

Diameter	Construction/Type	Number of Parts
25.47 mm	**Non Rot RLL**	**1**

107.	Rope Damage	**(SAT) Satisfactory**
108.	Lubrication	**(SAT) Satisfactory**
109.	End Connectors	**(SAT) Satisfactory**

Main Hoist Load Block/Headache Ball/Hook

110. Capacity and Weight

Capacity	Weight
12.5 tonnes	**500 kg**

111.	Capacity Marking	**(SAT) Satisfactory**
112.	Weight Marking	**(SAT) Satisfactory**
113.	Sheave(s)	**(NA) Not Applicable**
114.	Safety Latch(es)	**(SAT) Satisfactory**
115.	0° Hook Bend/Twist	**(SAT) Satisfactory**
116.	5% Hook Opening or 1/4" Max	**(SAT) Satisfactory**
117.	10% Hook Wear Max	**(SAT) Satisfactory**
118.	Bearing	**(SAT) Satisfactory**
119.	Wedge Socket/End Fitting	**(SAT) Satisfactory**
120.	Reeving	**(SAT) Satisfactory**

1 part of line

Auxiliary Drum Wire Rope

121. Wire Rope Information

Diameter	Constrcution/Type	Number of Parts
25.57mm	**Non Rot RLL**	**N/A**

Luffing Jib

122.	Rope Damage	**(SAT) Satisfactory**
123.	Lubrication	**(SAT) Satisfactory**
124.	End Connectors	**(SAT) Satisfactory**

Verification and Completion

125. Inspector Name & Signature **Anthony Capozzi**



126. Additional Inspection Notes

127.	Sticker Given	**(Y) Yes, Given on Site**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.