Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

Our Lady Of Lourdes Hospital Camden, Nj

on

10/24/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

_____ _____

Signature Date

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Table of Contents

		High	Med	Low	Section
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400) - *Our Lady Of Lourdes Hospital Camden, Nj*	Telescoping Boom Crane*: 085771 - S317*	0	0	0	**1.0**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview

Breakdown by Form

Form Type	High	Med	Low	# Forms
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Breakdown by Location

Location	High	Med	Low	# Forms
Our Lady Of Lourdes Hospital Camden, Nj	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Breakdown by Asset

Asset Type	High	Med	Low	# Assets
Telescoping Boom Crane	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)

FolderID: 102426S317
FormID: 31370756

Sautter Crane Rental
2900 Black Lake Place
Philadelphia, PA 19154



Telescoping Boom Crane

Location:	Our Lady Of Lourdes Hospital Camden, Nj
Serial Number:	085771
Unit Number:	S317
Status:	In Service

Additional Notes: 164 ft boom
2 parts of line

Manufacturer:	Liebherr
Model:	LTM1070 4.2
Capacity:	80 Tons
Length/Lift:	164'
Type of Crane:	All Terrain Crane
Number of Hoists:	Main and Auxiliary (Not in Use)
Boom Configuration:	Main Boom with Stowed Jib
Load Test:	No

Priorities Found: ● **114 - Good**

General

●	1.	Location of Equipment	**Our Lady of Lourdes Hospital**
	2.	Customer Sign Off	

Please return the entire report.
Customer Sign Off
-If there are no deficiencies nothing needs to be done
-If there are any (HIGH, RED) deficiencies please follow the instructions below
The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.
-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

_____ _____
Signature

●	3.	Hours & Mileage		
		Hours	Mileage	
		4,157	**24,649**	

Inspection Information

●	4.	Inspection Number	**102426S317**
●	5.	Inspection Date	**10/24/2026**
●	6.	Inspection Type	**(Ann) Annual**

Information & Records

●	7.	Documentation of Annual/Comprehensive Inspection	**(SAT) Satisfactory**
●	8.	Daily/Monthly Inspection Records	**(SAT) Satisfactory**
●	9.	Maintenance Records	**(SAT) Satisfactory**
●	10.	Hand Signal Chart	**(SAT) Satisfactory**
●	11.	Safety and Warning Decals	**(SAT) Satisfactory**
●	12.	Operators Manual	**(SAT) Satisfactory**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Safety Devices & Operational Aids		
13.	Backup Alarm	**(SAT) Satisfactory**
	Not used because of noise restriction	
14.	Audible Warning Device	**(SAT) Satisfactory**
15.	Boom Angle Indicator	**(SAT) Satisfactory**
16.	Boom Length Indicator	**(SAT) Satisfactory**
17.	Drum Rotation Indicator(s)	**(SAT) Satisfactory**
18.	Anti Two-Block Device/System	**(SAT) Satisfactory**
19.	Load Moment Indicator (LMI)	**(SAT) Satisfactory**
20.	Load Weight Indicator	**(SAT) Satisfactory**
21.	Radius Indicator	**(SAT) Satisfactory**
22.	Level Indicator(s)	**(SAT) Satisfactory**
23.	Fire Extinguisher	**(SAT) Satisfactory**
Load Chart		
24.	Visible/Accessible	**(SAT) Satisfactory**
25.	Per Configuration	**(SAT) Satisfactory**
26.	Durable/Legible/Secured	**(SAT) Satisfactory**
Carrier		
27.	Steering	**(SAT) Satisfactory**
28.	Parking Brake	**(SAT) Satisfactory**
29.	Exterior Lights (Headlights, Turn Signals, Brake Lights, Reverse Lights)	**(SAT) Satisfactory**
30.	Windshield & Wipers	**(SAT) Satisfactory**
31.	Windows & Mirrors	**(SAT) Satisfactory**
32.	Wheels & Tires	**(SAT) Satisfactory**
33.	Engine	**(SAT) Satisfactory**
34.	Exhaust System	**(SAT) Satisfactory**
35.	Axle Lockout	**(SAT) Satisfactory**
36.	Drive Line	**(SAT) Satisfactory**
37.	Main Frame Members	**(SAT) Satisfactory**
38.	Hoses/Fittings//Valves	**(SAT) Satisfactory**
39.	Hydraulic Tank & Fluid Level	**(SAT) Satisfactory**
40.	Slip Resistant Walking Surfaces	**(SAT) Satisfactory**
41.	Steps/Ladders/Handrails	**(SAT) Satisfactory**
Outriggers/Stabilizers		
42.	Structure & Mounting	**(SAT) Satisfactory**
43.	Boxes & Beams	**(SAT) Satisfactory**
44.	Cylinders	**(SAT) Satisfactory**
45.	Pads/Floats	**(SAT) Satisfactory**
46.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
Operators Station		
47.	Windows & Wipers	**(SAT) Satisfactory**
48.	Cab Door Restraint	**(SAT) Satisfactory**
49.	Cab Access	**(SAT) Satisfactory**
50.	Steps/Ladders/Handrails	**(SAT) Satisfactory**
51.	Anti-Skid Stepping Surfaces	**(SAT) Satisfactory**
52.	Fire Extinguisher	**(SAT) Satisfactory**
53.	Operator Horn	**(SAT) Satisfactory**
	Operators horn must be hooked up prior to use	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

54.	Controls Identified	**(SAT) Satisfactory**
55.	Control Functions	**(SAT) Satisfactory**
56.	Power Plant Controls	**(SAT) Satisfactory**
57.	Operator Cutoff Switch (Deadman)	**(SAT) Satisfactory**
58.	Brake & Clutch	**(SAT) Satisfactory**
59.	Travel Controls	**(SAT) Satisfactory**
60.	Accelerator/Throttle Control	**(SAT) Satisfactory**
61.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
62.	Housekeeping	**(SAT) Satisfactory**
Rotating Upper Structure		
63.	Structure	**(SAT) Satisfactory**
64.	Engine	**(NA) Not Applicable**
65.	Exhaust System/Guards/Insulators	**(NA) Not Applicable**
66.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
67.	Hydraulic & Pneumatic Pumps	**(SAT) Satisfactory**
68.	Hydraulic Pressure	**(SAT) Satisfactory**
69.	Electrical Wiring	**(SAT) Satisfactory**
70.	Ring & Pinion Gear	**(SAT) Satisfactory**
71.	Swing System/Assembly	**(SAT) Satisfactory**
72.	Counterweight Frame	**(SAT) Satisfactory**
73.	Counterweight Mounting	**(SAT) Satisfactory**
Hoist System		
74.	Brakes & Clutch System	**(SAT) Satisfactory**
75.	Wire Rope Reeving	**(SAT) Satisfactory**
	2 parts of line	
76.	2 Rope Wrap Minimum	**(SAT) Satisfactory**
77.	Hoist Motor	**(SAT) Satisfactory**
78.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
79.	Drums/Lagging/Flanges	**(SAT) Satisfactory**
80.	Anchor System	**(SAT) Satisfactory**
81.	Hoist Spooling	**(SAT) Satisfactory**
Main Boom		
82.	Lift Cylinder(s)	**(SAT) Satisfactory**
83.	Telescoping Boom Cylinder(s)	**(SAT) Satisfactory**
84.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
85.	Holding Device	**(SAT) Satisfactory**
86.	Boom Sections Alignment	**(SAT) Satisfactory**
87.	Wear Pads	**(SAT) Satisfactory**
88.	Sheaves	**(SAT) Satisfactory**
89.	Wire Rope Retainers	**(SAT) Satisfactory**
90.	Boom Hinge Pin	**(SAT) Satisfactory**
91.	Boom Head Section	**(SAT) Satisfactory**
92.	Auxiliary Boom Head	**(SAT) Satisfactory**
93.	Structure	**(SAT) Satisfactory**
Jib/Fly Extension		
94.	Structure	**(SAT) Satisfactory**
95.	Locking Devices	**(SAT) Satisfactory**
96.	Sheaves	**(SAT) Satisfactory**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

97.	Wire Rope Retainers	**(SAT) Satisfactory**
98.	Alignment	**(SAT) Satisfactory**
99.	End Connectors & Pins	**(SAT) Satisfactory**

Main Drum Wire Rope

100. Wire Rope Information

Diameter	Construction/Type	Number of Parts
17.53mm	**Non Rot RLL**	**2**

101.	Rope Damage	**(SAT) Satisfactory**
102.	Lubrication	**(SAT) Satisfactory**
103.	End Connectors	**(SAT) Satisfactory**

Main Hoist Load Block/Headache Ball/Hook

104. Capacity and Weight

Capacity	Weight
20 tonnes	**325 kg**

105.	Capacity Marking	**(SAT) Satisfactory**
106.	Weight Marking	**(SAT) Satisfactory**
107.	Sheave(s)	**(SAT) Satisfactory**
108.	Safety Latch(es)	**(SAT) Satisfactory**
109.	0° Hook Bend/Twist	**(SAT) Satisfactory**
110.	5% Hook Opening or 1/4" Max	**(SAT) Satisfactory**
111.	10% Hook Wear Max	**(SAT) Satisfactory**
112.	Bearing	**(SAT) Satisfactory**
113.	Wedge Socket/End Fitting	**(SAT) Satisfactory**
114.	Reeving	**(SAT) Satisfactory**

2 parts of line

Auxiliary Drum Wire Rope

115. Wire Rope Information

Diameter	Constrcution/Type	Number of Parts
17.68mm	**Non Rot RLL**	**N/A**

Verification and Completion

116. Inspector Name & Signature **Anthony Capozzi**



117. Additional Inspection Notes

118. Sticker Given **(Y) Yes, Given on Site**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.