

Below the Hook Lifting Devices
Sautter Crane Rental

Atlantic Crane Inspection Services P.O. Box 747 Bensalem, PA 19020 (215) 639-2579

> FolderID: 14758 FormID: 23222691



## Below the Hook Devices Completed by: Brian McMahon on 01/31/2025 Location: USA Serial Number: 11517-02 Unit #: SP-2

Type:	Material Basket (B30.20)	
Manufacturer:	IIS Inc	
Capacity:	3 tons	
Net Weight:	1400 lbs	
Rigging Attached :	No	
Work Performed:	Inspection	

Priorities Found: 6 - Good

## **Location of Equipment**

1. Location of Equipment Black Lake PI

## **Customer Sign Off**

2. Customer Sign Off

IF THERE ARE NO DEFICIENCIES NOTHING NEEDS TO BE DONE.

IF THERE ARE ANY HIGH, RED, DEFICIENCIES PLEASE FOLLOW THE BELOW INSTRUCTIONS

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS PAGE ONLY to either jaime@atlanticcrane.com or gina@atlanticcrane.com or fax THIS PAGE ONLY to our office at215-639-2316 and a certification and sticker will be issued. The above deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However, those items should be corrected to improve equipment reliability and safety.

The undersigned verifies the listed deficiencies denoted with an (DEF, HIGH, RED) have been corrected.

		Signature	Date	
In	spec	tion Information		
	3.	Inspection Number		24013101BM
	4.	Inspection Date		01/31/2025
	5.	Inspection Type		(Ann) Annual
M	ateri	al Basket		
	6.	Rating Plate		(SAT) Satisfactory
	7.	Edge & Surfaces		(SAT) Satisfactory
	8.	Welds		(SAT) Satisfactory
	9.	Attachment Points/Lifting Eyes		(SAT) Satisfactory
Ve	erific	ation and Completion		
	10.	Inspector Name & Signature		Brian C McMahon

Atlantic Crane Inspection Services disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Atlantic Crane Inspection Services. Atlantic Crane Inspection Services shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



11. Sticker Given
 (Y) Yes, Given on Site