



Prepared for:

Sautter Crane rental

2900 Black Lake Place Philadelphia, PA 19154

Sautter Yard

on

10/11/2025

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

Signature

Date

Table of Contents

 High  Med  Low Section

Lifting Bar - <i>Sautter Yard</i>	Below the Hook Devices: <i>SER NO - SB04 - SB04</i>	0	0	0	1.0
-----------------------------------	---	---	---	---	------------

Overview

Breakdown by Form

Form Type	 High	 Med	 Low	# Forms
Lifting Bar	0	0	0	1
Overall:	0	0	0	1

Breakdown by Location

Location	 High	 Med	 Low	# Forms
Sautter Yard	0	0	0	1
Overall:	0	0	0	1

Breakdown by Asset

Asset Type	 High	 Med	 Low	# Assets
Below the Hook Devices	0	0	0	1
Overall:	0	0	0	1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Lifting Bar
Sautter Crane rental
2900 Black Lake Place
Philadelphia, PA 19154

FolderID: 101125SB04
FormID: 26195785



Below the Hook Devices

Location: Sautter Yard
2900 Black Lake Place
Philadelphia, PA 19154

Identifier: SER NO - SB04

TagID: SB04

Type: Spreader Beam

Capacity: 5 tons

Manufacturer: Sautter

Model Number: SCR.5T

Length/Lift: 8'2" to 13'3"

Priorities Found: ● 13 - Good

General

● 1. Bar has no obvious bend, twist or deformation. (SAT) Satisfactory

Manufacturer

● 2. Make Sautter

Manufacturer Model Number

● 3. Model SCR.5T

Capacity

● 4. Rated Capacity of device 5 Tons

Tare Weight

● 5. Weight of device 135lbs

Markings

● 6. The weight and capacity of the device are clearly and permanently displayed. (Y) Yes

Proof Load Test

● 7. Was a proof load test performed at time of inspection? (Y) Yes

Proof tested at 12,500 lbs

Corrosion

● 8. No visible corrosion that may effect the structural integrity of the device. (SAT) Satisfactory

Rigging Connection Points

● 9. All possible points of connection do not have any visible cracks, deformation or excessive wear. (SAT) Satisfactory

Adjustability

● 10. If the device is adjustable, Are all pins/fixtures secure and in proper working condition? (Y) Yes

Name Of Inspector

● 11. Inspector Anthony Capozzi

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

**Date Of Inspection**

● 12. Inspection performed on **10/11/2025**

Certificate

● 13. Was a certificate issued? **(Y) Yes**