




Prepared for:

## **Sautter Crane Rental**

2900 Black Lake Place Philadelphia, PA 19154

3400 Spruce Street Phila

on

7/11/2026

Please return the entire report.

**Customer Sign Off**

**-If there are no deficiencies nothing needs to be done**

**-If there are any (HIGH, RED) deficiencies please follow the instructions below**

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to [tony.rossi@tandemlift.com](mailto:tony.rossi@tandemlift.com) or [jon.santimaw@tandemlift.com](mailto:jon.santimaw@tandemlift.com). After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

---

Signature

---

Date

# Table of Contents

Lifting Bar - 3400 Spruce Street Phila

Below the Hook Devices: SER NO -  
180074 - 20A

|  High |  Med |  Low | Section    |
|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|------------|
| 0                                                                                        | 0                                                                                       | 0                                                                                       | <b>1.0</b> |

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

# Overview

## Breakdown by Form

| Form Type   |  High |  Med |  Low | # Forms |
|-------------|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------|
| Lifting Bar | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |
| Overall:    | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |

## Breakdown by Location

| Location                 |  High |  Med |  Low | # Forms |
|--------------------------|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------|
| 3400 Spruce Street Phila | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |
| Overall:                 | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |

## Breakdown by Asset

| Asset Type             |  High |  Med |  Low | # Assets |
|------------------------|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|----------|
| Below the Hook Devices | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1        |
| Overall:               | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1        |



Tandem Lift LLC  
321 Enlow Place  
Pennsville, NJ 08070  
833-TANDEM1

## Lifting Bar

**Sautter Crane Rental**  
2900 Black Lake Place  
Philadelphia, PA 19154

FolderID: 07112620A  
FormID: 29904642



### Below the Hook Devices

**Location:** 3400 Spruce Street Phila  
**Identifier:** SER NO - 180074  
**TagID:** 20A  
**Description:** Modular Spreader Beam

**Type:** Modular Spreader Beam  
**Capacity:** 35 Tons  
**Manufacturer:** Boscaro  
**Model Number:** EZBAR-35T  
**Length/Lift:** 8' 6"

Priorities Found: ● 12 - Good

### General

- 1. Bar has no obvious bend, twist or deformation.

(SAT) Satisfactory

### Manufacturer

- 2. Make

Boscaro

### Manufacturer Model Number

- 3. Model

EZBAR-35T

### Capacity

- 4. Rated Capacity of device

35 Tons

### Tare Weight

- 5. Weight of device

239 lbs

### Markings

- 6. The weight and capacity of the device are clearly and permanently displayed.

(Y) Yes

### Corrosion

- 7. No visible corrosion that may effect the structural integrity of the device.

(SAT) Satisfactory

### Rigging Connection Points

- 8. All possible points of connection do not have any visible cracks, deformation or excessive wear.

(SAT) Satisfactory

### Adjustability

- 9. If the device is adjustable, Are all pins/fixtures secure and in proper working condition?

(Y) Yes



P9

☐ Safety pins must be installed on threaded pins before use

### Name Of Inspector

- 10. Inspector

Anthony Capozzi

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

*AC*


**Date Of Inspection**

- 11. Inspection performed on  
**Certificate**

07/11/2026

- 12. Was a certificate issued?

(Y) Yes



P9.1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Prepared for:

## **Sautter Crane Rental**

2900 Black Lake Place Philadelphia, PA 19154

3400 Spruce Street Phila

on

7/11/2026

Please return the entire report.

**Customer Sign Off**

**-If there are no deficiencies nothing needs to be done**

**-If there are any (HIGH, RED) deficiencies please follow the instructions below**

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to [tony.rossi@tandemlift.com](mailto:tony.rossi@tandemlift.com) or [jon.santimaw@tandemlift.com](mailto:jon.santimaw@tandemlift.com). After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

---

Signature

---

Date

# Table of Contents

Lifting Bar - 3400 Spruce Street Phila

Below the Hook Devices: SER NO -  
180075 - 20B

|  High |  Med |  Low | Section |
|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------|
| 0                                                                                        | 0                                                                                       | 0                                                                                       | 1.0     |

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

# Overview

## Breakdown by Form

| Form Type   |  High |  Med |  Low | # Forms |
|-------------|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------|
| Lifting Bar | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |
| Overall:    | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |

## Breakdown by Location

| Location                 |  High |  Med |  Low | # Forms |
|--------------------------|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------|
| 3400 Spruce Street Phila | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |
| Overall:                 | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |

## Breakdown by Asset

| Asset Type             |  High |  Med |  Low | # Assets |
|------------------------|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|----------|
| Below the Hook Devices | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1        |
| Overall:               | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1        |

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Tandem Lift LLC  
321 Enlow Place  
Pennsville, NJ 08070  
833-TANDEM1

## Lifting Bar

### Sautter Crane Rental

2900 Black Lake Place  
Philadelphia, PA 19154

FolderID: 07112620B  
FormID: 29904641



#### Below the Hook Devices

**Location:** 3400 Spruce Street Phila  
**Identifier:** SER NO - 180075  
**TagID:** 20B  
**Description:** Modular Spreader Beam

**Type:** Modular Spreader Beam  
**Capacity:** 35 Tons  
**Manufacturer:** Boscaro  
**Model Number:** EZBAR-35T  
**Length/Lift:** 8' 6"

Priorities Found: ● 12 - Good

#### General

- 1. Bar has no obvious bend, twist or deformation.

(SAT) Satisfactory

#### Manufacturer

- 2. Make

Boscaro

#### Manufacturer Model Number

- 3. Model

EZBAR-35T

#### Capacity

- 4. Rated Capacity of device

35 Tons

#### Tare Weight

- 5. Weight of device

239 lbs

#### Markings

- 6. The weight and capacity of the device are clearly and permanently displayed.

(Y) Yes

#### Corrosion

- 7. No visible corrosion that may effect the structural integrity of the device.

(SAT) Satisfactory

#### Rigging Connection Points

- 8. All possible points of connection do not have any visible cracks, deformation or excessive wear.

(SAT) Satisfactory

#### Adjustability

- 9. If the device is adjustable, Are all pins/fixtures secure and in proper working condition?

(Y) Yes



P9

☐ Safety pins must be installed on threaded pins before use

#### Name Of Inspector

- 10. Inspector

Anthony Capozzi

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

*[Handwritten Signature]*

**Date Of Inspection**


- 11. Inspection performed on

07/11/2026

**Certificate**

- 12. Was a certificate issued?

(Y) Yes



P9.1



Prepared for:

## **Sautter Crane Rental**

2900 Black Lake Place Philadelphia, PA 19154

3400 Spruce Street Phila

on

7/11/2026

Please return the entire report.

**Customer Sign Off**

**-If there are no deficiencies nothing needs to be done**

**-If there are any (HIGH, RED) deficiencies please follow the instructions below**

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to [tony.rossi@tandemlift.com](mailto:tony.rossi@tandemlift.com) or [jon.santimaw@tandemlift.com](mailto:jon.santimaw@tandemlift.com). After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

---

Signature

---

Date

# Table of Contents

Lifting Bar - 3400 Spruce Street Phila

Below the Hook Devices: SER NO -  
180076 - 20C

|  High |  Med |  Low | Section |
|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------|
| 0                                                                                        | 0                                                                                       | 0                                                                                       | 1.0     |

# Overview

## Breakdown by Form

| Form Type   |  High |  Med |  Low | # Forms |
|-------------|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------|
| Lifting Bar | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |
| Overall:    | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |

## Breakdown by Location

| Location                 |  High |  Med |  Low | # Forms |
|--------------------------|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------|
| 3400 Spruce Street Phila | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |
| Overall:                 | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |

## Breakdown by Asset

| Asset Type             |  High |  Med |  Low | # Assets |
|------------------------|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|----------|
| Below the Hook Devices | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1        |
| Overall:               | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1        |



Tandem Lift LLC  
321 Enlow Place  
Pennsville, NJ 08070  
833-TANDEM1

**Lifting Bar**  
**Sautter Crane Rental**  
2900 Black Lake Place  
Philadelphia, PA 19154

FolderID: 07112620C  
FormID: 29904643



#### Below the Hook Devices

**Location:** 3400 Spruce Street Phila  
**Identifier:** SER NO - 180076  
**TagID:** 20C  
**Description:** Modular Spreader Beam

**Type:** Modular Spreader Beam  
**Capacity:** 35 Tons  
**Manufacturer:** Boscaro  
**Model Number:** EZBAR-35T  
**Length/Lift:** 8' 6"

Priorities Found: ● 12 - Good

#### General

- 1. Bar has no obvious bend, twist or deformation. (SAT) Satisfactory

#### Manufacturer

- 2. Make Boscaro

#### Manufacturer Model Number

- 3. Model EZBAR-35T

#### Capacity

- 4. Rated Capacity of device 35 Tons

#### Tare Weight

- 5. Weight of device 239 lbs

#### Markings

- 6. The weight and capacity of the device are clearly and permanently displayed. (Y) Yes

#### Corrosion

- 7. No visible corrosion that may effect the structural integrity of the device. (SAT) Satisfactory

#### Rigging Connection Points

- 8. All possible points of connection do not have any visible cracks, deformation or excessive wear. (SAT) Satisfactory

#### Adjustability

- 9. If the device is adjustable, Are all pins/fixtures secure and in proper working condition? (Y) Yes P9

☐ Safety pins must be installed on threaded pins before use

#### Name Of Inspector

- 10. Inspector Anthony Capozzi

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

AL

**Date Of Inspection**

- 11. Inspection performed on

07/11/2026

**Certificate**


- 12. Was a certificate issued?

(Y) Yes



P9.1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Prepared for:

## **Sautter Crane Rental**

2900 Black Lake Place Philadelphia, PA 19154

3400 Spruce Street Phila

on

7/11/2026

Please return the entire report.

**Customer Sign Off**

**-If there are no deficiencies nothing needs to be done**

**-If there are any (HIGH, RED) deficiencies please follow the instructions below**

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to [tony.rossi@tandemlift.com](mailto:tony.rossi@tandemlift.com) or [jon.santimaw@tandemlift.com](mailto:jon.santimaw@tandemlift.com). After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

---

Signature

---

Date

# Table of Contents

Lifting Bar - 3400 Spruce Street Phila

Below the Hook Devices: SER NO -  
180091 - 20D

|  High |  Med |  Low | Section |
|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------|
| 0                                                                                        | 0                                                                                       | 0                                                                                       | 1.0     |

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

# Overview

## Breakdown by Form

| Form Type   |  High |  Med |  Low | # Forms |
|-------------|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------|
| Lifting Bar | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |
| Overall:    | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |

## Breakdown by Location

| Location                 |  High |  Med |  Low | # Forms |
|--------------------------|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------|
| 3400 Spruce Street Phila | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |
| Overall:                 | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |

## Breakdown by Asset

| Asset Type             |  High |  Med |  Low | # Assets |
|------------------------|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|----------|
| Below the Hook Devices | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1        |
| Overall:               | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1        |



Tandem Lift LLC  
321 Enlow Place  
Pennsville, NJ 08070  
833-TANDEM1

**Lifting Bar**  
**Sautter Crane Rental**  
2900 Black Lake Place  
Philadelphia, PA 19154

FolderID: 07112620D  
FormID: 29904640



#### Below the Hook Devices

**Location:** 3400 Spruce Street Phila  
**Identifier:** SER NO - 180091  
**TagID:** 20D  
**Description:** Modular Spreader Beam

**Type:** Modular Spreader Beam  
**Capacity:** 30 Tons  
**Manufacturer:** Boscaro  
**Model Number:** EZBAR-30T  
**Length/Lift:** 7' 3"

Priorities Found: ● 12 - Good

#### General

- 1. Bar has no obvious bend, twist or deformation.

(SAT) Satisfactory

#### Manufacturer

- 2. Make

Boscaro

#### Manufacturer Model Number

- 3. Model

EZBAR-30T

#### Capacity

- 4. Rated Capacity of device

35 Tons

#### Tare Weight

- 5. Weight of device

185 lbs

#### Markings

- 6. The weight and capacity of the device are clearly and permanently displayed.

(Y) Yes

#### Corrosion

- 7. No visible corrosion that may effect the structural integrity of the device.

(SAT) Satisfactory

#### Rigging Connection Points

- 8. All possible points of connection do not have any visible cracks, deformation or excessive wear.

(SAT) Satisfactory

#### Adjustability

- 9. If the device is adjustable, Are all pins/fixtures secure and in proper working condition?

(Y) Yes



P9

 Safety pins must be installed on threaded pins before use

#### Name Of Inspector

- 10. Inspector

Anthony Capizzi

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

AG.

**Date Of Inspection**


- 11. Inspection performed on

07/11/2026

**Certificate**

- 12. Was a certificate issued?

(Y) Yes



P9.1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Prepared for:

## **Sautter Crane Rental**

2900 Black Lake Place Philadelphia, PA 19154

3400 Spruce Street Phila

on

7/11/2026

Please return the entire report.

**Customer Sign Off**

**-If there are no deficiencies nothing needs to be done**

**-If there are any (HIGH, RED) deficiencies please follow the instructions below**

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to [tony.rossi@tandemlift.com](mailto:tony.rossi@tandemlift.com) or [jon.santimaw@tandemlift.com](mailto:jon.santimaw@tandemlift.com). After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

---

Signature

---

Date

# Table of Contents

Lifting Bar - 3400 Spruce Street Phila

Below the Hook Devices: SER NO -  
180090 - 20E

|  High |  Med |  Low | Section |
|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------|
| 0                                                                                        | 0                                                                                       | 0                                                                                       | 1.0     |

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

# Overview

## Breakdown by Form

| Form Type   |  High |  Med |  Low | # Forms |
|-------------|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------|
| Lifting Bar | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |
| Overall:    | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |

## Breakdown by Location

| Location                 |  High |  Med |  Low | # Forms |
|--------------------------|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------|
| 3400 Spruce Street Phila | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |
| Overall:                 | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1       |

## Breakdown by Asset

| Asset Type             |  High |  Med |  Low | # Assets |
|------------------------|------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|----------|
| Below the Hook Devices | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1        |
| Overall:               | 0                                                                                        | 0                                                                                       | 0                                                                                       | 1        |

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Tandem Lift LLC  
321 Enlow Place  
Pennsville, NJ 08070  
833-TANDEM1

**Lifting Bar**  
**Sautter Crane Rental**  
2900 Black Lake Place  
Philadelphia, PA 19154

FolderID: 07112620E  
FormID: 29904644



#### Below the Hook Devices

**Location:** 3400 Spruce Street Phila  
**Identifier:** SER NO - 180090  
**TagID:** 20E  
**Description:** Modular Spreader Beam

**Type:** Modular Spreader Beam  
**Capacity:** 35 Tons  
**Manufacturer:** Boscaro  
**Model Number:** EZBAR-30T  
**Length/Lift:** 7' 3"

Priorities Found: ● 12 - Good

#### General

- 1. Bar has no obvious bend, twist or deformation. (SAT) Satisfactory

#### Manufacturer

- 2. Make Boscaro

#### Manufacturer Model Number

- 3. Model EZBAR-30T

#### Capacity

- 4. Rated Capacity of device 30 Tons

#### Tare Weight

- 5. Weight of device 185 lbs

#### Markings

- 6. The weight and capacity of the device are clearly and permanently displayed. (Y) Yes

#### Corrosion

- 7. No visible corrosion that may effect the structural integrity of the device. (SAT) Satisfactory

#### Rigging Connection Points

- 8. All possible points of connection do not have any visible cracks, deformation or excessive wear. (SAT) Satisfactory

#### Adjustability

- 9. If the device is adjustable, Are all pins/fixtures secure and in proper working condition? (Y) Yes P9

☛ Safety pins must be installed on threaded pins before use

#### Name Of Inspector

- 10. Inspector Anthony Capozzi

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

EG

**Date Of Inspection**


- 11. Inspection performed on

07/11/2026

**Certificate**

- 12. Was a certificate issued?

(Y) Yes



P9.1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.