



Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

Sautter Yard

on

6/1/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

Signature

Date

Table of Contents

● High ● Med ● Low Section

Inspection - *Sautter Yard*

Below the Hook Devices: *SER NO - 11517-03 - SP03*

0

0




0

1.0




Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview




Breakdown by Form

Form Type	 High	 Med	 Low	# Forms
Inspection	0	0	0	1
Overall:	0	0	0	1

Breakdown by Location

Location	 High	 Med	 Low	# Forms
Sautter Yard	0	0	0	1
Overall:	0	0	0	1

Breakdown by Asset

Asset Type	 High	 Med	 Low	# Assets
Below the Hook Devices	0	0	0	1
Overall:	0	0	0	1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Inspection

Sautter Crane Rental
 2900 Black Lake Place
 Philadelphia, PA 19154

FolderID: 060126SP03
 FormID: 29347400



Below the Hook Devices

Location: Sautter Yard
 2900 Black Lake Place
 Philadelphia, PA 19154

Identifier: SER NO - 11517-03

TagID: SP03

Description: Skip Pan

Type:	Skip Pan
Capacity:	6,000 lbs
Manufacturer:	Innovative
Model Number:	N/A
Length/Lift:	6'6" x 4'5"

Priorities Found: ● 7 - Good

General Criteria

- | | |
|---|-------------|
| ● 1. Checked for structural deformation, cracks, or excessive wear of any part of the lifter. | Pass |
| ● 2. Proper markings: Rated load, and name plates. | Pass |

Structural & Mechanical Devices

- | | |
|---|-------------|
| ● 3. Checked condition and operation of controls. | Pass |
| ● 4. Checked loose or missing guards, fasteners, covers, stops and name plates. | Pass |
| ● 5. Checked for loose bolts or fasteners. | Pass |
| ● 6. Checked for excessive wear of linkages and other mechanical parts. | Pass |
| ● 7. Checked for excessive wear at hoist hooking points and load support clevises, or pins. | Pass |