



Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

654 Berlin Crosskeys Rd

on

5/17/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

Signature

Date

Table of Contents




● High ● Med ● Low Section

Inspection - 654 Berlin Crosskeys Rd	Boom Truck Crane: 303864 - S442	0	0	0	1.0
--------------------------------------	---------------------------------	---	---	---	------------




Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview




Breakdown by Form

Form Type	 High	 Med	 Low	# Forms
Inspection	0	0	0	1
Overall:	0	0	0	1

Breakdown by Location

Location	 High	 Med	 Low	# Forms
654 Berlin Crosskeys Rd	0	0	0	1
Overall:	0	0	0	1

Breakdown by Asset

Asset Type	 High	 Med	 Low	# Assets
Boom Truck Crane	0	0	0	1
Overall:	0	0	0	1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Inspection
Sautter Crane Rental
 2900 Black Lake Place
 Philadelphia, PA 19154

FolderID: 051626S442
 FormID: 29122669



Boom Truck Crane
Completed by: Steve Edling on 05/16/2026
Location: 654 Berlin Crosskeys Rd
Serial #: 303864
TagID: S442
Status: In Service

Manufacturer: National
Model Number: NTC 45-2
Capacity: 45 Tons
Hook Type : Overhaul Ball & Hook
Length/Lift: 127'

Priorities Found: ● 108 - Good

Miles and Hours

1. Miles	9379.9 Miles
2. Hours	313.1 Hours

General

● 3. Guards / Covers	(SAT) Satisfactory	
● 4. External Lights	(SAT) Satisfactory	
● 5. Warning Decals	(SAT) Satisfactory	P5
● 6. Housekeeping	(SAT) Satisfactory	
● 7. Hand Signal Chart	(SAT) Satisfactory	P7

Historical Data

● 8. Monthly Inspection Records	(SAT) Satisfactory
● 9. Maintenance Records	(SAT) Satisfactory
● 10. Modification Records	(SAT) Satisfactory
● 11. Load Test Records	(SAT) Satisfactory


Driver's Cab

● 12. Glass	(SAT) Satisfactory
● 13. Windshield Wipers	(SAT) Satisfactory
● 14. Mirrors	(SAT) Satisfactory
● 15. Fire Extinguishers	(SAT) Satisfactory
● 16. Seat	(SAT) Satisfactory
● 17. Seat Belt	(SAT) Satisfactory
● 18. Power Take-Off	(SAT) Satisfactory
● 19. Parking Brake	(SAT) Satisfactory
● 20. Air Pressure	(SAT) Satisfactory
● 21. Instruments / Gauges	(SAT) Satisfactory
● 22. Switches / Functions	(SAT) Satisfactory

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 23. Horn	(SAT) Satisfactory	
● 24. Steering	(SAT) Satisfactory	
● 25. Engine Clutch	(NA) Not Applicable	
● 26. Accelerator	(SAT) Satisfactory	
● 27. Brake	(SAT) Satisfactory	
● 28. Defroster	(SAT) Satisfactory	
● 29. Operator's Manual	(SAT) Satisfactory	
Truck Power Plant		
● 30. Performance	(SAT) Satisfactory	
● 31. Exhaust System Guards & Insulators	(SAT) Satisfactory	
● 32. Belts / Hoses	(SAT) Satisfactory	
● 33. Moving Parts Guards & Covers	(SAT) Satisfactory	
Chassis		
● 34. Transmission	(SAT) Satisfactory	
● 35. Driveline	(SAT) Satisfactory	
● 36. Tires / Wheels	(SAT) Satisfactory	
● 37. Tire Air Pressure	(SAT) Satisfactory	
● 38. Chassis Frame Members	(SAT) Satisfactory	
● 39. Hydraulic Hoses / Tubing / Fittings	(SAT) Satisfactory	
● 40. Hydraulic Fluid Level	(SAT) Satisfactory	
● 41. Anti Skid Surface	(SAT) Satisfactory	
● 42. Guards / Covers	(SAT) Satisfactory	
● 43. Backup Alarm	(SAT) Satisfactory	
Outriggers / Stabilizers		
● 44. Boxes	(SAT) Satisfactory	P44
● 45. Beams	(SAT) Satisfactory	P45
● 46. Cylinders	(SAT) Satisfactory	
● 47. Floats / Pads	(SAT) Satisfactory	
● 48. Hydraulic Hoses / Tubes / Fittings	(SAT) Satisfactory	
● 49. Holding Valves	(SAT) Satisfactory	
● 50. Caution / Warning Signs	(SAT) Satisfactory	P50
Operators Station		
● 51. Grab Rails / Steps / Platforms	(SAT) Satisfactory	
● 52. Door Restraint	(SAT) Satisfactory	
● 53. Windows	(SAT) Satisfactory	
● 54. Anti Skid Surface	(SAT) Satisfactory	
● 55. Fire Extinguisher	(SAT) Satisfactory	
● 56. Electrocution Warning Sign	(SAT) Satisfactory	P56
● 57. Controls Identified	(SAT) Satisfactory	P57
● 58. Accelerator / Throttle Control	(SAT) Satisfactory	
● 59. Horn	(SAT) Satisfactory	
● 60. Seat	(SAT) Satisfactory	
Load Chart		
● 61. Per Configuration	(SAT) Satisfactory	
● 62. Durable	(SAT) Satisfactory	
● 63. Legible	(SAT) Satisfactory	
● 64. Secured	(SAT) Satisfactory	
● 65. Visible From Operators Station	(SAT) Satisfactory	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Safety Devices / Operational Aids		
● 66. Boom Angle Indicator	(SAT) Satisfactory	
● 67. Boom Length Indicator	(SAT) Satisfactory	
● 68. Drum Rotation Indicator	(SAT) Satisfactory	
● 69. Overload Protection	(SAT) Satisfactory	
● 70. Crane Level Indicator	(SAT) Satisfactory	
● 71. Anti Two-Block Device	(SAT) Satisfactory	
● 72. Outrigger / Stabilizer Position Sensor	(SAT) Satisfactory	
Upper Structure 		
● 73. Turntable	(SAT) Satisfactory	P73
● 74. Mounting	(SAT) Satisfactory	
● 75. Turret	(SAT) Satisfactory	
● 76. Hydraulic Pump(s)	(SAT) Satisfactory	
● 77. Hydraulic Hoses / Tubes / Fittings	(SAT) Satisfactory	
● 78. Hydraulic Pressure	(SAT) Satisfactory	
● 79. Electrical Wiring	(SAT) Satisfactory	
● 80. Hoist Brake	(SAT) Satisfactory	
● 81. Hoist - Motor / Valves / Lines	(SAT) Satisfactory	
● 82. Hoist Spooling	(SAT) Satisfactory	P82
● 83. Hoist - Minimum 2 Rope Wraps	(SAT) Satisfactory	
● 84. Swing Gear Box	(SAT) Satisfactory	
● 85. Electrocution Warning Sign	(SAT) Satisfactory	P85
Main Boom 		
● 86. Lift Cylinder(s)	(SAT) Satisfactory	
● 87. Telescoping Cylinder(s)	(SAT) Satisfactory	
● 88. Hydraulic Hoses / Tubes / Fittings	(SAT) Satisfactory	
● 89. Holding Device	(SAT) Satisfactory	
● 90. Boom Sections Alignment	(SAT) Satisfactory	P90
● 91. Wear Pads	(SAT) Satisfactory	
● 92. Sheave(s)	(SAT) Satisfactory	
● 93. Hoist Line Dead End	(SAT) Satisfactory	
● 94. Wire Rope Retainer	(SAT) Satisfactory	
● 95. Boom Hinge Pin	(SAT) Satisfactory	
● 96. Boom Head Section	(SAT) Satisfactory	P96
● 97. Structure	(SAT) Satisfactory	
Overhaul Ball & Hook 		
● 113. Capacity Marking	(SAT) Satisfactory	P113
● 114. Weight Marking	(SAT) Satisfactory	
● 115. Safety Latches	(SAT) Satisfactory	
● 116. 0° Hook Bend or Twist	(SAT) Satisfactory	
● 117. 5% Hook Opening or 1/4" Max	(SAT) Satisfactory	
● 118. 10% Hook Wear Max	(SAT) Satisfactory	
● 119. Swivel / Bearing	(SAT) Satisfactory	
● 120. Wedge Socket / End Fitting	(SAT) Satisfactory	P120
Wire Rope		
● 121. Rope Damage	(SAT) Satisfactory	
● 122. Measured Wear	(SAT) Satisfactory	
● 123. Broken Wires	(SAT) Satisfactory	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 124. Lubrication	(SAT) Satisfactory
● 125. End Connectors	(SAT) Satisfactory
Verification and Completion	
126. Inspector Name and Signature	Steven Edling
	
127. Date of Inspection	05/16/2026
128. Customer Name and Signature	
● 129. Certificate Issued	(Y) Yes P129



P45.1



P5.2



P7.3



P44.4



P45.5



P50.6



P50.7



P56.8




P57.9



P73.10



P82.11



P85.12

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



P90.13



P96.14



P113.15



P120.16



P129.17

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.