Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

Sautter Yard

on

10/4/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

_____ _____

Signature Date

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Table of Contents

		High	Med	Low	Section
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400) - *Sautter Yard*	Telescoping Boom Crane*: 302763 - S365*	0	0	0	**1.0**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview

Breakdown by Form

Form Type	High	Med	Low	# Forms
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Breakdown by Location

Location	High	Med	Low	# Forms
Sautter Yard	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Breakdown by Asset

Asset Type	High	Med	Low	# Assets
Telescoping Boom Crane	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)

FolderID: 100326S365
FormID: 31078959

Sautter Crane Rental
2900 Black Lake Place
Philadelphia, PA 19154



Telescoping Boom Crane

Completed by: Steve Edling on 10/03/2026

Location:	Sautter Yard 2900 Black Lake Place Philadelphia, PA 19154
Serial Number:	302763
Unit Number:	S365
Status:	In Service

Manufacturer:	National
Model:	800D
Capacity:	23 Tons
Length/Lift:	100'
Type of Crane:	Boom Truck
Number of Hoists:	Main Only
Boom Configuration:	Main Boom w/o Attached Jib
Load Test:	No

Priorities Found: **89 - Good**

General

1.	Location of Equipment	**sautter yard**
2.	Customer Sign Off	
3.	Hours & Mileage	

Hours	Mileage
3854.9	**78,367.0**

Inspection Information

4.	Inspection Number	**100326S365**
5.	Inspection Date	**10/03/2026**
6.	Inspection Type	**(Ann) Annual**

Information & Records

7.	Documentation of Annual/Comprehensive Inspection	**(SAT) Satisfactory**	
8.	Daily/Monthly Inspection Records	**(SAT) Satisfactory**	
9.	Maintenance Records	**(SAT) Satisfactory**	
10.	Hand Signal Chart	**(SAT) Satisfactory**	P10
11.	Safety and Warning Decals	**(SAT) Satisfactory**	P11
12.	Operators Manual	**(SAT) Satisfactory**	
13.	Equipment Modification(s) or Additions	**(SAT) Satisfactory**	

Safety Devices & Operational Aids

14.	Backup Alarm	**(SAT) Satisfactory**	
15.	Audible Warning Device	**(SAT) Satisfactory**	
16.	Boom Angle Indicator	**(SAT) Satisfactory**	P16
17.	Boom Length Indicator	**(SAT) Satisfactory**	
18.	Drum Rotation Indicator(s)	**(NA) Not Applicable**	
19.	Anti Two-Block Device/System	**(SAT) Satisfactory**	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

20.	Load Moment Indicator (LMI)	**(SAT) Satisfactory**	P20
21.	Load Weight Indicator	**(SAT) Satisfactory**	
22.	Radius Indicator	**(SAT) Satisfactory**	
23.	Level Indicator(s)	**(SAT) Satisfactory**	
24.	Fire Extinguisher	**(SAT) Satisfactory**	
Load Chart			
25.	Visible/Accessible	**(SAT) Satisfactory**	
26.	Per Configuration	**(SAT) Satisfactory**	
27.	Durable/Legible/Secured	**(SAT) Satisfactory**	
Chassis			
28.	Windshield & Wipers	**(SAT) Satisfactory**	
29.	Windows & Mirrors	**(SAT) Satisfactory**	
30.	PTO/Hydraulic Pump	**(SAT) Satisfactory**	
31.	Hoses/Fittings/Valves	**(SAT) Satisfactory**	
32.	Brakes	**(SAT) Satisfactory**	
33.	Engine/Drivetrain	**(SAT) Satisfactory**	
34.	Exterior Lights (Head Lights, Turn Signals, Brake Lights, Reverse Lights)	**(SAT) Satisfactory**	
35.	Air Pressure	**(SAT) Satisfactory**	
36.	Instruments & Gauges	**(SAT) Satisfactory**	
37.	Steering	**(SAT) Satisfactory**	
38.	Brakes/Parking Brake	**(SAT) Satisfactory**	
39.	Driveline	**(SAT) Satisfactory**	
40.	Wheels & Tires	**(SAT) Satisfactory**	
41.	Chassis Frame Members	**(SAT) Satisfactory**	
42.	Hydraulic Tank & Fluid Level	**(SAT) Satisfactory**	
43.	Guards & Covers	**(SAT) Satisfactory**	
44.	Engine	**(SAT) Satisfactory**	
45.	Exhaust System/Guards/Insulators	**(SAT) Satisfactory**	
Carrier			
46.	Axle Lockout	**(SAT) Satisfactory**	
Outriggers/Stabilizers			
47.	Structure & Mounting	**(SAT) Satisfactory**	P47
48.	Boxes & Beams	**(SAT) Satisfactory**	
49.	Cylinders	**(SAT) Satisfactory**	
50.	Pads/Floats	**(SAT) Satisfactory**	
51.	Hoses/Fittings/Valves	**(SAT) Satisfactory**	
Operators Station			
52.	Fire Extinguisher	**(SAT) Satisfactory**	
53.	Operator Horn	**(SAT) Satisfactory**	
54.	Controls Identified	**(SAT) Satisfactory**	
55.	Control Functions	**(SAT) Satisfactory**	
56.	Operator Cutoff Switch (Deadman)	**(SAT) Satisfactory**	
57.	Accelerator/Throttle Control	**(SAT) Satisfactory**	
58.	Hoses/Fittings/Valves	**(SAT) Satisfactory**	
59.	Housekeeping	**(SAT) Satisfactory**	
Upper Structure			
60.	Turntable	**(SAT) Satisfactory**	
61.	Mounting	**(SAT) Satisfactory**	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

62.	Turret	**(SAT) Satisfactory**	
63.	Hydraulic Pump(s)	**(SAT) Satisfactory**	
64.	Hoses/Fittings/Valves	**(SAT) Satisfactory**	
65.	Electrical Wiring	**(SAT) Satisfactory**	
66.	Hoist Brake	**(SAT) Satisfactory**	
67.	Hoist Motor	**(SAT) Satisfactory**	
68.	Hoist Spooling	**(SAT) Satisfactory**	P68
69.	Hoist-Minimum 2 Rope Wraps	**(SAT) Satisfactory**	
70.	Swing Gearbox	**(SAT) Satisfactory**	

Main Boom

71.	Lift Cylinder(s)	**(SAT) Satisfactory**	
72.	Telescoping Boom Cylinder(s)	**(SAT) Satisfactory**	
73.	Hoses/Fittings/Valves	**(SAT) Satisfactory**	
74.	Holding Device	**(SAT) Satisfactory**	
75.	Boom Sections Alignment	**(SAT) Satisfactory**	P75
76.	Wear Pads	**(SAT) Satisfactory**	
77.	Sheaves	**(SAT) Satisfactory**	
78.	Wire Rope Retainers	**(SAT) Satisfactory**	
79.	Boom Hinge Pin	**(SAT) Satisfactory**	
80.	Boom Head Section	**(SAT) Satisfactory**	P80
81.	Structure	**(SAT) Satisfactory**	

Main Drum Wire Rope

82. Wire Rope Information

Diameter	Construction/Type	Number of Parts
9/16 inch	**non rotation**	**2**

83.	Rope Damage	**(SAT) Satisfactory**	
84.	Lubrication	**(SAT) Satisfactory**	
85.	End Connectors	**(SAT) Satisfactory**	

Main Hoist Load Block/Headache Ball/Hook

86. Capacity and Weight

Capacity	Weight
12.5 tons	**310 lbs**

87.	Capacity Marking	**(SAT) Satisfactory**	P87
88.	Weight Marking	**(SAT) Satisfactory**	
89.	Sheave(s)	**(SAT) Satisfactory**	P89
90.	Safety Latch(es)	**(SAT) Satisfactory**	
91.	0° Hook Bend/Twist	**(SAT) Satisfactory**	
92.	5% Hook Opening or 1/4" Max	**(SAT) Satisfactory**	
93.	10% Hook Wear Max	**(SAT) Satisfactory**	
94.	Bearing	**(SAT) Satisfactory**	
95.	Wedge Socket/End Fitting	**(SAT) Satisfactory**	
96.	Reeving	**(SAT) Satisfactory**	

Verification and Completion

97. Inspector Name & Signature **Steven Edling**



Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

	98.	Additional Inspection Notes	
●	99.	Sticker Given	**(Y) Yes, Given on Site** P99



P10.1



P11.2



P16.3



P20.4



P47.5



P68.6



P75.7



P80.8



P87.9



P89.10



P99.11

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.