Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

Sautter Yard

on

10/4/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

_____ _____

Signature Date

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Table of Contents

		High	Med	Low	Section
Inspection - *Sautter Yard*	Boom Truck Crane: *1T914792VDW140744 - S186*	0	0	0	**1.0**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview

Breakdown by Form

Form Type	High	Med	Low	# Forms
Inspection	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Breakdown by Location

Location	High	Med	Low	# Forms
Sautter Yard	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Breakdown by Asset

Asset Type	High	Med	Low	# Assets
Boom Truck Crane	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Inspection

Sautter Crane Rental
2900 Black Lake Place
Philadelphia, PA 19154

FolderID: 100326S186
FormID: 31078148



Boom Truck Crane

Completed by: Steve Edling on 10/03/2026

Location:	Sautter Yard 2900 Black Lake Place Philadelphia, PA 19154
Serial #:	1T914792VDW140744
TagID:	S186
Status:	In Service

Manufacturer:	Terex
Model Number:	BT4792
Capacity:	23 1/2 Tons
Hook Type :	Load Block & Hook
Length/Lift:	92 ft.

Priorities Found: **105 - Good**

Miles and Hours			
	1.	Miles	**88,485.1 Miles**
	2.	Hours	**3928.8 Hours**
General			
●	3.	Guards / Covers	**(SAT) Satisfactory**
●	4.	External Lights	**(SAT) Satisfactory**
●	5.	Warning Decals	**(SAT) Satisfactory** P5
●	6.	Housekeeping	**(SAT) Satisfactory**
●	7.	Hand Signal Chart	**(SAT) Satisfactory** P7
Historical Data			
●	8.	Monthly Inspection Records	**(SAT) Satisfactory**
●	9.	Maintenance Records	**(SAT) Satisfactory**
●	10.	Modification Records	**(SAT) Satisfactory**
○	11.	Load Test Records	**(NA) Not Applicable**
Driver's Cab			
●	12.	Glass	**(SAT) Satisfactory**
●	13.	Windshield Wipers	**(SAT) Satisfactory**
●	14.	Mirrors	**(SAT) Satisfactory**
●	15.	Fire Extinguishers	**(SAT) Satisfactory**
●	16.	Seat	**(SAT) Satisfactory**
●	17.	Seat Belt	**(SAT) Satisfactory**
●	18.	Power Take-Off	**(SAT) Satisfactory**
●	19.	Parking Brake	**(SAT) Satisfactory**
●	20.	Air Pressure	**(SAT) Satisfactory**
●	21.	Instruments / Gauges	**(SAT) Satisfactory**
●	22.	Switches / Functions	**(SAT) Satisfactory**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

23.	Horn	**(SAT) Satisfactory**	
24.	Steering	**(SAT) Satisfactory**	
25.	Engine Clutch	**(NA) Not Applicable**	
26.	Accelerator	**(SAT) Satisfactory**	
27.	Brake	**(SAT) Satisfactory**	
28.	Defroster	**(SAT) Satisfactory**	
29.	Operator's Manual	**(SAT) Satisfactory**	
Truck Power Plant			
30.	Performance	**(SAT) Satisfactory**	
31.	Exhaust System Guards & Insulators	**(SAT) Satisfactory**	
32.	Belts / Hoses	**(SAT) Satisfactory**	
33.	Moving Parts Guards & Covers	**(SAT) Satisfactory**	
Chassis			
34.	Transmission	**(SAT) Satisfactory**	
35.	Driveline	**(SAT) Satisfactory**	
36.	Tires / Wheels	**(SAT) Satisfactory**	
37.	Tire Air Pressure	**(SAT) Satisfactory**	
38.	Chassis Frame Members	**(SAT) Satisfactory**	
39.	Hydraulic Hoses / Tubing / Fittings	**(SAT) Satisfactory**	
40.	Hydraulic Fluid Level	**(SAT) Satisfactory**	
41.	Anti Skid Surface	**(SAT) Satisfactory**	
42.	Guards / Covers	**(SAT) Satisfactory**	
43.	Backup Alarm	**(SAT) Satisfactory**	
Outriggers / Stabilizers			
44.	Boxes	**(SAT) Satisfactory**	
45.	Beams	**(SAT) Satisfactory**	
46.	Cylinders	**(SAT) Satisfactory**	
47.	Floats / Pads	**(SAT) Satisfactory**	P47
48.	Hydraulic Hoses / Tubes / Fittings	**(SAT) Satisfactory**	
49.	Holding Valves	**(SAT) Satisfactory**	
50.	Caution / Warning Signs	**(SAT) Satisfactory**	P50
Operators Station			
51.	Grab Rails / Steps / Platforms	**(SAT) Satisfactory**	
52.	Door Restraint	**(NA) Not Applicable**	
53.	Windows	**(NA) Not Applicable**	
54.	Anti Skid Surface	**(SAT) Satisfactory**	
55.	Fire Extinguisher	**(SAT) Satisfactory**	P55
56.	Electrocution Warning Sign	**(SAT) Satisfactory**	
57.	Controls Identified	**(SAT) Satisfactory**	
58.	Accelerator / Throttle Control	**(SAT) Satisfactory**	
59.	Horn	**(SAT) Satisfactory**	
60.	Seat	**(NA) Not Applicable**	
Load Chart			
61.	Per Configuration	**(SAT) Satisfactory**	P61
62.	Durable	**(SAT) Satisfactory**	
63.	Legible	**(SAT) Satisfactory**	
64.	Secured	**(SAT) Satisfactory**	
65.	Visible From Operators Station	**(SAT) Satisfactory**	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Safety Devices / Operational Aids			
●	66. Boom Angle Indicator	**(SAT) Satisfactory**	P66
●	67. Boom Length Indicator	**(SAT) Satisfactory**	
○	68. Drum Rotation Indicator	**(NA) Not Applicable**	
●	69. Overload Protection	**(SAT) Satisfactory**	
●	70. Crane Level Indicator	**(SAT) Satisfactory**	P70
●	71. Anti Two-Block Device	**(SAT) Satisfactory**	
●	72. Outrigger / Stabilizer Position Sensor	**(SAT) Satisfactory**	
Upper Structure			
●	73. Turntable	**(SAT) Satisfactory**	
●	74. Mounting	**(SAT) Satisfactory**	
●	75. Turret	**(SAT) Satisfactory**	
●	76. Hydraulic Pump(s)	**(SAT) Satisfactory**	
●	77. Hydraulic Hoses / Tubes / Fittings	**(SAT) Satisfactory**	
●	78. Hydraulic Pressure	**(SAT) Satisfactory**	
●	79. Electrical Wiring	**(SAT) Satisfactory**	
●	80. Hoist Brake	**(SAT) Satisfactory**	
●	81. Hoist - Motor / Valves / Lines	**(SAT) Satisfactory**	
●	82. Hoist Spooling	**(SAT) Satisfactory**	
●	83. Hoist - Minimum 2 Rope Wraps	**(SAT) Satisfactory**	
●	84. Swing Gear Box	**(SAT) Satisfactory**	
●	85. Electrocution Warning Sign	**(SAT) Satisfactory**	
Main Boom			
●	86. Lift Cylinder(s)	**(SAT) Satisfactory**	
●	87. Telescoping Cylinder(s)	**(SAT) Satisfactory**	
●	88. Hydraulic Hoses / Tubes / Fittings	**(SAT) Satisfactory**	
●	89. Holding Device	**(SAT) Satisfactory**	
●	90. Boom Sections Alignment	**(SAT) Satisfactory**	P90
●	91. Wear Pads	**(SAT) Satisfactory**	
●	92. Sheave(s)	**(SAT) Satisfactory**	
●	93. Hoist Line Dead End	**(SAT) Satisfactory**	
●	94. Wire Rope Retainer	**(SAT) Satisfactory**	
●	95. Boom Hinge Pin	**(SAT) Satisfactory**	
●	96. Boom Head Section	**(SAT) Satisfactory**	P96
●	97. Structure	**(SAT) Satisfactory**	
Load Block & Hook			
●	103. Capacity Marking	**(SAT) Satisfactory**	P103
●	104. Weight Marking	**(SAT) Satisfactory**	
●	105. Sheave(s)	**(SAT) Satisfactory**	
●	106. Safety Latche(s)	**(SAT) Satisfactory**	P106
●	107. 0° Hook Bend or Twist	**(SAT) Satisfactory**	
●	108. 5% Hook Opening or 1/4" Max	**(SAT) Satisfactory**	
●	109. 10% Hook Wear Max	**(SAT) Satisfactory**	
●	110. Bearing	**(SAT) Satisfactory**	
●	111. Wedge Socket / End Fitting	**(SAT) Satisfactory**	
●	112. Reeving	**(SAT) Satisfactory**	
Wire Rope			
●	121. Rope Damage	**(SAT) Satisfactory**	

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

122.	Measured Wear	**(SAT) Satisfactory**	
123.	Broken Wires	**(SAT) Satisfactory**	
124.	Lubrication	**(SAT) Satisfactory**	
125.	End Connectors	**(SAT) Satisfactory**	P125

Verification and Completion

126.	Inspector Name and Signature	**Steven Edling**	



127.	Date of Inspection	**10/03/2026**	
128.	Customer Name and Signature		
129.	Certificate Issued	**(Y) Yes**	P129



P5.1



P7.2



P47.3



P50.4



P55.5



P61.6



P66.7



P70.8



P90.9



P96.10



P103.11



P106.12

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



P125.13



P129.14

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.