



Below the Hook Lifting Devices
 Sautter Crane Rental

FolderID: 11974
 FormID: 16400321



Below the Hook Devices
 Completed by: **Matt Hottenstein on 04/03/2023**
 Location: USA
 Serial Number: 15-38930-2
 Unit #: SB-11

Type:	Lifting Beam (B30.20)
Manufacturer:	Caldwell
Capacity:	20 tons
Net Weight:	540 lbs
Rigging Attached :	Yes
Work Performed:	Inspection

Priorities Found: ● 10 - Good

Location of Equipment

1. Location of Equipment **Philadelphia PA Yard**

Customer Sign Off

2. Customer Sign Off

IF THERE ARE NO DEFICIENCIES NOTHING NEEDS TO BE DONE.

IF THERE ARE ANY HIGH, RED, DEFICIENCIES PLEASE FOLLOW THE BELOW INSTRUCTIONS

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS PAGE ONLY to either jaime@atlanticcrane.com or gina@atlanticcrane.com or fax THIS PAGE ONLY to our office at 215-639-2316 and a certification and sticker will be issued. The above deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However, those items should be corrected to improve equipment reliability and safety.

The undersigned verifies the listed deficiencies denoted with an (DEF, HIGH, RED) have been corrected.

 Signature

 Date

Inspection Information

3. Inspection Number	23040308MH
4. Inspection Date	04/03/2023
● 5. Inspection Type	(Ann) Annual


Lifting Equipment

6. Lifting Equipment Description	Adjustable Lifting Beam
7. Lifting Equipment Dimensions	8 ft -14 ft
● 8. Identification Marking	(SAT) Satisfactory
● 9. Weight & Capacity marking	(SAT) Satisfactory
● 10. Manufacturer Plate	(SAT) Satisfactory
● 11. Structure	(SAT) Satisfactory
● 12. Welds	(SAT) Satisfactory
● 13. Lifting Eyes	(SAT) Satisfactory
● 14. Locking Pins/Keeper Pins	(SAT) Satisfactory

Rigging



Atlantic Crane Inspection Services disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Atlantic Crane Inspection Services. Atlantic Crane Inspection Services shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

15. Wire Rope Information			P15
Size	Overall Capacity	Number of Legs	
1 1/8"	21 ton	2	
● 16. Wire Rope Condition	(SAT) Satisfactory		
17. Ring Link Information			
Size	Capacity		
● 18. Ring Link Condition	(SAT) Satisfactory		
Verification and Completion			
19. Inspector Name & Signature			
			
20. Additional Inspection Notes			
<i>No visible deficiencies found at time of inspection</i>			



P15.1



P15.2