



Below the Hook Lifting Devices
Sautter Crane Rental

FolderID: 12150
FormID: 16775470



Below the Hook Devices

Completed by: Billy Ciavaglia on 05/11/2023

Location: USA

Serial Number: J7310

Unit #: 11

Type: Material Basket (B30.20)

Manufacturer: Lakeshore

Model Number: M44

Capacity: 1000 lbs

Net Weight: 550

Rigging Attached : Yes

Work Performed: Inspection

Priorities Found: ● 9 - Good

Location of Equipment

1. Location of Equipment **Philly yard**

Customer Sign Off

2. Customer Sign Off

IF THERE ARE NO DEFICIENCIES NOTHING NEEDS TO BE DONE.

IF THERE ARE ANY HIGH, RED, DEFICIENCIES PLEASE FOLLOW THE BELOW INSTRUCTIONS

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS PAGE ONLY to either jaime@atlanticcrane.com or gina@atlanticcrane.com or fax THIS PAGE ONLY to our office at 215-639-2316 and a certification and sticker will be issued. The above deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However, those items should be corrected to improve equipment reliability and safety.

The undersigned verifies the listed deficiencies denoted with an (DEF, HIGH, RED) have been corrected.

Signature

Date

Inspection Information

3. Inspection Number **23051103bc**

4. Inspection Date **05/11/2023**

● 5. Inspection Type **(Ann) Annual**

Material Basket

● 6. Rating Plate **(SAT) Satisfactory**

● 7. Edge & Surfaces **(SAT) Satisfactory**

● 8. Welds **(SAT) Satisfactory**

● 9. Attachment Points/Lifting Eyes **(SAT) Satisfactory**


Rigging

10. Wire Rope Information

Size	Overall Capacity	Number of Legs
1/2"	8.8ton @60degrees	4+1

● 11. Wire Rope Condition **(SAT) Satisfactory**

Atlantic Crane Inspection Services disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Atlantic Crane Inspection Services. Atlantic Crane Inspection Services shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

12. Shackle Information		
Size	Capacity	Number of Shackles
5/8"	3-1/4ton	4
● 13. Shackle Condition	(SAT) Satisfactory	
14. Ring Link Information		
Size	Capacity	
na		
● 15. Ring Link Condition	(SAT) Satisfactory	
Verification and Completion		
16. Inspector Name & Signature	Bill Ciavaglia	
		
17. Additional Inspection Notes		
● 18. Sticker Given	(Y) Yes, Given on Site	

Atlantic Crane Inspection Services disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Atlantic Crane Inspection Services. Atlantic Crane Inspection Services shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.