



Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

Sautter Yard

on

12/14/2025

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

Signature

Date

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Table of Contents

 High  Med  Low Section

Inspection - Sautter Yard

Boom Truck Crane:
1T914792EDW140748 - S189

0 0 0 **1.0**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview

Breakdown by Form

Form Type	High	Med	Low	# Forms
Inspection	0	0	0	1
Overall:	0	0	0	1

Breakdown by Location

Location	High	Med	Low	# Forms
Sautter Yard	0	0	0	1
Overall:	0	0	0	1

Breakdown by Asset

Asset Type	High	Med	Low	# Assets
Boom Truck Crane	0	0	0	1
Overall:	0	0	0	1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Inspection

Sautter Crane Rental
2900 Black Lake Place
Philadelphia, PA 19154

FolderID: 121325S189
FormID: 26971820



Boom Truck Crane

Location: Sautter Yard
2900 Black Lake Place
Philadelphia, PA 19154
Serial #: 1T9I4792EDW140748
TagID: S189
Status: In Service

Manufacturer: Terex
Model Number: BT4792
Capacity: 23 1/2 Ton
Hook Type : Load Block & Hook
Length/Lift: 92'

*Additional Notes: 92 ft boom
2 parts of line
Can't inspect extend and retract cables without
disassembling boom*

Priorities Found: ● 106 - Good

Miles and Hours

● 1. Miles	103,253 Miles
● 2. Hours	2662 Hours

General

● 3. Guards / Covers	(SAT) Satisfactory
● 4. External Lights	(SAT) Satisfactory
● 5. Warning Decals	(SAT) Satisfactory
● 6. Housekeeping	(SAT) Satisfactory
● 7. Hand Signal Chart	(SAT) Satisfactory

Historical Data

● 8. Monthly Inspection Records	(SAT) Satisfactory
● 9. Maintenance Records	(SAT) Satisfactory

Driver's Cab

● 10. Glass	(SAT) Satisfactory
● 11. Windshield Wipers	(SAT) Satisfactory
● 12. Mirrors	(SAT) Satisfactory
● 13. Fire Extinguishers	(SAT) Satisfactory
● 14. Seat	(SAT) Satisfactory
● 15. Seat Belt	(SAT) Satisfactory
● 16. Power Take-Off	(SAT) Satisfactory
● 17. Parking Brake	(SAT) Satisfactory
● 18. Air Pressure	(SAT) Satisfactory
● 19. Instruments / Gauges	(SAT) Satisfactory
● 20. Switches / Functions	(SAT) Satisfactory

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 21. Horn	(SAT) Satisfactory
● 22. Steering	(SAT) Satisfactory
● 23. Engine Clutch	(NA) Not Applicable
● 24. Accelerator	(SAT) Satisfactory
● 25. Brake	(SAT) Satisfactory
● 26. Defroster	(SAT) Satisfactory
● 27. Operator's Manual	(SAT) Satisfactory

Truck Power Plant

● 28. Performance	(SAT) Satisfactory
● 29. Exhaust System Guards & Insulators	(SAT) Satisfactory
● 30. Belts / Hoses	(SAT) Satisfactory
● 31. Moving Parts Guards & Covers	(SAT) Satisfactory

Chassis

● 32. Transmission	(SAT) Satisfactory
● 33. Driveline	(SAT) Satisfactory
● 34. Tires / Wheels	(SAT) Satisfactory
● 35. Tire Air Pressure	(SAT) Satisfactory
● 36. Chassis Frame Members	(SAT) Satisfactory
● 37. Hydraulic Hoses / Tubing / Fittings	(SAT) Satisfactory
● 38. Hydraulic Fluid Level	(SAT) Satisfactory
● 39. Anti Skid Surface	(SAT) Satisfactory
● 40. Guards / Covers	(SAT) Satisfactory
● 41. Backup Alarm	(SAT) Satisfactory

Outriggers / Stabilizers

● 42. Boxes	(SAT) Satisfactory
● 43. Beams	(SAT) Satisfactory
● 44. Cylinders	(SAT) Satisfactory
● 45. Floats / Pads	(SAT) Satisfactory
● 46. Hydraulic Hoses / Tubes / Fittings	(SAT) Satisfactory
● 47. Holding Valves	(SAT) Satisfactory
● 48. Caution / Warning Signs	(SAT) Satisfactory

Operators Station

● 49. Grab Rails / Steps / Platforms	(SAT) Satisfactory
● 50. Door Restraint	(NA) Not Applicable
● 51. Windows	(NA) Not Applicable
● 52. Anti Skid Surface	(SAT) Satisfactory
● 53. Fire Extinguisher	(NA) Not Applicable
● 54. Electrocution Warning Sign	(SAT) Satisfactory
● 55. Controls Identified	(SAT) Satisfactory
● 56. Accelerator / Throttle Control	(SAT) Satisfactory
● 57. Horn	(SAT) Satisfactory
● 58. Seat	(NA) Not Applicable

Load Chart

● 59. Per Configuration	(SAT) Satisfactory
● 60. Durable	(SAT) Satisfactory
● 61. Legible	(SAT) Satisfactory
● 62. Secured	(SAT) Satisfactory
● 63. Visible From Operators Station	(SAT) Satisfactory

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Safety Devices / Operational Aids

64. Boom Angle Indicator	(SAT) Satisfactory
65. Boom Length Indicator	(SAT) Satisfactory
66. Drum Rotation Indicator	(NA) Not Applicable
67. Overload Protection	(SAT) Satisfactory
68. Crane Level Indicator	(SAT) Satisfactory
69. Anti Two-Block Device	(SAT) Satisfactory
70. Outrigger / Stabilizer Position Sensor	(SAT) Satisfactory

Upper Structure

71. Turntable	(SAT) Satisfactory
72. Mounting	(SAT) Satisfactory
73. Turret	(SAT) Satisfactory
74. Hydraulic Pump(s)	(NA) Not Applicable
75. Hydraulic Hoses / Tubes / Fittings	(SAT) Satisfactory
76. Hydraulic Pressure	(SAT) Satisfactory
77. Electrical Wiring	(SAT) Satisfactory
78. Hoist Brake	(SAT) Satisfactory
79. Hoist - Motor / Valves / Lines	(SAT) Satisfactory
80. Hoist Spooling	(SAT) Satisfactory
81. Hoist - Minimum 2 Rope Wraps	(SAT) Satisfactory
82. Swing Gear Box	(SAT) Satisfactory
83. Electrocution Warning Sign	(SAT) Satisfactory

Main Boom

84. Lift Cylinder(s)	(SAT) Satisfactory
85. Telescoping Cylinder(s)	(SAT) Satisfactory
86. Hydraulic Hoses / Tubes / Fittings	(SAT) Satisfactory
87. Holding Device	(SAT) Satisfactory
88. Boom Sections Alignment	(SAT) Satisfactory
89. Wear Pads	(SAT) Satisfactory
90. Sheave(s)	(SAT) Satisfactory
91. Hoist Line Dead End	(SAT) Satisfactory
92. Wire Rope Retainer	(SAT) Satisfactory
93. Boom Hinge Pin	(SAT) Satisfactory
94. Boom Head Section	(SAT) Satisfactory
95. Structure	(SAT) Satisfactory

Load Block & Hook

96. Capacity Marking	(SAT) Satisfactory
97. Weight Marking	(SAT) Satisfactory
98. Sheave(s)	(SAT) Satisfactory
99. Safety Latche(s)	(SAT) Satisfactory
100. 0° Hook Bend or Twist	(SAT) Satisfactory
101. 5% Hook Opening or 1/4" Max	(SAT) Satisfactory
102. 10% Hook Wear Max	(SAT) Satisfactory
103. Bearing	(SAT) Satisfactory
104. Wedge Socket / End Fitting	(SAT) Satisfactory
105. Reeving	(SAT) Satisfactory

2 parts of line

Wire Rope

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 106. Rope Damage	(SAT) Satisfactory
● 107. Measured Wear 5/8 inch cable <i>Actual - .566 inch</i>	(SAT) Satisfactory
● 108. Broken Wires	(SAT) Satisfactory
● 109. Lubrication	(SAT) Satisfactory
● 110. End Connectors	(SAT) Satisfactory

Verification and Completion

● 111. Inspector Name and Signature	Anthony Capozzi
	
● 112. Date of Inspection	12/13/2025
113. Customer Name and Signature	
● 114. Certificate Issued	(Y) Yes

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.