



Prepared for:

Sautter Crane rental

2900 Black Lake Place Philadelphia, PA 19154

on

10/5/2025

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

Signature

Date

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Table of Contents

Inspection - Sautter Yard

Boom Truck Crane: 301395 - S283

 High  Med  Low Section

0 1 2 **1.0**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview

Breakdown by Form

Form Type	High	Med	Low	# Forms
Inspection	0	1	2	1
Overall:	0	1	2	1

Breakdown by Location

Location	High	Med	Low	# Forms
Sautter Yard	0	1	2	1
Overall:	0	1	2	1

Breakdown by Asset

Asset Type	High	Med	Low	# Assets
Boom Truck Crane	0	1	2	1
Overall:	0	1	2	1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Inspection

Sautter Crane rental
2900 Black Lake Place
Philadelphia, PA 19154

FolderID: 100425S283
FormID: 26111704



Boom Truck Crane

Completed by: Christopher Volz on 10/04/2025

Location: Sautter Yard
2900 Black Lake Place
Philadelphia, PA 19154
Serial #: 301395
TagID: S283
Status: In Service

Manufacturer: National
Model Number: 800D
Capacity: 23 Tons
Hook Type : Load Block & Hook
Length/Lift: 100 ft.

Priorities Found: ● 1 - Medium ● 2 - Low ● 98 - Good

Miles and Hours

1. Miles	144399 Miles
2. Hours	7361 Hours

General

● 3. Guards / Covers	(SAT) Satisfactory
● 4. External Lights	(SAT) Satisfactory
● 5. Warning Decals	(SAT) Satisfactory
● 6. Housekeeping	(SAT) Satisfactory
● 7. Hand Signal Chart	(SAT) Satisfactory

Driver's Cab

● 12. Glass	(SAT) Satisfactory
● 13. Windshield Wipers	(SAT) Satisfactory
● 14. Mirrors	(SAT) Satisfactory
● 15. Fire Extinguishers	(SAT) Satisfactory
● 16. Seat	(SAT) Satisfactory
● 17. Seat Belt	(SAT) Satisfactory
● 18. Power Take-Off	(SAT) Satisfactory
● 19. Parking Brake	(SAT) Satisfactory
● 20. Air Pressure	(SAT) Satisfactory
● 21. Instruments / Gauges	(SAT) Satisfactory
● 22. Switches / Functions	(SAT) Satisfactory
● 23. Horn	(SAT) Satisfactory
● 24. Steering	(SAT) Satisfactory
● 25. Engine Clutch	(NA) Not Applicable
● 26. Accelerator	(SAT) Satisfactory
● 27. Brake	(SAT) Satisfactory

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 28. Defroster	(SAT) Satisfactory
● 29. Operator's Manual	(SAT) Satisfactory
Truck Power Plant	
● 30. Performance	(SAT) Satisfactory
● 31. Exhaust System Guards & Insulators	(SAT) Satisfactory
● 32. Belts / Hoses	(SAT) Satisfactory
● 33. Moving Parts Guards & Covers	(SAT) Satisfactory
Chassis	
● 34. Transmission	(SAT) Satisfactory
● 35. Driveline	(SAT) Satisfactory
● 36. Tires / Wheels	(SAT) Satisfactory
● 37. Tire Air Pressure	(SAT) Satisfactory
● 38. Chassis Frame Members	(SAT) Satisfactory
● 39. Hydraulic Hoses / Tubing / Fittings	(SAT) Satisfactory
● 40. Hydraulic Fluid Level	(SAT) Satisfactory
● 41. Anti Skid Surface	(SAT) Satisfactory
● 42. Guards / Covers	(SAT) Satisfactory
● 43. Backup Alarm	(SAT) Satisfactory
Outriggers / Stabilizers	
● 44. Boxes	(SAT) Satisfactory
● 45. Beams	(SAT) Satisfactory
● 46. Cylinders	(SAT) Satisfactory
● 47. Floats / Pads	(SAT) Satisfactory
● 48. Hydraulic Hoses / Tubes / Fittings	(SAT) Satisfactory
● 49. Holding Valves	(SAT) Satisfactory
● 50. Caution / Warning Signs	(SAT) Satisfactory
Operators Station	
● 51. Grab Rails / Steps / Platforms	(SAT) Satisfactory
● 52. Door Restraint	(NA) Not Applicable
● 53. Windows	(NA) Not Applicable
● 54. Anti Skid Surface	(SAT) Satisfactory
● 55. Fire Extinguisher	(NA) Not Applicable
● 56. Electrocution Warning Sign	(SAT) Satisfactory
● 57. Controls Identified	(SAT) Satisfactory
● 58. Accelerator / Throttle Control	(SAT) Satisfactory
● 59. Horn	(SAT) Satisfactory
● 60. Seat	(NA) Not Applicable
Load Chart	
● 61. Per Configuration	(SAT) Satisfactory
● 62. Durable	(SAT) Satisfactory
● 63. Legible	(SAT) Satisfactory
● 64. Secured	(SAT) Satisfactory
● 65. Visible From Operators Station	(SAT) Satisfactory
Safety Devices / Operational Aids	
● 66. Boom Angle Indicator	(SAT) Satisfactory
● 67. Boom Length Indicator	(SAT) Satisfactory
● 68. Drum Rotation Indicator	(NA) Not Applicable
● 69. Overload Protection	(SAT) Satisfactory

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 70. Crane Level Indicator	(REC) Recommendation
<i>Both levels need to be recalibrated; torpedo level used during inspection</i>	
● 71. Anti Two-Block Device	(SAT) Satisfactory
● 72. Outrigger / Stabilizer Position Sensor	(SAT) Satisfactory
Upper Structure	
● 73. Turntable	(SAT) Satisfactory
● 74. Mounting	(SAT) Satisfactory
● 75. Turret	(SAT) Satisfactory
● 76. Hydraulic Pump(s)	(SAT) Satisfactory
● 77. Hydraulic Hoses / Tubes / Fittings	(SAT) Satisfactory
● 78. Hydraulic Pressure	(SAT) Satisfactory
● 79. Electrical Wiring	(SAT) Satisfactory
● 80. Hoist Brake	(SAT) Satisfactory
● 81. Hoist - Motor / Valves / Lines	(SAT) Satisfactory
● 82. Hoist Spooling	(MON) Monitor
<i>Slight gap on drum, unable to fix during inspection</i>	P82
● 83. Hoist - Minimum 2 Rope Wraps	(SAT) Satisfactory
● 84. Swing Gear Box	(SAT) Satisfactory
● 85. Electrocution Warning Sign	(SAT) Satisfactory
Main Boom	
● 86. Lift Cylinder(s)	(SAT) Satisfactory
● 87. Telescoping Cylinder(s)	(SAT) Satisfactory
● 88. Hydraulic Hoses / Tubes / Fittings	(SAT) Satisfactory
● 89. Holding Device	(SAT) Satisfactory
● 90. Boom Sections Alignment	(SAT) Satisfactory
● 91. Wear Pads	(SAT) Satisfactory
● 92. Sheave(s)	(SAT) Satisfactory
● 93. Hoist Line Dead End	(SAT) Satisfactory
● 94. Wire Rope Retainer	(SAT) Satisfactory
● 95. Boom Hinge Pin	(SAT) Satisfactory
● 96. Boom Head Section	(SAT) Satisfactory
● 97. Structure	(SAT) Satisfactory
Load Block & Hook	
● 103. Capacity Marking	(SAT) Satisfactory
● 104. Weight Marking	(SAT) Satisfactory
● 105. Sheave(s)	(SAT) Satisfactory
● 106. Safety Latche(s)	(SAT) Satisfactory
● 107. 0° Hook Bend or Twist	(SAT) Satisfactory
● 108. 5% Hook Opening or 1/4" Max	(SAT) Satisfactory
● 109. 10% Hook Wear Max	(SAT) Satisfactory
● 110. Bearing	(SAT) Satisfactory
● 111. Wedge Socket / End Fitting	(SAT) Satisfactory
● 112. Reeving	(SAT) Satisfactory
Wire Rope	
● 121. Rope Damage	(SAT) Satisfactory
● 122. Measured Wear	(SAT) Satisfactory
● 123. Broken Wires	(SAT) Satisfactory
● 124. Lubrication	(SAT) Satisfactory

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 125. End Connectors

(MON) Monitor P125

■ *No broken wires/strands but slight cable damage just before becket*

Verification and Completion

126. Inspector Name and Signature

Chris Volz



127. Date of Inspection

10/04/2025

128. Customer Name and Signature

● 129. Certificate Issued

(Y) Yes



P82.1



P125.2

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.