



Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

25 Broad St. Stockton, Nj

on

7/2/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

Signature

Date

Table of Contents

	 High	 Med	 Low	Section
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400) - 25 Broad St. Stockton, Nj	0	1	0	1.0
Telescoping Boom Crane: 089 251 - S277				

Overview

Breakdown by Form

Form Type	 High	 Med	 Low	# Forms
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)	0	1	0	1
Overall:	0	1	0	1

Breakdown by Location

Location	 High	 Med	 Low	# Forms
25 Broad St. Stockton, Nj	0	1	0	1
Overall:	0	1	0	1

Breakdown by Asset

Asset Type	 High	 Med	 Low	# Assets
Telescoping Boom Crane	0	1	0	1
Overall:	0	1	0	1

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)

Sautter Crane Rental
2900 Black Lake Place
Philadelphia, PA 19154

FolderID: 070226S277
FormID: 29790981



Telescoping Boom Crane

Location: 25 Broad St. Stockton, Nj
Serial Number: 089 251
Unit Number: S277
Status: In Service

Manufacturer: Liebherr
Model: LTM 1090-4.2
Capacity: 110 Tons
Length/Lift: 197'
Type of Crane: All Terrain Crane
Number of Hoists: Main and Auxiliary (Not in Use)
Boom Configuration: Main Boom with Stowed Jib
Load Test: No

Priorities Found: ● 1 - Medium ● 106 - Good

General

- | | |
|--------------------------|---------------------------|
| 1. Location of Equipment | 25 Broad St. Stockton, Nj |
| 2. Hours & Mileage | |
| Hours | Mileage |
| 8225 | 62,013 |
| Lower hours 2929 | |

Inspection Information

- | | |
|----------------------|--------------|
| 3. Inspection Number | 070226S277 |
| 4. Inspection Date | 07/02/2026 |
| 5. Inspection Type | (Ann) Annual |

Information & Records

- | | | |
|---|----------------------|-----|
| 6. Documentation of Annual/Comprehensive Inspection | (SAT) Satisfactory | |
| 7. Daily/Monthly Inspection Records | (SAT) Satisfactory | |
| 8. Maintenance Records | (SAT) Satisfactory | |
| 9. Hand Signal Chart | (SAT) Satisfactory | P9 |
| 10. Safety and Warning Decals | (REC) Recommendation | P10 |
| 11. Operators Manual | (SAT) Satisfactory | |
| 12. Equipment Modification(s) or Additions | (NA) Not Applicable | |

Safety Devices & Operational Aids

- | | |
|----------------------------------|--------------------|
| 13. Backup Alarm | (SAT) Satisfactory |
| 14. Audible Warning Device | (SAT) Satisfactory |
| 15. Boom Angle Indicator | (SAT) Satisfactory |
| 16. Boom Length Indicator | (SAT) Satisfactory |
| 17. Drum Rotation Indicator(s) | (SAT) Satisfactory |
| 18. Anti Two-Block Device/System | (SAT) Satisfactory |

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 19.	Load Moment Indicator (LMI)	(SAT) Satisfactory	
● 20.	Load Weight Indicator	(SAT) Satisfactory	
● 21.	Radius Indicator	(SAT) Satisfactory	
● 22.	Level Indicator(s)	(SAT) Satisfactory	
● 23.	Fire Extinguisher	(SAT) Satisfactory	P23
Load Chart			
● 24.	Visible/Accessible	(SAT) Satisfactory	
● 25.	Per Configuration	(SAT) Satisfactory	
● 26.	Durable/Legible/Secured	(SAT) Satisfactory	
Carrier			
● 27.	Steering	(SAT) Satisfactory	
● 28.	Parking Brake	(SAT) Satisfactory	
● 29.	Exterior Lights (Headlights, Turn Signals, Brake Lights, Reverse Lights)	(SAT) Satisfactory	
● 30.	Windshield & Wipers	(SAT) Satisfactory	
● 31.	Windows & Mirrors	(SAT) Satisfactory	
● 32.	Wheels & Tires	(SAT) Satisfactory	
● 33.	Engine	(SAT) Satisfactory	
● 34.	Exhaust System	(SAT) Satisfactory	
● 35.	Axle Lockout	(SAT) Satisfactory	
● 36.	Drive Line	(SAT) Satisfactory	
● 37.	Main Frame Members	(SAT) Satisfactory	
● 38.	Hoses/Fittings/Valves	(SAT) Satisfactory	
● 39.	Hydraulic Tank & Fluid Level	(SAT) Satisfactory	
● 40.	Slip Resistant Walking Surfaces	(SAT) Satisfactory	
● 41.	Steps/Ladders/Handrails	(SAT) Satisfactory	
Outriggers/Stabilizers			
● 42.	Structure & Mounting	(SAT) Satisfactory	
● 43.	Boxes & Beams	(SAT) Satisfactory	
● 44.	Cylinders	(SAT) Satisfactory	
● 45.	Pads/Floats	(SAT) Satisfactory	P45
● 46.	Hoses/Fittings/Valves	(SAT) Satisfactory	
Operators Station			
● 47.	Windows & Wipers	(SAT) Satisfactory	
● 48.	Cab Door Restraint	(SAT) Satisfactory	
● 49.	Cab Access	(SAT) Satisfactory	
● 50.	Steps/Ladders/Handrails	(SAT) Satisfactory	P50
● 51.	Anti-Skid Stepping Surfaces	(SAT) Satisfactory	
● 52.	Fire Extinguisher	(SAT) Satisfactory	P52
● 53.	Operator Horn	(SAT) Satisfactory	
● 54.	Controls Identified	(SAT) Satisfactory	
● 55.	Control Functions	(SAT) Satisfactory	
● 56.	Power Plant Controls	(SAT) Satisfactory	
● 57.	Operator Cutoff Switch (Deadman)	(SAT) Satisfactory	
● 58.	Brake & Clutch	(SAT) Satisfactory	
● 59.	Accelerator/Throttle Control	(SAT) Satisfactory	
● 60.	Hoses/Fittings/Valves	(SAT) Satisfactory	
● 61.	Housekeeping	(SAT) Satisfactory	
Rotating Upper Structure			

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 62.	Structure	(SAT) Satisfactory
● 63.	Engine	(SAT) Satisfactory
● 64.	Exhaust System/Guards/Insulators	(SAT) Satisfactory
● 65.	Hoses/Fittings/Valves	(SAT) Satisfactory
● 66.	Hydraulic & Pneumatic Pumps	(SAT) Satisfactory
● 67.	Hydraulic Pressure	(SAT) Satisfactory
● 68.	Electrical Wiring	(SAT) Satisfactory
● 69.	Ring & Pinion Gear	(SAT) Satisfactory
● 70.	Swing System/Assembly	(SAT) Satisfactory
● 71.	Counterweight Frame	(SAT) Satisfactory
● 72.	Counterweight Mounting	(SAT) Satisfactory
Hoist System		
● 73.	Brakes & Clutch System	(SAT) Satisfactory
● 74.	Wire Rope Reeving	(SAT) Satisfactory
● 75.	2 Rope Wrap Minimum	(SAT) Satisfactory
● 76.	Hoist Motor	(SAT) Satisfactory
● 77.	Hoses/Fittings/Valves	(SAT) Satisfactory
● 78.	Drums/Lagging/Flanges	(SAT) Satisfactory
● 79.	Anchor System	(SAT) Satisfactory
● 80.	Hoist Spooling	(SAT) Satisfactory
Main Boom		
● 81.	Lift Cylinder(s)	(SAT) Satisfactory
● 82.	Telescoping Boom Cylinder(s)	(SAT) Satisfactory
● 83.	Hoses/Fittings/Valves	(SAT) Satisfactory
● 84.	Holding Device	(SAT) Satisfactory
● 85.	Boom Sections Alignment	(SAT) Satisfactory
● 86.	Wear Pads	(SAT) Satisfactory
● 87.	Sheaves	(SAT) Satisfactory
● 88.	Wire Rope Retainers	(SAT) Satisfactory
● 89.	Boom Hinge Pin	(SAT) Satisfactory
● 90.	Boom Head Section	(SAT) Satisfactory
● 91.	Auxiliary Boom Head	(SAT) Satisfactory
● 92.	Structure	(SAT) Satisfactory
Jib/Fly Extension		
● 93.	Structure	(SAT) Satisfactory
● 94.	Locking Devices	(SAT) Satisfactory
● 95.	Sheaves	(SAT) Satisfactory
● 96.	Wire Rope Retainers	(SAT) Satisfactory
● 97.	Alignment	(SAT) Satisfactory
● 98.	End Connectors & Pins	(SAT) Satisfactory
Main Drum Wire Rope		
99.	Wire Rope Information	
	Diameter	Construction/Type
	17mm	non-rotational
		Number of Parts
		2 parts
● 100.	Rope Damage	(SAT) Satisfactory
● 101.	Lubrication	(SAT) Satisfactory
● 102.	End Connectors	(SAT) Satisfactory
Main Hoist Load Block/Headache Ball/Hook		

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.


103. Capacity and Weight			P103
Capacity	Weight		
20 tons	300kg		
104. Capacity Marking	(SAT) Satisfactory		P104
105. Weight Marking	(SAT) Satisfactory		P105
106. Sheave(s)	(SAT) Satisfactory		P106
107. Safety Latch(es)	(SAT) Satisfactory		P107
108. 0° Hook Bend/Twist	(SAT) Satisfactory		
109. 5% Hook Opening or 1/4" Max	(SAT) Satisfactory		
110. 10% Hook Wear Max	(SAT) Satisfactory		
111. Bearing	(SAT) Satisfactory		
112. Wedge Socket/End Fitting	(SAT) Satisfactory		
113. Reeving	(SAT) Satisfactory		
Auxiliary Drum Wire Rope			
114. Wire Rope Information			
Diameter	Construction/Type	Number of Parts	
17mm	non rotational	stowed	
Verification and Completion			
115. Inspector Name & Signature		James Doan	
			
116. Additional Inspection Notes			P116
117. Sticker Given			(Y) Yes, Given on Site



P9.1



P10.2



P10.3



P23.4



P45.5:



P45.6



P45.7



P45.8



P50.9



P52.10



P103.11



P104.12




P105.13



P106.14



P107.15



P116.16