Prepared for:

Sautter Crane Rental

2900 Black Lake Place Philadelphia, PA 19154

Our Lady Of Lourdes Hospital Camden, Nj

on

10/31/2026

Please return the entire report.

Customer Sign Off

-If there are no deficiencies nothing needs to be done

-If there are any (HIGH, RED) deficiencies please follow the instructions below

The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.

-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

_____ _____

Signature Date

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Table of Contents

		High	Med	Low	Section
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400) - *Our Lady Of Lourdes Hospital Camden, Nj*	Telescoping Boom Crane*: 042 766 - S423*	0	0	0	**1.0**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Overview

Breakdown by Form

Form Type	High	Med	Low	# Forms
Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Breakdown by Location

Location	High	Med	Low	# Forms
Our Lady Of Lourdes Hospital Camden, Nj	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Breakdown by Asset

Asset Type	High	Med	Low	# Assets
Telescoping Boom Crane	0	0	0	1
Overall:	**0**	**0**	**0**	**1**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Tandem Lift LLC
321 Enlow Place
Pennsville, NJ 08070
833-TANDEM1

Hydraulic Boom Crane Annual Inspection Report (1910.180 & 1926.1400)

FolderID: 103126S423
FormID: 31474166

Sautter Crane Rental
2900 Black Lake Place
Philadelphia, PA 19154



Telescoping Boom Crane

Location:	Our Lady Of Lourdes Hospital Camden, Nj
Serial Number:	042 766
Unit Number:	S423

Additional Notes: 254' boom
69' jib 40 degree offset
229,000 lbs counterweight

Manufacturer:	Liebherr
Model:	LTM 1450-8.1
Capacity:	550 Tons
Length/Lift:	279'
Type of Crane:	All Terrain Crane
Number of Hoists:	Main Only
Boom Configuration:	Main Boom with Erected jib
Load Test:	No

Priorities Found: ● **111 - Good**

General

●	1.	Location of Equipment	**Our Lady of Lourdes Hospital**
	2.	Customer Sign Off	

Please return the entire report.
Customer Sign Off
-If there are no deficiencies nothing needs to be done
-If there are any (HIGH, RED) deficiencies please follow the instructions below
The deficiencies marked HIGH in RED shall be corrected and this report must be dated, signed and email THIS ENTIRE REPORT to tony.rossi@tandemlift.com or jon.santimaw@tandemlift.com. After the signed document is received, a certification and label will be issued. The deficiencies denoted with (REC, MEDIUM, ORANGE) are recommended and are not required to be corrected to achieve certification. However those items should be corrected to improve equipment reliability and performance.
-The undersigned verifies that the deficiencies denoted with (DEF, HIGH, RED) have been corrected.

_____ _____
Signature

●	3.	Hours & Mileage		
		Hours	Mileage	
		1,462	**7,796**	

Inspection Information

●	4.	Inspection Number	**103126S423**
●	5.	Inspection Date	**10/31/2026**
●	6.	Inspection Type	**(Ann) Annual**

Information & Records

●	7.	Documentation of Annual/Comprehensive Inspection	**(SAT) Satisfactory**
●	8.	Daily/Monthly Inspection Records	**(SAT) Satisfactory**
●	9.	Maintenance Records	**(SAT) Satisfactory**
●	10.	Hand Signal Chart	**(SAT) Satisfactory**
●	11.	Safety and Warning Decals	**(SAT) Satisfactory**
●	12.	Operators Manual	**(SAT) Satisfactory**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

13.	Equipment Modification(s) or Additions	**(SAT) Satisfactory**
Safety Devices & Operational Aids		
14.	Backup Alarm	**(SAT) Satisfactory**
	Unhooked for job site noise restriction	
15.	Audible Warning Device	**(SAT) Satisfactory**
16.	Boom Angle Indicator	**(SAT) Satisfactory**
17.	Boom Length Indicator	**(SAT) Satisfactory**
18.	Drum Rotation Indicator(s)	**(SAT) Satisfactory**
19.	Anti Two-Block Device/System	**(SAT) Satisfactory**
20.	Load Moment Indicator (LMI)	**(SAT) Satisfactory**
21.	Load Weight Indicator	**(SAT) Satisfactory**
22.	Radius Indicator	**(SAT) Satisfactory**
23.	Level Indicator(s)	**(SAT) Satisfactory**
24.	Fire Extinguisher	**(SAT) Satisfactory**
Load Chart		
25.	Visible/Accessible	**(SAT) Satisfactory**
26.	Per Configuration	**(SAT) Satisfactory**
27.	Durable/Legible/Secured	**(SAT) Satisfactory**
Carrier		
28.	Steering	**(SAT) Satisfactory**
29.	Parking Brake	**(SAT) Satisfactory**
30.	Exterior Lights (Headlights, Turn Signals, Brake Lights, Reverse Lights)	**(SAT) Satisfactory**
31.	Windshield & Wipers	**(SAT) Satisfactory**
32.	Windows & Mirrors	**(SAT) Satisfactory**
33.	Wheels & Tires	**(SAT) Satisfactory**
34.	Engine	**(SAT) Satisfactory**
35.	Exhaust System	**(SAT) Satisfactory**
36.	Axle Lockout	**(SAT) Satisfactory**
37.	Drive Line	**(SAT) Satisfactory**
38.	Main Frame Members	**(SAT) Satisfactory**
39.	Hoses/Fittings//Valves	**(SAT) Satisfactory**
40.	Hydraulic Tank & Fluid Level	**(SAT) Satisfactory**
41.	Slip Resistant Walking Surfaces	**(SAT) Satisfactory**
42.	Steps/Ladders/Handrails	**(SAT) Satisfactory**
Outriggers/Stabilizers		
43.	Structure & Mounting	**(SAT) Satisfactory**
44.	Boxes & Beams	**(SAT) Satisfactory**
45.	Cylinders	**(SAT) Satisfactory**
46.	Pads/Floats	**(SAT) Satisfactory**
47.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
Operators Station		
48.	Windows & Wipers	**(SAT) Satisfactory**
49.	Cab Door Restraint	**(SAT) Satisfactory**
50.	Cab Access	**(SAT) Satisfactory**
51.	Steps/Ladders/Handrails	**(SAT) Satisfactory**
52.	Anti-Skid Stepping Surfaces	**(SAT) Satisfactory**
53.	Fire Extinguisher	**(SAT) Satisfactory**
54.	Operator Horn	**(SAT) Satisfactory**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

55.	Controls Identified	**(SAT) Satisfactory**
56.	Control Functions	**(SAT) Satisfactory**
57.	Power Plant Controls	**(SAT) Satisfactory**
58.	Operator Cutoff Switch (Deadman)	**(SAT) Satisfactory**
59.	Brake & Clutch	**(NA) Not Applicable**
60.	Travel Controls	**(NA) Not Applicable**
61.	Accelerator/Throttle Control	**(SAT) Satisfactory**
62.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
63.	Housekeeping	**(SAT) Satisfactory**
Rotating Upper Structure		
64.	Structure	**(SAT) Satisfactory**
65.	Engine	**(NA) Not Applicable**
66.	Exhaust System/Guards/Insulators	**(NA) Not Applicable**
67.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
68.	Hydraulic & Pneumatic Pumps	**(SAT) Satisfactory**
69.	Hydraulic Pressure	**(SAT) Satisfactory**
70.	Electrical Wiring	**(SAT) Satisfactory**
71.	Ring & Pinion Gear	**(SAT) Satisfactory**
72.	Swing System/Assembly	**(SAT) Satisfactory**
73.	Counterweight Frame	**(SAT) Satisfactory**
74.	Counterweight Mounting	**(SAT) Satisfactory**
Hoist System		
75.	Brakes & Clutch System	**(SAT) Satisfactory**
76.	Wire Rope Reeving	**(SAT) Satisfactory**
	1 part of line	
77.	2 Rope Wrap Minimum	**(SAT) Satisfactory**
78.	Hoist Motor	**(SAT) Satisfactory**
79.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
80.	Drums/Lagging/Flanges	**(SAT) Satisfactory**
81.	Anchor System	**(SAT) Satisfactory**
82.	Hoist Spooling	**(SAT) Satisfactory**
Main Boom		
83.	Lift Cylinder(s)	**(SAT) Satisfactory**
84.	Telescoping Boom Cylinder(s)	**(SAT) Satisfactory**
85.	Hoses/Fittings/Valves	**(SAT) Satisfactory**
86.	Holding Device	**(SAT) Satisfactory**
87.	Boom Sections Alignment	**(SAT) Satisfactory**
88.	Wear Pads	**(SAT) Satisfactory**
89.	Sheaves	**(SAT) Satisfactory**
90.	Wire Rope Retainers	**(SAT) Satisfactory**
91.	Boom Hinge Pin	**(SAT) Satisfactory**
92.	Boom Head Section	**(SAT) Satisfactory**
93.	Auxiliary Boom Head	**(NA) Not Applicable**
94.	Structure	**(SAT) Satisfactory**
Jib/Fly Extension		
95.	Structure	**(SAT) Satisfactory**
96.	Locking Devices	**(SAT) Satisfactory**
97.	Sheaves	**(SAT) Satisfactory**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

98.	Wire Rope Retainers	**(SAT) Satisfactory**
99.	Alignment	**(SAT) Satisfactory**
100.	End Connectors & Pins	**(SAT) Satisfactory**

Main Drum Wire Rope

101. Wire Rope Information

Diameter	Construction/Type	Number of Parts
25.56mm	**Non Rot RLL**	**1**

102.	Rope Damage	**(SAT) Satisfactory**
103.	Lubrication	**(SAT) Satisfactory**
104.	End Connectors	**(SAT) Satisfactory**

Main Hoist Load Block/Headache Ball/Hook

105. Capacity and Weight

Capacity	Weight
16 tonnes	**500kg**

106.	Capacity Marking	**(SAT) Satisfactory**
107.	Weight Marking	**(SAT) Satisfactory**
108.	Sheave(s)	**(SAT) Satisfactory**
109.	Safety Latch(es)	**(SAT) Satisfactory**
110.	0° Hook Bend/Twist	**(SAT) Satisfactory**
111.	5% Hook Opening or 1/4" Max	**(SAT) Satisfactory**
112.	10% Hook Wear Max	**(SAT) Satisfactory**
113.	Bearing	**(SAT) Satisfactory**
114.	Wedge Socket/End Fitting	**(SAT) Satisfactory**
115.	Reeving	**(SAT) Satisfactory**

1 part of line

Verification and Completion

116. Inspector Name & Signature **Anthony Capozzi**



117.	Additional Inspection Notes	
118.	Sticker Given	**(Y) Yes, Given on Site**

Tandem Lift LLC disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Tandem Lift LLC. Tandem Lift LLC shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.